

DATE:

April 13, 2022

SUBJECT:

Certificate of Appropriateness Request: Applicant: Location of Subject Property: PINs: Staff Report Prepared by: H-03-22 Thomas Duquette & Aimee Cain (joint request) 148 & 154 Union Street S 5620-79-9327 & 5620-96-7858 Brad Lagano, Senior Planner

BACKGROUND

- The first subject property at 148 Union Street S is designated as a "Contributing" structure in the South Union Street Historic District (ca. 1921-27) (Exhibit A).
- "Large, two-story frame residence with Colonial Revival and bungalow style details; deep setback, landscaped driveway, and the vertical emphasis of the house's design combine to give the residence a most impressive appearance. House is composed of hip-roofed and gable-roofed wings set at right angles; the gable-roof wing makes up the norther (right) portion of the house and projects forward of the hip-roofed block. Three-bay front porch upheld by Doric columns. Beneath the porch is the entrance, which is framed by elaborate portal of heavy columns Porte-cochere upheld by Doric columns adjoins south (left) end of hip-roofed section. A hip-roofed garage that appears to be contemporary with the house stands at the rear of the property" (Exhibit A).
- The second subject property at 154 Union Street S is designated as a "Pivotal" structure in the South Union Street Historic District (ca. pre-1866 or 1866-1882) (Exhibit A).
- "Two-story brick Italianate residence, possibly erected before the Civil War and certainly the oldest structure in the district. Although the house underwent considerable change during the mid-twentieth century, it retains many original features. House follows two-story, single-pile, gable-roofed form typical of piedmont farmhouses throughout the nineteenth century. Surviving Italianate exterior features include bracketed cornice, sawn bargeboards at the gable ends, a handsome slanted bay window on the house's south side, two interior chimneys that rise from either side of the center hall, and the shallow segmental arches framing the 6/6 sash windows. Twentieth century additions include the colonial style entrance and portico and a sunroom adjoining the north (right) side of the house. The interior retains many original details, but has also undergone a degree of Colonial style remodeling" (Exhibit A).
- Applicants' jointly requested modification: remove one (1) willow oak tree on the property line and replace with one (1) similar shade tree in the same general vicinity (Exhibit B).

DISCUSSION

On January 28, 2022, Thomas H. Duquette applied for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 to remove one (1) willow oak tree located on a shared property line and replace with one (1) similar shade tree in the same general vicinity with the stump removed below ground level (Exhibit B).

On March 9, 2022, the Certificate of Appropriateness Application was amended to include the adjacent property owner, Aimee E. Cain, as a joint applicant due to the fact the subject tree is located on the shared property line (Exhibit B).

The applicants are jointly requesting to remove a 110' tall willow oak with an 80' spread, 37" DBH, and a Risk Rating of 4 (Exhibit D). When standing on Union Street S facing both houses, the subject tree is located along the shared property line running between the two (2) driveways (Exhibit E).

According to the Tree Risk Assessment Form (Exhibit D), the subject tree was inspected and evaluated by Bill Leake, City Arborist, on January 26, 2022. Bill notes the subject tree has no above normal structural risk issues to the trunk and crown. The exposed roots have been subject to years of vehicle and lawnmower damage. Any attempts to repair either driveway will require significant root cutting and damage.

The applicants note the tree presents an ongoing challenge due to the roots growing underneath and breaking apart the concrete driveways, primarily on the 148 Union Street S property, as well as the limbs rubbing against the structure and growing over the roof on the 154 Union Street S property. The applicants also note the tree presents a potential hazard due to falling limbs as demonstrated by previous automobile damage incurred (Exhibits E and F).

Due to the Risk Rating score of four (4), the removal of healthy trees/limbs requires Historic Preservation Commission review and approval.

If removal is approved, the applicants would like to replant one (1) similar shade tree in the general vicinity of the tree removed, but away from the driveway areas to prevent a repeat situation in the future. The stump will be removed below ground level as it is visible from the street.

ATTACHMENTS

Exhibit A: National Register of Historic Places Inventory Exhibit B: Certificate of Appropriateness Application Exhibit C: Subject Properties Map Exhibit D: Tree Risk Assessment Form Exhibit E: City Arborist Tree Photograph Exhibit F: Photographs of Tree Hazards and Damage

HISTORIC HANDBOOK DESIGN RECOMMENDATIONS

Approval Requirement Needs Table

- *Removal of healthy trees or pruning of limbs over six (6) inches in diameter in any location on the property requires Commission hearing and approval.*
- Tree topping removal of one-third of green surface of canopy, or leaving stubs larger than three (3) inches in diameter requires Commission hearing and approval.

Chapter 5 – Section 8: Landscaping and Trees

- One of the most visible features of the Districts is the landscaping and the associated tree canopy. Activities which negatively impact any aspect of the landscape should be avoided, such as the removal of healthy trees and mature shrubs.
- Tree health may be decided upon by the acquisition of a Tree Hazard Evaluation Form issued by the City Arborist or a report submitted by a certified arborist. Healthy trees are trees that have a hazard rating of four (4) or lower. Removal of healthy trees over the size of six (6) inches in

diameter (measured four (4) feet above ground) or pruning of healthy tree limbs over six (6) inches in diameter requires Historic Preservation Commission review and approval.

• All trees that are removed should be replaced with a tree of similar species in an appropriate location unless no suitable location exists on the subject site. Trees removed within street view must also have the stumps removed below ground level.

• Design Standards: Landscaping and Trees

2. Trees which are removed shall be replaced by a species which, upon maturity, is similar in scale to the removed specimen. For example, canopy trees shall be replaced with canopy trees, and understory trees with understory trees.

RECOMMENDATION

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u> <u>Handbook and Guidelines</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
 - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
 - Completed project will be photographed to update the historic properties survey.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

OMB No. 1024-0018

Expires 10-31-87

Continuation sheet	Item number	Page
Inventory List - South Union Street	#7	23
Historic District, Concord		

45. Doctor's Office 164 S. Union St. 1921-1927 (SM) F

> Two-story, frame, double-pile house with bungalow style details compromised by the enclosure of the wrap-around porch. Surviving details include broad eaves with exposed rafters, hip-roofed ventilator dormer centered over second story of facade, and a few tapered porch posts.

46. D. L. Bost House 158 S. Union St. ca. 1905 (IO) P

> Highly distinctive, two-story frame house blending Queen Anne and Colonial Revival styles. House designed by Charlotte architectural firm of Hook and Sawyer. House's dominant Queen Anne feature is the semi-circular second story facade, which is crowned by a witch's cap roof pierced by two hip-roofed ventilator dormers with flared eaves. At the center of this rounded section is a window consisting of three stained glass panels trimmed with a bow-like ornament. The one-story, full-facade porch is the principal Colonial Revival feature of the exterior; its Doric columns rise from a brick base to a dentil frieze. Colonial Revival details predominate inside the house.

> The house was built for D. L. Bost, a partner in the grocery firm of Dove and Bost. Upon Bost's death the house passed to his son, E. Gray Bost, who served as treasurer of Cannon Mills Company.

47. John O. Wallace House 154 S. Union St. poss. pre 1866, or 1866-1882 P


> Two-story brick Italianate residence, possibly erected before the Civil War and certainly the oldest structure in the district. Although the house underwent considerable change during the mid-twentieth century, it retains many original features. House follows two-story, singlepile, gable-roofed form typical of piedmont farmhouses throughout the nineteenth century. Surviving Italianate exterior features include bracketed cornice, sawn bargeboards at the gable ends, a handsome slanted bay window on the house's south side, two interior chimneys that rise from either side of the center hall, and the shallow segmental arches framing the 6/6 sash windows. Twentieth century additions



NPS Form 10-900-a (3-82)

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet	Item number	Page
Inventory List - South Union Street	#7	24
Historic District, Concord		

include the Colonial style entrance and portico and a sunroom adjoining the north (right) side of the house. The interior retains many original details but has also undergone a degree of Colonial style remodeling.

Local tradition maintains that county official John Osborne Wallace (1807-1873) erected the house shortly before the Civil War. It is known that Wallace sold a house on this site to Benjamin F. Fraley in 1866, but the architectural features of the house make it equally likely that the present house was a product of the early post-bellum period. Fraley sold a house on the site to A. J. Fry in 1874. Elam King (1831-1913) later owned the house. King was an organizer of the Concord National Bank in the late 1880s and one of its first directors.

48. M. Luther Marsh House 148 S. Union St. 1921-1927 (SM)

> Large, two-story frame residence with Colonial Revival and bungalow style details; deep setback, landscaped driveway, and the vertical emphasis of the house's design combine to give the residence a most impressive appearance. House is composed of hip-roofed and gableroofed wings set at right angles; the gable-roof wing makes up the northern (right) portion of the house and projects forward of the hiproofed block. Three-bay front porch upheld by Doric columns. Beneath the 'porch is the entrance, which is framed by elaborate portal of heavy columns. Porte-cochere upheld by Doric columns adjoins south (left) end of hip-roofed section. A hip-roofed garage that appears to be contemporary with the house stands at the rear of the property.

> Marsh was a doctor prominent in the city's business affairs. He served at various times as a vice-president of Citizen's Bank and Trust; secretary-treasurer of Porter Drug Company; and secretary-treasurer of Concord Motor Company.

49. Vacant lot (with garage) between 142 and 148 S. Union St. VL

> Vacant lot; a one-story, hip-roofed garage of frame construction, similar in appearance to the garage of the Marsh house, indicates that the lot is a former house site.





Please note this COA application was amended to include Thomas' adjacent neighbor, Aimee Cain, as a joint applicant since the subject tree is located on the common property line dividing the driveways. Both Thomas and Aimee signed the amended application on the bottom of page 2 on 3/9/22.

High Performance Living

Certificate of Appropriateness

AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

APPLICANT INFORMATION Name: THOMAS DUQUET Address: 148 UNIDN ST. City: COM COND State: NCZip Code: 280217	775 South Felephone: 704-890 502
OWNER INFORMATION Name: THOMAS DUP OFFE Address: 148 UNION ST. So- City: Concretate: NCZip Code: 28025 T	57h Felephone: 707-890 5021
SUBJECT PROPERTY Street Address: 21 M8 UNION St Sout Area (acres or square feet): 2 67 ACL Current Zoning:	
Staff Use Only: Application Received by: Fee: \$20.00 Received by:	


Planning & Neighborhood Development 35 Cabarrus Ave W • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordinc.gov

The application fee is nonrefundable.

EXHIBIT B

	NORTH CAROLINA High Performance Living HEREBEREREE	Application for Certificate of Appropriateness
	General Requirements	Tree #2 - elm tree RR5 - staff COA approval issued 2/1/22.
	The Unified Development Ordinance imposes the following rules, regulation Certificates of Appropriateness. The applicant must, with reference to the proposed use satisfies these requirements:	ons and requirements on requests for attached plans, demonstrate how the
ree #1 - illow oak ee RR4 - eeds HPC eview and oproval	With # SIMILOR TYPE OF	
	Required Attachments/Submittals 1. Scaled site plan, if additions or accessory structures are proposed, on copies will be accepted if 16 folded copies are submitted for distributi 2. A photograph of the front of the house. 3. Photographs of site, project, or existing structures from a "before" per 4. Drawings, sketches, renderings, elevations, or photographs necessary from an "after" perspective. 5. Samples of windows, doors, brick, siding, etc. must be submitted with 6. Detailed list of materials that will be used to complete the project. ***Applications may be submitted electronically.***	on. spective to present an illustration of the project
	Certification (1) I hereby acknowledge and say that the information contained herein ar shall not be scheduled for official consideration until all of the required co City of Concord Development Services Department. (2) I understand that Preservation Commission may make routine visits to the site to insure that that was approved. (3) I understand that photographs of the completed projection	ontents are submitted in proper form to the City staff and/or members of the Historic at work being done is the same as the work

3922 Planning & Neighborhood Development 35 Cabarrus Ave W • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920.6962 • www.concordinc.gov 3927 MMEEL 2AN





RISK RATING:

Potential

1

certificate of appropriateness.

Failure + Size + Target = Risk

of part Rating

4

Rating

2

If approved for removal, the replacement tree species and location shall be listed on the

Site/Address: 148 Union St S

Map/Location: Left side property line between driveways.

Owner: public: _____ private: ___X unknown: _____ other: _____

Date: 01/26/22____ Inspector: Bill Leake

Date of last inspection:

TREE CHARACTERISTICS

Tree #: 1 Species: Willow Oak (Quercus phellos)

DBH: 37" # of trunks: 1 Height: 110' Spread: 80'

Form: \boxtimes generally symmetric \square minor asymmetry \square major asymmetry \square stump sprout \square stag-headed

Crown class: □ dominant ⊠ co-dominant □ intermediate □ suppressed

Live crown ratio: 95 % Age class: \Box young \Box semi-mature \boxtimes mature \Box over-mature/senescent

 Pruning history:
 □ crown cleaned
 □ excessively thinned
 □ topped
 ⊠ crown raised
 □ pollarded
 □ crown reduced
 □ flush cuts

 □ cabled/braced
 □ none
 □ multiple pruning events
 Approx. dates:

Special Value: 🗆 specimen 🛛 heritage/historic 🗆 wildlife 🗆 unusual 🗆 street tree 🗆 screen 🗆 shade 🗆 indigenous 🖾 protected by gov. agency

TREE HEALTH _____

Foliage color. 🗆 normal	\Box chlorotic	□ necrotic	Epicormics; 🗆		Growth obstruc	tions:
Foliage density:	⊠normal	⊠normal □sparse Leaf size : □ normal □ small		\Box stakes \Box wire/ties	\Box signs \Box cables	
Annual shoot growth:	\Box excellent	🛛 average	🗆 poor 🗆 none	Twig Dieback: 🛛	⊠ curb/pavement	□ guards
Woundwood :	□ excellent ⊠average □ fair □ poor					
Vigor class:	□ excellent ⊠average □ fair □ poor					
Major pests/diseases:	None					

SITE CONDITIONS ____

TARGET_

Use Under Tree: △ building □ parking □ traffic □ pedestrian □ recreation □ landscape □ hardscape □ small features □ utility lines **Can target be moved?** NO **Can use be restricted?** NO

Can target be moved? NO Can use be restricted? NO

Occupancy: \Box occasional use \boxtimes intermittent use \Box frequent use \Box constant use



TREE DEFECTS

_ _ _ _ _ _

ROOT DEFECTS:
Suspect root rot: YES Mushroom/conk/bracket present: NO ID:
Exposed roots: \Box severe \boxtimes moderate \Box lowUndermined: \Box severe \Box moderate \boxtimes low
Root pruned: NO distance from trunk Root area affected: Buttress wounded: 🛛 When:
Restricted root area: \boxtimes severe \square moderate \square low Potential for root failure: \square severe \square moderate \boxtimes low
LEAN: 1 deg. from vertical \square natural \square unnatural \square self-corrected \square Soil heaving:
Decay in plane of lean: Roots broken: Soil cracking:
Compounding factors: Lean severity: Severe Moderate Iow

Concern Areas: Indicate presence of individual structural issues and rate their severity (**S** = severe, **M** = moderate, **L** = low)

DEFECT	ROOT CROWN	TRUNK	SCAFFOLDS	BRANCHES
Poor taper				
Bow, sweep				
Codominants/forks			М	
Multiple attachments				
Included bark				
Excessive end weight				
Cracks/splits				
Hangers				
Girdling				
Wounds/seam	Μ			
Decay				
Cavity				
Conks/mushrooms/bracket				
Bleeding/sap flow				
Loose/cracked bark				
Nesting hole/bee hive				
Deadwood/stubs			L	L
Borers/termites/ants				
Cankers/galls/burls				
Previous failure				
RISK RATING				

Tree part most likely to fail in the next six months: Branches

Failure potential: 1 - low: 2 - medium; 3 - high; 4 - severe	Size of part: 0 -0" - 3" 1 - 3"-6"	2 -6"-18"	3 -18"-30"	4 ->30"
Target rating: 0 - no target 1 - occasional use 2 - intermittent use 3 - frequent use 4	- constant use			

Maintenance Recommendations

Failure Potential + Size of Part + Target Rating = Hazard Rating	\Box none \Box remove defective part \Box reduce end weight \boxtimes crown clean	
<u> 1 1 2 4 </u>	\Box thin \boxtimes raise canopy \Box crown reduce \Box restructure \Box cable/brace	
	Inspect further \Box root crown \Box decay \Box aerial \Box monitor	
$\hfill\square$ Remove tree $\hfill\square$ When replaced, a similar sized tree spe	cies would be appropriate in same general location	
\square When replaced, alternate tree replacement locations are available		
Effect on adjacent trees: \Box none \boxtimes evaluate		
Notification: \boxtimes owner \square manager \boxtimes governing agency	Date: 01/26/22	
COMMENTS		

This tree has no above normal structural risk issues to the trunk and crown. The exposed roots been subject to years of vehicle and lawnmower damage. Any attempts to repair either driveway will require significant root cutting and damage.

Bill Leake



















