### HISTORIC PRESERVATION COMMISSION MEETING AGENDA

Wednesday, June 14, 2023 at 6:00 PM

City Hall Council Chambers, 35 Cabarrus Avenue West

- 1. CALL TO ORDER *Chair*
- 2. ORDER OF BUSINESS Chair (Ask Staff if there are any adjustments to agenda)
- 3. INTRODUCTIONS Chair and Commissioners (give your name for the record)
- 4. APPROVAL OF MINUTES *Motion, second, and vote needed.*
- 5. SWEARING IN OF WITNESSES *Chair*
- 6. OLD BUSINESS *Chair*

### 7. NEW BUSINESS

### H-07-23 (Quasi-Judicial Hearing)

**Cary Gluf** has submitted a Certificate of Appropriateness application for modifications including, but not limited to, partial demolition, a second story addition, addition of porches/deck, and modification to the driveway at 391 Union St S. PIN 5630-24-0612.

- a. Open Public Hearing by Motion *Motion, second, and vote needed*.
- b. Staff Presentation
- c. Applicant's Testimony
- d. Other Testimony
- e. Close Public Hearing by Motion Motion, second, and vote needed.
- f. Approve Findings of Fact by Motion Motion, second, and vote needed.
- g. Approve Conclusions of Law by Motion *Motion, second, and vote needed.*
- h. Approve/Deny Conditions and Permit by Motion Motion, second, and vote needed.

#### H-08-23 (Quasi-Judicial Hearing)

**Brian and Robin Dicka** have submitted a Certificate of Appropriateness application to remove a chain link fence and install a wood privacy fence in the backyard at 216 Union St S. 5630-05-4967

- a. Open Public Hearing by Motion Motion, second, and vote needed.
- b. Staff Presentation
- c. Applicant's Testimony
- d. Other Testimony
- e. Close Public Hearing by Motion Motion, second, and vote needed.
- f. Approve Findings of Fact by Motion *Motion, second, and vote needed*.
- g. Approve Conclusions of Law by Motion Motion, second, and vote needed.
- h. Approve/Deny Conditions and Permit by Motion Motion, second, and vote needed.

#### H-06-23 (Quasi-Judicial Hearing)

**Chad VanKeuren** has submitted a Certificate of Appropriateness application for the removal of a tree to the right of the house at 120 Union St N. PIN 5620-79-9239.

- a. Open Public Hearing by Motion *Motion, second, and vote needed*.
- b. Staff Presentation
- c. Applicant's Testimony
- d. Other Testimony
- e. Close Public Hearing by Motion Motion, second, and vote needed.
- f. Approve Findings of Fact by Motion Motion, second, and vote needed.

- g. Approve Conclusions of Law by Motion Motion, second, and vote needed.
- h. Approve/Deny Conditions and Permit by Motion Motion, second, and vote needed.

#### H-09-23 (Quasi-Judicial Hearing)

**Robert Ritchie** has submitted a Certificate of Appropriateness application to relocate an existing fence, replace portion of curb and widen section of the driveway at 406 Union St S. PIN 5630-14-7115.

- a. Open Public Hearing by Motion Motion, second, and vote needed.
- b. Staff Presentation
- c. Applicant's Testimony
- d. Other Testimony
- e. Close Public Hearing by Motion Motion, second, and vote needed.
- f. Approve Findings of Fact by Motion *Motion, second, and vote needed.*
- g. Approve Conclusions of Law by Motion Motion, second, and vote needed.
- h. Approve/Deny Conditions and Permit by Motion Motion, second, and vote needed.

#### H-10-23 (Quasi-Judicial Hearing)

**Melody Sloan** has submitted a Certificate of Appropriateness application to continue an existing wooden fence in the rear yard, along with removal and replacement of two trees at 40 Marsh Ave. NW. PIN 5620-79-0542.

- a. Open Public Hearing by Motion Motion, second, and vote needed.
- b. Staff Presentation
- c. Applicant's Testimony
- d. Other Testimony
- e. Close Public Hearing by Motion Motion, second, and vote needed.
- f. Approve Findings of Fact by Motion Motion, second, and vote needed.
- g. Approve Conclusions of Law by Motion Motion, second, and vote needed.
- h. Approve/Deny Conditions and Permit by Motion Motion, second, and vote needed.

#### H-11-23 (Quasi-Judicial Hearing)

**Dimitrios and Holli Arethas** have submitted a Certificate of Appropriateness application to remove a tree from the right, rear yard at 312 Union St S. PIN 5630-05-9180.

- a. Open Public Hearing by Motion Motion, second, and vote needed.
- b. Staff Presentation
- c. Applicant's Testimony
- d. Other Testimony
- e. Close Public Hearing by Motion *Motion, second, and vote needed.*
- f. Approve Findings of Fact by Motion Motion, second, and vote needed.
- g. Approve Conclusions of Law by Motion Motion, second, and vote needed.
- h. Approve/Deny Conditions and Permit by Motion Motion, second, and vote needed.

#### H-12-23 (Quasi-Judicial Hearing)

**Stephen Rohrer** has submitted an ex-post facto Certificate of Appropriateness application for staining of the rear fence at 113 Union St N. PIN 5620-79-8008.

- a. Open Public Hearing by Motion Motion, second, and vote needed.
- b. Staff Presentation
- c. Applicant's Testimony
- d. Other Testimony
- e. Close Public Hearing by Motion Motion, second, and vote needed.
- f. Approve Findings of Fact by Motion *Motion, second, and vote needed.*
- g. Approve Conclusions of Law by Motion Motion, second, and vote needed.
- h. Approve/Deny Conditions and Permit by Motion Motion, second, and vote needed.

#### STAFF UPDATES/DISCUSSIONS

Handbook Updates

a. Discuss Committee's Progress

### 8. ADJOURNMENT

In accordance with ADA Regulations, please note that anyone who needs an accommodation to participate in the meeting should notify Planning & Neighborhood Development Department at 704/920-5152 at least twenty-four (24) hours prior to the meeting.



Agenda Memorandum Historic Preservation Commission

<u>DATE</u> <u>SUBJECT</u>
Certificate of Appropriateness Request:
Applicant:
Location of subject property:
<u>PIN:</u>
Staff Report prepared by:

June 14, 2023

H-07-23 Cary Gluf (on behalf of David & Jillian Hobson) 391 Union St. S 5630-24-0612 Autumn C. James, Planning & Development Manager

#### **BACKGROUND**

- The subject property, 391 Union St. S is designated as a "Pivotal" structure in the South Union Street Historic District (Exhibit A).
- "Large and magnificently situated two-story frame house with Queen Anne and Colonial Revival elements and exceptionally deep wrap-around porch, the major product of an early twentieth century remodeling. Visually the most important property in the district, the house stands impressively at the crest of a hill several hundred feet east of S. Union St., and is reached by a curving driveway. Set in its broad, deep lot, the rear portions of which are wooded, the house vividly recalls the semi-rural character of S. Union St. during the early years of development. The major feature of the house is the huge porch, which wraps around both sides of the house and has both a four-bay balcony and a porte-cochere on the south (right) side. The porch has a retaining wall clad in shingles and is supported by paired, tapered Tuscan columns rising from the wall. All of the gables on the front and sides of the house have spindle work ornaments. The house retains its early twentieth century covering of slate shingles, and its two corbeled chimneys remain intact. The interior has a pleasing combination of Queen Anne and Colonia Revival details." (Exhibit A).

#### **DISCUSSION**

On March 7, 2023, Cary Gluf, applied for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 for modifications including, but not limited to, partial demolition, a second story addition, addition of porches and a rear deck, and modification to the driveway (Exhibit B).

The applicant is proposing to demolish most of the existing roof structure at the rear of the house which covers the single-story area. The kitchen pantry, rear wood deck, and trashcan enclosure will also be demolished, along with the second story shed roof and the unused brick chimney on the back of the laundry room.

The applicant is also proposing a two-story addition at the rear of the house and includes the following:

#### **First Floor Modifications**

- Kitchen addition which includes a new, triple 20x44 double-hung, one-over-one window on the rear of the house.
- Remodeled Breakfast Room with a 3'-5" x 11'-0" bump-out. The bump-out includes a pair of 30"x96" patio doors and four 18"x72" double-hung, one-over-one windows.
- 3'x7'-6" hanger rod supported aluminum canopy above the entry doors.
- Family room addition to include a double 28"x80", double-hung, two-over-one window on the left side to replace two separate, existing mis-matched double hung windows.

- Pantry/Half Bath addition (7' X 14') connecting the kitchen to a new screened porch. The pantry and half bath each have one 20"x20" awning window. One faces the back of the house and one faces the front.
- Addition of a screened porch (14' x 16') which includes a stacked-stone fireplace, brick foundation and slate roof.
- Existing rear window to be replaced with a pair of double-hung, two-over-one windows which will fit the existing opening.
- Wood deck addition (447 sq. ft) on the rear with a combination wood and metal railing. Decking may be either standard pressure treated lumber or DuxxBak composite lumber.

#### **Second Floor Modifications**

- Owner's Suite (15'-8" x 21'-10") to match footprint of the first-floor laundry room/bathroom area. Includes two 32"x72" double-hung, two-over-one windows on the right side; triple 32"x72" double-hung, two-over-one set of windows on the rear.
- Covered porch addition with a 60'x60" picture window located on the back wall of the new owner's bath; porch design mimics the elements of existing porches.
- Children's Suite addition (16'-7" x 28'-5") located above the new kitchen/family room area. Includes two 32"x60" double-hung, two-over-one windows; one 20"X20" awning window on the left side; a pair of 32"x72" double-hung, two-over-one windows on the rear.

#### **Additional Modifications**

- Existing generator to be relocated to less prominent location on the property and screened on the front with vegetation.
- Partial parts of the existing gravel drive will be removed and replaced with lawn and a new circular area will be added to the front, right of the house.

#### **ATTACHMENTS**

Exhibit A: National Register of Historic Places Inventory Exhibit B: Application for Certificate of Appropriateness Exhibit C: Subject Property Map Exhibit D: Site Plans Exhibit E: Existing Floor Plans Exhibit F: Proposed Floor Plans Exhibit G: Proposed Elevations Exhibit H: Project Description and Proposed Materials Exhibit I: Applicant Submitted Photographs

#### HISTORIC HANDBOOK DESIGN RECOMMENDATIONS

#### **Chapter 4: Local Standards and General Policies**

**Alterations:** Alterations having no historical basis shall be avoided whenever possible. Any type of alteration of exterior features of a building, site, or environment within the Historic Districts which is not specifically listed within these regulations shall be referred to the Historic Preservation Commission for action on the issuance of a Certificate of Appropriateness.

• Contemporary design for alterations and additions to existing properties shall be encouraged when such alterations and additions do not destroy significant historical, architectural or cultural material, and such design is compatible with the size, scale, color, material and character of the property, neighborhood or environment.

• New additions or alterations shall be construed in such a manner as to preserve the essential form and integrity of the structure, should the addition or alteration be removed.

#### **Approval Requirement Needs Table: Demolition**

Demolition of any building or part thereof requires Commission Hearing and Approval.

#### **Approval Requirement Needs Table: New Construction or Additions**

All new construction and additions require Commission Hearing and Approval.

#### Chapter 5 – Section 2: New Addition Construction

- Wherever possible, new additions to buildings shall be done in such a manner that if they were to be removed in the future, the essential form and integrity of the original building would not be impaired.
- New addition design for historic structures shall be compatible with the size, scale, color, material and character of the neighborhood, the building and its environment.
- Although designed to be compatible with the historic building, an addition should be discernible from the original building.

#### Design Standards: New Addition Construction

- Site new additions as inconspicuously as possible, preferably on rear elevations and where historic character defining features are not damaged, destroyed, or obscured.
- Inset additions from rear building corners to differentiate them from the existing building and to reduce public visibility.
- Design additions so they are compatible with the existing building in height, massing, roof form and pitch.
- New additions should be installed in such a manner that would allow the home to be reverted to its original state without damaging historic features.
- New additions should be compatible in character but use a contemporary design in order to differentiate additions from the historic structure.
- Windows in additions should be similar to those in the original buildings in their proportions, spacing, and materials.
- Select exterior surface siding and details that are compatible with the existing building in material, texture, color, and character.

#### **Approval Requirement Needs Table: Awnings and Canopies**

Adding awnings and canopies requires Commission Hearing and Approval.

#### **Approval Requirement Needs Table: Windows**

*Replacement/changes in window design. Removal of original windows, window components, and changes in the window openings require Commission Hearing and Approval.* 

#### **Chapter 5 - Section 5: Fenestrations**

- Awnings and canopies constructed of canvas are appropriate with commercial structures and in some instances with residential structures. Types of residential structures with which awnings are most compatible are Bungalow, Queen Ann, and Colonial Revival.
- Aluminum awnings or canopies are inappropriate.
- New windows should be consistent or compatible with existing units.
- The emphasis of new windows should be vertical rather than horizontal.
- Wood is the most appropriate material

#### Design Standards: Fenestrations

- Choose windows that are appropriate for the style of building, maintain vertical emphasis, and avoid large single paned units.
- Awnings or canopies should be mounted within the opening, directly on the window or door frame, or as an alternate, just outside the opening.

#### **Approval Requirement Needs Table: Balconies and Decks**

Addition of a balcony or deck where none previously existed requires Commission Hearing and Approval.

#### **Approval Requirement Needs Table: Porches**

Removal of porches, adding a new porch, altering a porch, or enclosing a porch requires Commission Hearing and Approval.

#### **Chapter 5 – Section 6: Porches**

- Decks are generally not appropriate for homes within the districts. However, when decks are constructed, they should he located in the rear yard only, and should not project into the interior side yard.
- Decks should be avoided on corner lots, since their view cannot be completely obscured from both streets.
- Rails on decks should match those on the porches. Lattice and shrubbery around the foundations enhance the appearance of decks, and should be utilized when possible.

#### Design Standards: Porches

- Decks may only be located in the rear of the property.
- Design decks to be compatible in material, color, and detail with the historic building.
- Construct decks so that they can be removed in the future without damaging the historic structure.
- Construct decks so that there is the least possible loss of historic fabric. Also, ensure that characterdefining features of the historic building are not obscured, damaged, or destroyed.
- Inset decks from the corner of the primary structure where necessary in order to prevent visibility from the street.

#### Approval Requirement Needs Table: Patios, Walks, And Driveways

All new patios, walks, and driveways require Commission Hearing and Approval.

#### Chapter 5 - Section 10: Driveways, Walkways, and Parking

• Gravel and pavement are acceptable materials for driveways, as are some alternative materials such as cobblestone, brick, and pervious pavers.

#### Design Standards: Driveways, Walkways, and Parking

- Parking areas should not be the focal point of the property, and should be located in such a manner as to minimize their visibility from the street.
- Use vegetation screen or berms to reduce reflection and visual confusion. Within residential areas, integrate parking areas into landscaping and surface with the appropriate materials such as concrete, brick, crushed stone or gravel.

#### **Approval Requirement Needs Table: Mechanical Equipment**

All mechanical equipment requires Commission Hearing and Approval.

#### Chapter 5 – Section 12: Mechanical and Incidental Equipment

• Equipment that is visible from the street should utilize shrubbery or fencing for screening from the street and adjacent property.

#### Design Standards: Mechanical and Incidental Equipment

• Place mechanical equipment in areas which utilize existing features such as fences, walls, and landscaping to screen their view.

#### Approval Requirement Needs Table: Siding

Alteration of siding from one material to another (shingles to clapboard etc.) requires Commission Hearing and Approval.

#### Approval Requirement Needs Table: Siding Removal

*Removal of siding to be replaced with another material (shingles to clapboard etc.) requires Commission Hearing and Approval.* 

#### Chapter 5 – Section 4: Siding and Exterior Materials

• There are a variety of materials available for use on the exterior of both existing structures and for new construction. Wood siding is the predominate exterior material within the Historic Districts.

#### Design Standards: Siding and Exterior Materials

• The removal of artificial siding and restoration of original siding materials in encouraged.

#### Approval Requirement Needs Table: Roof Materials and Shape

Repairs or changes which alter the shape of the roof requires Commission Hearing and Approval.

#### **Chapter 5 – Section 7: Roofing**

- Typical roofing materials used are tin, copper, slate, tiles, wood, and composition shingles.
- Changes to roof pitch, configuration and materials from that of the original should be avoided.

#### Design Standards: Siding and Exterior Materials

- Use materials in new construction that are consistent with the style of the building; materials should be unobtrusive in texture as well as color.
- *Roof shapes, texture and material should be compatible with new construction as well as with immediate buildings*

#### **Approval Requirement Needs Table: Miscellaneous**

Any type of alteration of exterior features of a building, site, or environment which is not specifically listed requires Commission Hearing and Approval.


#### **RECOMMENDATION**

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u> <u>Handbook</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
  - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
  - Completed project will be photographed to update the historic properties survey.

NPS Form 10-900-a (3-82)

United States Department of the Interior National Park Service

# National Register of Historic Places Inventory—Nomination Form



OMB No. 1024-0018

Expires 10-31-87

Continuation sheet	item number	Page	
Inventory List - South Union Street	#7	36	
Historic District, Concord			

90. William A. Ritchie House 377 S. Union St. 1926 (IO) C

> One-and-a-half story, frame house attractively combining Colonial Revival and bungalow style features. House has side gable roof with broad center facade gable. House's most distinctive feature is a shallow entrance portico with flared horseshoe-arched canopy supported by two Doric columns and two pilasters. Two bays of three 9/1 sash windows flank the entrance; they retain their original canvas awnings. A porte-cochere upheld by Doric columns adjoins the house's south (left) side.

> This house occupies the north side of the Ritchie family tract purchased by Charles F. Ritchie in the early 1900s. William Ritchie, one of Ritchie's sons, erected this house on land he obtained from his father. William Ritchie ran his father's business, the Ritchie Hardware Store in downtown Concord. William Ritchie's widow still lives in the house.

#### 91.

# Caldwell-Ritchie House 391 S. Union St.

erected before 1902, remodeled between 1908 and 1914 (IO,CD) - P

Large and magnificently situated two-story frame house with Queen Anne and Colonial Revival elements and exceptionally deep wrap-around porch, the major product of an early twentieth century remodeling. Visually the most important property in the district, the house stands impressively at the crest of a hill several hundred feet east of S. Union St., and is reached by a curving driveway. Set in its broad, deep lot, the rear portions of which are wooded, the house vividly recalls the semi-rural character of S. Union St. during the early years of development.

The major feature of the house is the huge porch, which wraps around both sides of the house and has both a four-bay balcony and a portecochere on the south (right) side. The porch has a retaining wall clad in shingles and is supported by paired, tapered Tuscan columns rising from the wall. All of the gables on the front and sides of the house have spindle work ornaments. The house retains its early twentieth century covering of slate shingles, and its two corbeled chimneys remain intact. The interior has a pleasing combination of Queen Anne and Colonial Revival details.

#### United States Department of the Interior National Park Service

# National Register of Historic Places Inventory—Nomination Form

For NPS use only

date entered

Continuation sheet

Item number

#7

Page

Inventory List - South Union Street Historic District, Concord

> The house is said to have been built about 1900 for attorney Morrison Caldwell. It is not known when he acquired the land, but city directories indicate he was living there in 1902. By 1908 Caldwell seems to have left Concord and the house belonged to G. C. Love. Charles F. Ritchie (d. 1941), who in 1908 lived on Mt. Pleasant Road, had come to reside in the house by 1914. According to one of Ritchie's sons, it was he who arranged for the considerable enlargement of Ritchie was the proprietor of the Ritchie Hardware Company, the house. founded 1900 and incorporated in 1907. Ritchie and business. in associates erected the Pythian Building, a substantial three-story brick building in downtown Concord that is being considered for listing in the National Register.

92. George Patterson Ritchie House 401 S. Union St. 1921-1927 (SM) P

> Handsome, two-story brick house combining Neo-Federal and Mission Revival elements and enjoying deep setting in pleasantly landscaped grounds. House designed by Charlotte architect M. R. Marsh. The tiled **roof and** creamy tan brick give the design its Mission flavor; most of the details are Neo-Federal in character. The finest feature in the latter style is the entrance, composed of a gable-roofed portico upheld by thin Doric columns, and a fanlit doorway. Four roundheaded windows with awnings flank the entrance. There is an open porch upheld by Doric columns on the house's south (right) side. The interior displays restrained Neo-Federal details.

> This house occupies the southern side of the Ritchie family tract purchased by Charles F. Ritchie during the early 1900s. George Patterson Ritchie, one of Charles Ritchie's sons, obtained this parcel from his father in a trade. George Patterson Ritchie founded Ritchie Auto Parts as a branch of the family business, the Ritchie Hardware Company. He still lives in the house.

93. Vacant Lot

between 401 and 429 S. Union St.  $\rm VL$ 

Open, pleasantly landscaped tract adjoining George Patterson Ritchie House (inv. #92) and owned by the Ritchie family. Contributes to the district as a reminder of the formerly semi-rural character of S. Union St.



Application for Certificate of Appropriateness

### AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

APPLICANT INFORMATION	
Name: CARY GLUF	
Address: 147 GLEANDALE AVE SE	
City: Concorn State: NC Zip Code: 28025	Felephone: 960 621 0037
OWNER INFORMATION	
Name: DAVID & JILLIAN HEISSON	
Address: 391 UNION ST SOUTH	
City: CONCO20 State: NC Zip Code: 23025	Telephone: 602.809.0824
	JILL
SUBJECT PROPERTY	
Street Address: 391 UNION ST SOUTH	H P.I.N. # 5630240612
Area (acres or square feet):Current Zoning:	Land Use:
Staff Use Only:	
Application Received by:	_Date:, 20
Fee: \$20.00 Received by:	_Date:, 20
The application fee is nonre	efundable

Planning & Neighborhood Development 35 Cabarrus Ave W • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov



DETAILED

PLANS

#### **General Requirements**

SPECIFICADINS

The Unified Development Ordinance imposes the following rules, regulations and requirements on requests for Certificates of Appropriateness. The applicant must, with reference to the attached plans, demonstrate how the proposed use satisfies these requirements:

1.	Project or '	Type of Work to	be Done:	AD	Diponl,	/remoder	BACK	OF	HOUSE	•
						, DRIVENA				

PHOTOS

2. Detailed specifications of the project (type of siding, windows, doors, height/style of fence, color, etc.):

EXISTING

SUBMITTED AS WORD DOC,

#### Required Attachments/Submittals

- 1. Scaled site plan, if additions or accessory structures are proposed, on letter, legal or ledger paper. Larger sized copies will be accepted. Digital copies are preferred.
- 2. Detailed written description of the project.
- 3. Photographs of site, project, or existing structures from a "before" perspective.
- 4. Drawings, sketches, renderings, elevations, or photographs necessary to present an illustration of the project from an "after" perspective if applicable.
- 5. Samples of windows, doors, brick, siding, etc. must be submitted with application.
- 6. Detailed list of materials that will be used to complete the project.


#### Certification

(1) I hereby acknowledge and say that the information contained herein and herewith is true and that this application shall not be scheduled for official consideration until all of the required contents are submitted in proper form to the City of Concord Development Services Department. (2) I understand that City staff and/or members of the Historic Preservation Commission may make routine visits to the site to insure that work being done is the same as the work that was approved. (3) I understand that photographs of the completed project will be made to update the City's historic districts inventory database.

Date

Signature of Owner/Agent


Planning & Neighborhood Development 35 Cabarrus Ave W • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov



H-07-23

391 Union St S

PIN: 5630-24-0612







Source: City of Concord Planning Department


#### Disclaimer

These maps and products are designed for general reference only and data contained herein is subject to change. The City Of Concord, it's employees or agents make no warranty of merchantability or fitness for any purpose, expressed or implied, and assume no legal responsibility for the information contained therein. Data used is from multiple sources with various scales and accuracy. Additional research such as field surveys may be necessary to determine actual conditions.

Exhibit C








USED BY DIMENSION COMPLEX PRORE T COMPLIANT THE RES WORK. THE RES WORK. THE RES WORK. THE RES WORK. COMPLEX THE RES COMPLEX CO	UNES SHALL COPICATIONS INCE OVER A WHERE WRW RAWINGS ARE INS AND DET COPERIENCI VENTARY TO INS MUST BE O INSTALLATION INCE WITH TH POINSIBILITY	The Cost stand of the Cost stands of the	TIC, NOT INDICATING ALL REF. INTERACED TO BE S.S. ALC OROUTIONS AND S.S. ALL CONDITIONS AND BY THE CONTRACTOR K PERFORMED NOT IN FIRESE DOCUMENTS IS BSONS PERFORMING THE NOT THEREDNI IS THE NOT ALTERNITION OR USE INT ALTERNITION OR USE INT ALTERNITION OR USE INTERNITION THERE BOLGET WITHOUTS IN THE REMINSION TO MAKE WIND.
REALECT REMODEL OF RITCHIE HILL FOR:	THE HOBSON FAMILY	391 UNION STREET SOUTH CONCORD, NC	EXISTING 1st FLOOR PLAN
FINA	IGN: 01	.24.20 .31.20 .04.20	23
DRAV		C. J.	

Exhibit E




 1
 EXISTING 2nd FLOOR PLAN

 A-2
 3/32" = 1'-0"


CONDITI USED B COMPLIE DIMENSI DIMENSI DIMENSI DIMENSI THE RE WORK. THIS DR PROPER FOR OT THE WR NOT PEI "PROJEC UNALTE	Ins and det y experience mentary to ons must be o installatio ince with th sponsibility (	ALS, AND 7 ED WECHAN THE OTHER E VERIFIED IN. WOR E INTENT C OF THE PEI HE INFORM ESIGNS. E INTENDED IT CONSENT RSON OR C CK HAVE P F THIS DR	NTION THEREON I ANY ALTERATION PROJECT WITHO T OF CARY J. GL SOMPANY NAMED ERMISSION TO M WING.	HEL INS AND INS AND ITOR ITOR IT IN ENTS IS ING THE
DRAWN BY:	CJG Designs	CARY J GLUF The CABEM Corporation	147 GLENDALE AVE SE CONCORD NC 28025 C 980.621.0037	cjgdesigns@earthlink.net www.cjgdesigns.net
PROJECT: REMODEL OF RITCHIE HILL FOR:	THE HOBSON FAMILY	391 UNION STREET SOUTH CONCORD, NC	EXISTING 2nd FLOOR PLAN	] -
FINA	ign: 01 ⊾: 03	.24.20 .31.20 .04.20	23	
	ISIONS:			
DRA	WING NUI WN BY: CKED BY:	C. J.		2
DETA	Α	\-	2	







	NOTICE: ALL FED REGULAT AND SPI PRECEDI	IERAL, STATE, LOCAL CON NONS SHALL BE CONSID ECIFICATIONS FOR THIS F ENCE OVER ANYTHING SH WHERE WARMON'S OCCU	des, ordinances and Red as part of plans Juliding and Shall Take Kown, described or Jr.	
	THESE D CONDITION USED BY COMPLET DIMENSIO	DRAWINGS ARE DIAGRAMA ONS AND DETAILS, AND / VEXPERIENCED MECHAN MENTARY TO THE OTHER ONS MUST BE VERIFIED	JR. TIC, NOT INDICATING ALL NER INTERDED TO BE CS. EACH DRAWING IS S. ALL CONDITIONS AND BY THE CONTRACTOR (F THESE DOCUMENTS IS RSONS PERFORMING THE	
	PRIOR T COMPLIA THE RES WORK. THIS DR	IO INSTALLATION. WOR INCE WITH THE INTENT O SPONSIBILITY OF THE PE WINNG AND THE INFORM	K PERFORMED NOT IN IF THESE DOCUMENTS IS RSONS PERFORMING THE NTION THEREON IS THE	
	FOR OTH THE WRI NOT PER UNALTER C COF	HT OF CUG DESIGNES. HER THAN THE INTENDED TITEN CONSENT CONSENT RMITTED. PERSON OR C 21 TITLE" BLOCK HAVE P RED COPIES OF THIS DR PYRIGHT 2023, CUG DESI	NTON THEREON IS THE MAY ALTERATION OR USE   PROJECT WITHOUT   OF CARY J. GLUF, IS OURPARY INAMED IN THE ERMISSION TO MAKE WINS. CNS.	
		oration	28025 18.net	
		The CABEM Corporation	147 GLENDALE AVE SE CONCORD NC 28025 C 980.621.0037 cjędesigns@earthlink.net www.cjędesigns.net	
		The CA	CORD www.c	
		ns	CON	
		G Designs	VE SE k.net	
		G Desi	147 GLENDALE AVE S C 980.621.0037 cjędesigns@earthlink.net	
	I BY:	GARY	LEND/ 621.00 gns@e	
	DRAWN BY		147 G C 980 cjgdesi	
		NC NC		
		CONCORD, NC		
		NCO	7	
			1st FLOOR PLAN	
	<b>OF RITCHIE HILL FOR:</b>	JBSON FAMILY	с С	
	Ē	AM	Ō	
	E H	L N	Γ	
	<b>RIT</b>	SO	1st	
	ΓOΓ	Ч С Е		
	REMODEL	391 UNION STREET SOUTH	PROPOSED	
	REM		DAC	
		STRI	RC	
		NOI		
		1 UN		
	PROJECT:	39		
	DATI DES FINA	IGN: 01.31.20	23	
	REV	ISIONS:		
	•			
	DRAV	WING NUMBER:	нов- А-3	
		WN BY: C. J. CKED BY: CJG	GLUF	
SF: 2,306 SF	Γ	٨		
852 SF Exhibit F		A-	<u>ර</u>	
	DETA	AIL		


# 2nd FLOOR HSF: 2,306 SF TOTAL HSF: 4,852 SF




МОДЕ: МОДЕ: ВОДИНОВ СТАНТИСКИ СОСТАНИИ СТАНТИКИ ВОДИНОВ САНТИКИ СОСТОВИНИ ОТ ИНИСКИ ИНИСКИ СТАНТИКИ СОСТОВИИ ОТ ИНИСКИ ИНИСКИ СТАНТИКИ СОСТОВИИ ОТ ИНИСКИ ИНИСКИ СТАНТИКИ СОСТОВИИ ОТ ИНИСКИ ИНИСКИ СТАНТИКИ ОТ ИНИСКИ ИНИСКИ СТАНТИКИ ИНИСКИ ПОНИСКИ СТАНИТИКИ ИНИСКИ СТАНТИКИ ИНИСКИ СТАНТИКИ ИНИСКИ СТАНТИ						
DRAWN BY:	CIG Designs	CARY J GLUF The CABEM Corporation	147 GLENDALE AVE SE CONCORD NC 28025 C 980.621.0037	cjgdesigns@earthlink.net www.cjgdesigns.net		
PROJECT: REMODEL OF RITCHIE HILL FOR:	THE HOBSON FAMILY	391 UNION STREET SOUTH CONCORD, NC	PROPOSED 2nd ELOOR PLAN	5		
FINA	IGN: 01	.24.20 .31.20 .04.20	23			
DRA	WING NU WN BY: CKED BY	C. J.		4		
DETA	Α	\	4			










STRUCTURE MEMBRANE ROOF PARAPET WALL IGN NEW PORCH EMENTS W/EXIST. d FLOOR PORCH CHING COLUMNS CESSED PORCH MATCHING SHAKE SIDING 2nd FLR ELEV. ISV WOODD DECK W/ UM. RAILING Ist FLR ELEV. W WOODD DECK W/ UM. RAILING MUDDING UM MEMBRANE ROD SHAKE SIDING 2nd FLR ELEV. W WOODD DECK W/ UM. RAILING MUDDING UM MEMBRANE ROD SHAKE SIDING 2nd FLR ELEV. MUDDING UM MEMBRANE ROD 2nd FLR ELEV. M			
IED OR NEW       MEMBRANE ROOF         MEMBRANE ROOF       PARAPET WALL         IGN NEW PORCH       EMENTS W/EXIST.         d FLOOR PORCH       MEMBRANE SUBING        2nd FLR ELEV.       Ist FLR ELEV.         Ist FLR ELEV.       Ist FLR ELEV.         WWOOD DECK W/ UM. RAILING       Ist RELEV.	D/HARDI	ALL FEDERAL, STATE, LOCAL CODES, ORDINANCES AND REGULATIONS SHALL BE CONSIDERED AS PART OF PLANS AND SPECIFICATIONS FOR THIS BUILDING AND SHALL TAKE REFERENCE OVER MARTHING SHORM DESCRIBED OF	
B <sup>I</sup> PARAPET WALL IGN NEW PORCH EMENTS W/EXIST. d FLOOR PORCH CHING COLUMNS CESSED PORCH MATCHING SHAKE SIDING 2nd FLR ELEV. IEW HANGER ROD SUPPORTED ALUM. NTRY CANOPY 1st FLR ELEV. W WOOD DECK W/ JM. RAILING MULTING IST PLR ELEV. W WOOD DECK W/ JM. RAILING IST PLR ELEV. IST PLR EL	STRUCTURE IED OR NEW	THE LINUMING AND THE INFORMATION THEREON IS THE PROPERTY OF CLO EDSING. WAY ALTERATION OR USE FOR OTHER THAN THE INTENDED PROJECT WITHOUT THE WRITTER CORRECT CONSISTOR OF CARY J. GUF, IS NOT PROMITTED, PERSON OR COMPANY NAMED IN THE PROJECT THE" BLOCK HAVE PERMISSION TO MAKE UNALTERED COMES OF THIS DRIVING.	
1st FLR ELEV. W WOOD DECK W/ UM. RAILING	SHAKE SIDING ———2nd FLR ELEV.	PRAMN BY: CJG Designs A CARY J GLUF CARY J GLUF 147 GLENDALE AVE SE CON C 980.621.0037 cjędesigns@earthlink.net	
FINAL: 03.04.2023 REVISIONS: DRAWING NUMBER: HOB- A-7 DRAWN BY: C, J. GLUF CHECKED BY: CJG	SUPPORTED ALUM. Intry CANOPY 1st FLR ELEV. W WOOD DECK W/ UM. RAILING	PROPOSED RIGHT ELEVAT	
CHECKED BY: CJG		Desiste: 01.31.2023 FINAL: 03.04.2023 REVISIONS:	




**Project Description:** 

- 1. Owners are proposing to demolish most of the existing roof structure on the back of the house which covers the single-story area of the house. The non-contributing, first story Kitchen Pantry, rear wood deck, and trash can enclosure, will also be demolished. The small, second story shed roof, which covers the only second story bathroom will also be demolished. The unused brick chimney on the back of the Laundry Room will be demolished.
- 2. Left and Right designations are considered looking from the front of the house.
- 3. Exterior new work is limited to the area behind the two story, double gable back wall, considered to be the limit of the main, original house. All exterior walls affected by this project, including the double gable back wall, are currently covered with vinyl siding.
- 4. Owners are proposing a two-story addition which will square up the back of the house and the existing bay window with an additional 323 SF of heated area on the first floor and 974 SF on the second floor.
- 5. The addition/remodel includes the following First Floor items: A new Kitchen which includes a new, triple 20x44 double-hung, 1 over 1 window on the rear of the house. A remodeled Breakfast Room with a 3'-5" x 11'-0" bump-out. The bump-out includes a pair of 30"x96" patio doors and four 18"x72" double-hung, 1 over 1 windows. A new 3'x7'-6" hanger rod supported aluminum canopy will sill sit above the entry doors. A new Family room which includes a double 28"x80", double-hung, 2 over 1 window on the left side. This double window replaces two separate, mis-matched double hung windows in the same area. A new 7' X 14', one-story Pantry/Half Bath addition which connects the Kitchen to a new Screened Porch. The Pantry and Half Bath each have one 20"x20" awning window. One faces the back of the house and one faces the front. A 32"x84" patio door opens to the Screened Porch. A new 14' x 16' Screened Porch which includes a stacked-stone fireplace. It has a brick foundation and slate roof. The rear window (center picture with flanking casements) will be replaced with a pair of doublehung, 2 over 1 windows which will fit the existing opening. A new 447 SF wood deck on the rear, with a combination wood and metal railing. Decking may be either standard pressure treated lumber or DuxxBak composite lumber.
- 6. The addition/remodel includes the following Second Floor items: A new Owner's Suite (15'-8" x 21'-10") matches the footprint of the first floor Laundry Room/Bathroom area. It includes tow 32"x72" double-hung, 2 over 1 windows on the right side and a triple 32"x72" double-hung, 2 over 1 set of windows on the rear. The new roof line will extend from the existing left gable on the rear of the house. A new Covered Porch, accessed from the Owner's Suite via a 32"x84" patio door. The porch includes a 60'x60" picture window located on the back wall of the new Owner's Bath. Porch design mimics the elements of existing porches with the addition of a metal railing to improve the view of the back yard. A new Children's Suite (16'-7" x 28'-5") located above the new Kitchen/Family Room area. It includes two 32"x60" double-hung, 2 over 1 windows and one 20"X20" awning window on the left side and a pair of 32"x72" double-hung, 2 over 1 windows on the rear.
- 7. The existing generator will be relocated to less prominent location on the property per the new Site Plan. It will be screened on the front with vegetation.

- 8. Owners intend to match the existing siding, trim, soffit/fascia, and roofing materials of the original, existing house as closely as possible. New siding will be solid wood or cement fiber lap siding and shake siding. Lap exposure and shake size to match as closely as possible, noting the varied sizes of shake siding pieces. New wood columns will match existing columns as closely as possible. New roof pitches will match existing as closely as possible with the exception of the Kitchen/Screened Porch connector. The new Screened Porch and Connector will have a slate tile roof (new or reclaimed). The two new, second story gables will have slate tiles roofing on the outward facing planes and asphalt shingles on the interior facing planes. There is a large cricket roof between the two new gables, which will be covered with a membrane system.
- 9. Some existing gravel drive areas will be removed and replaced with lawn. A new circular area will be added at the front, right of the house. Please see the Site Plans.


Proposed Windows by Marvin

Multiple sizes, as described above, will be used These all wood windows will match the materials of the main house windows. None of the new windows are replacing any original, historically significant windows. the new windows are designed to be compatible with the existing house, and per the Historic handbook, will be discernable from the original windows. The 5/8" SDL mullion detail will be used.



Proposed Window Details

Windows will not include aluminum cladding on the exterior.



Metal Deck Railing-Color: Black



## Why OPTIMA<sup>™</sup> Plus Rail for Your Deck Rail Options?

- Pre-Assembled Panels for Fast and Easy Installation
- Durable aluminum construction with an Akzo Nobel AAMA 2604 powder-coat applied by certified AAMA painters
- Engineered, tested and approved to ICC-ESR 4813 and is IBC/IRC-compliant
- Flat Top Rail for a beverage-friendly surface
- Hidden Fastener System and No Welds
- Available in three textured powder coat colors: Black, White and Bronze.
- 15-Year Limited Warranty

# New Rear Deck. Wood Grain Embossed. Color to be determined.





**DuxxBak® Dekk** is our revolutionary deck board that made us famous by combining our weather defying compound with a water-shedding, no drip profile that creates a dry space beneath your deck, walkway or balcony.

Rescue your family barbecue from an unexpected downpour or create a functional storage area underneath your deck with this premiere composite. Its unique water-shedding properties protect your home by channeling water away from the foundation. You will also protect your deck structure from rotting as a result of exposure to the elements, a major cause of deck failure. Available in both our beautiful, wood-grain embossed ArmorCap or more functional Traction finish, this no drip through composite decking will increase the functionality of your deck, and is increasingly being specified for use on multi-family housing projects where stacked decks are popular.

DuxxBak Dekk is engineered to shed water from the deck without the need for a secondary water-drainage system. It diverts the water away from your home through its watertight design.

Create additional living space with Duxxbak Dekk. It is the only complete wood-free and PVC-free, composite, water-shedding deck system on the market.

## Screened Porch Chimney. Color to be determined.



#### **Natural Stone Panels**


Natural Stone Panels are trimmed pieces of REAL stone affixed together to form modular interlocking panels. This allows for a fast and efficient installation of a beautiful dry stacked stone veneer.

- Color/Type
- □ Cambridge Blend<sup>™</sup>
- Homestead
- Shape Ledgestone Stone Veneer Stacked Stone Stone Panels





# New Entry Canopy at New Back Doors



### End of Document

# **Existing Photos**

# Existing House: View from Union Street South



# Existing House: View from Left Side



Area of Addition will replace the singled roof areas on the left side of this photo

Existing House: View from Rear



Additional Rear View



Existing House: View from Left Side



Area of Addition will replace the singled roof area on the right side of this photo

The only new work that will be visible from Union Street will be the new Screened Porch and Connector to the Kitchen.

End of Document



### DATE:

SUBJECT:

Certificate of Appropriateness Request: Applicants: Location of Subject Property: <u>PIN :</u> Staff Report Prepared by: June 14, 2023

H-08-23 Brian and Robin Dicka 216 Union Street S 5630-05-4967 Jeff Ellis, Planner

#### **BACKGROUND**

- The subject property at 216 Union St S is designated as a "Pivotal" structure in the South Union Street Historic District (ca. 1901) (Exhibit A).
- Picturesque, asymmetrical, two-story, frame, Queen Anne style residence, the finest example of the style in the district and one of the best in Concord. House has wrap-around porch, supported by turned posts, with an unusual balustrade of horizontal and vertical members and an arched spindle frieze. A pair of projecting two-story bays flank the center of the three-bay facade and gives the front elevation its picturesque asymmetry. Both bays have ornate corner brackets and are sheathed in decorative sawn arid paneled boards; the north (right) bay projects at a 45-degree angle. from the rest of the facade. A broad arch engaged by the main roofline shelters a tiny balcony at  $\cdot$  the center of the second story. The house retains its massive original chimneys. The interior has lost its original mantels but retains a notable three-run stair.
- The house was built for James ·F. Dayvault, who purchased the property in 1901. Dayvault was a partner in Dayvault and Guffey, a meat packing firm established in 1892 as a successor to the Cook Packing Company.

#### **DISCUSSION**

• On March 9th, 2023, Brian and Robin Dicka applied for a Certificate of Appropriateness requesting approval to remove the current chain link fence at the back of their property, in order to construct a 6' wooden privacy fence. The fence would then be stained in order to match their existing home located at 216 Union St S. (Exhibit B)

#### **ATTACHMENTS**

Exhibit A: National Register of Historic Places Inventory Exhibit B: Certificate of Appropriateness Application Exhibit C: Subject Property Map Exhibit D: Applicant Submitted Photographs

#### HISTORIC HANDBOOK DESIGN RECOMMENDATIONS

Approval Requirement Needs Table: Type of Work Requiring Commission Hearing and Approval

• Fencing and Gates: All types require Commission Hearing and Approval.

#### Chapter 5 – Section 9: Fences and Walls

• All wooden fences should be "stick-built" on site.

- Painting or staining is recommended, but not required, for rear yard fences unless they are visible from the street.
- Rear yard fences may be higher than four feet. The portions of rear yard fences that face the street should be landscaped with shrubs and trees of a planting size that will fully hide the fence from the street within two years. Size, type, and growth habits of plant materials to screen rear yard fences that face the street should be submitted at time of application.
- All proposed fences and walls should not negatively affect existing trees and mature landscaping.
- Privacy fences are defined as fences with no spacing between pickets or fences of the shadowbox design. Privacy fences may be allowed at the discretion of the Commission in the following circumstances:
  - 1. Privacy fences are most appropriate in rear yards.
  - 2. Privacy fences may be allowed where the applicant's rear yard is directly adjacent to property that is either not in a historic district, or is within a historic district but is non-contributing or intrusive in that district. The applicant shall show to the satisfaction of the Commission:
    - (a) that the adjacent property is unsightly in comparison to other properties surrounding the applicant's property,
    - *(b)that the adjacent property or nearby property raises reasonable security concerns for the applicant, or*
    - (c) that the adjacent property could reasonably be determined to negatively impact the property value of the applicant's property.
  - 3. Privacy fences encompassing an area of no more than 250 square feet may be allowed at the discretion of the Commission when adjacent to the applicant's house, garage, or other outbuilding in order to screen from view trash cans, mechanical equipment, cars or other unsightly items, provided such fence does not unreasonably impact any neighbor by blocking windows or the like.
  - 4. Privacy fences allowed by the Commission should be landscaped where practical with appropriate shrubbery to soften the appearance of the fence.

#### <u>Design Guidelines</u>

- 1. Use materials like stone, brick, wood and iron.
- 2. Chain link or plastic materials are prohibited. Adding slats to existing chain link fences for screening purposes is prohibited.
- 3. Materials and style should coordinate with building and neighboring buildings as well as other walls and fences in the area.


#### **RECOMMENDATION:**

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u> <u>Handbook and Guidelines</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
  - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
  - Completed project will be photographed to update the historic properties survey.

NPS Form 10-900-a (3-82)

### **United States Department of the Interior** National Park Service

# National Register of Historic Places Inventory—Nomination Form



OMB No. 1024-0018

Expires 10-31-87

Continuation sheet	Item number	Page
Inventory List - South Union Street	#7	18
Historic District, Concord		

many years and is a knowledgeable local historian and genealogist. He and his wife still live in the house they built in 1924.

33. House 222 S. Union St. ca. 1950 F

Simple, two-story, frame Colonial style house with side gable roof and shed-roofed porch along north elevation.

34. James 216 9

James Dayvault House 216 S. Union St. 1901 P

Picturesque, asymmetrical, two-story, frame, Queen Anne style residence, the finest example of the style in the district and one of the best in House has wrap-around porch, supported by turned posts, Concord. with an unusual balustrade of horizontal and vertical members and A pair of projecting two-story bays flank an arched spindle frieze. the center of the three-bay facade and gives the front elevation its picturesque asymmetry. Both bays have ornate corner brackets and are sheathed in decorative sawn and paneled boards; the north (right) bay projects at a 45-degree angle from the rest of the facade. Α broad arch engaged by the main roofline shelters a tiny balcony at the center of the second story. The house retains its massive original The interior has lost its original mantels but retains a chimneys. notable three-run stair.

The house was built for James F. Dayvault, who purchased the property in 1901. Dayvault was a partner in Dayvault and Guffey, a meat packing firm established in 1892 as a successor to the Cook Packing Company.

35.

House 210 S. Union St. by 1906 (SM) C

Two-story, frame house with clipped side gable roof and unusual flanking one-story wings, also with clipped gables. Unusual recessed center bay on both stories. Full facade porch with turned posts and balustrade on first floor, and balcony in recessed space above entrance on second flcor; balcony is topped with decorative center gable.





Exhibit B

### AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

APPLICANT INFORMATION		
Name: Brigh & Robin Dicko		
Address: 216 Union St. S.		,
City: Concord State: NC Zip Code: 27025	Telephone: <u>919-454</u>	-8955
OWNER INFORMATION		
Name: Sand as above		
Address:	/	
City: State: Zip Code:	Telephone:	
SUBJECT PROPERTY		
Street Address: 216 Union St. S.	P.I.N. #	······
Area (acres or square feet):Current Zoning:	Land Use:	
Staff Use Only:		
Application Received by:	Date:	, 20
Fee: \$20.00 Received by:	Date:	20

The application fee is nonrefundable.

Planning & Neighborhood Development 35 Cabarrus Ave W • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov



#### **General Requirements**

The Unified Development Ordinance imposes the following rules, regulations and requirements on requests for Certificates of Appropriateness. The applicant must, with reference to the attached plans, demonstrate how the proposed use satisfies these requirements:

1. Project or Type of Work to be Done: 2. ailed specifications of the project (type of siding, windows, doors, height/style of fence, color, etc.) Det Wood neo

#### Required Attachments/Submittals

- 1. Scaled site plan, if additions or accessory structures are proposed, on letter, legal or ledger paper. Larger sized copies will be accepted if **16 folded copies** are submitted for distribution.
- 2. A photograph of the front of the house.
- 3. Photographs of site, project, or existing structures from a "before" perspective
- 4. Drawings, sketches, renderings, elevations, or photographs necessary to present an illustration of the project from an "after" perspective.
- 5. Samples of windows, doors, brick, siding, etc. must be submitted with application.
- 6. Detailed list of materials that will be used to complete the project.

\*\*\*Applications may be submitted electronically.\*\*\*

#### Certification

(1) I hereby acknowledge and say that the information contained herein and herewith is true and that this application shall not be scheduled for official consideration until all of the required contents are submitted in proper form to the City of Concord Development Services Department. (2) I understand that City staff and/or members of the Historic Preservation Commission may make routine visits to the site to insure that work being done is the same as the work that was approved. (3) I understand that photographs of the completed project will be made to update the City's historic districts inventory database.


Date

Signature of Owner/Agent

Planning & Neighborhood Development 35 Cabarrus Ave W • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov



H-08-23 216 Union St S PIN: 5630-05-4967





Source: City of Concord Planning Department

#### Disclaimer

These maps and products are designed for general reference only and data contained herein is subject to change. The City Of Concord, it's employees or agents make no warranty of merchantability or fitness for any purpose, expressed or implied, and assume no legal responsibility for the information contained therein. Data used is from multiple sources with various scales and accuracy. Additional research such as field surveys may be necessary to determine actual conditions.







wood privacy fence to replace 

existing wood fence to stain/paint to preserve









# DATE:

June 14, 2023

**SUBJECT:** 

Certificate of Appropriateness Request: Applicant: Location of Subject Property: <u>PINs:</u> Staff Report Prepared by: H-06-23 Chad VanKeuren 120 Union St N 5620-79-1486 Jeff Ellis, Planner

# BACKGROUND

- The subject property at 120 Union Street N is designated as a "Contributing" structure in the North Union Street Historic District (ca. 1916) (Exhibit A).
- "One-and-a-half-story, frame, Colonial Revival house with gambrel roof. House has broad, onebay, pedimented portico with Tuscan columns and board, pedimented dormer with four windows. Windows have 9/1 sash; round-headed windows light attic on both sides of house. I. I. Davis was Assistant Secretary-Treasurer to the Hartsell Mills Company" (Exhibit A).
- Applicant requesting modification: removal of one (1) Burford Holly tree on the right side of property. (Exhibit B).

# **DISCUSSION**

On March 7, 2023, Chad VanKueren applied for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 to remove one (1) Burford Holly tree located on the right side of the home (front of house perspective). (Exhibit E).

According to the Tree Risk Assessment Form (Exhibit D), the subject tree was inspected and evaluated by Bill Leake, City Arborist, on November 22, 2022. Bill notes the subject tree has no structural defects, and that it is in close proximity to the applicant's home.

Due to the Risk Rating score of three (3), the removal of healthy trees/limbs requires Historic Preservation Commission review and approval.

# **ATTACHMENTS**

Exhibit A: National Register of Historic Places Inventory Exhibit B: Certificate of Appropriateness Application Exhibit C: Subject Property Map Exhibit D: Tree Risk Assessment Form Exhibit E: City Arborist Tree Photograph

# HISTORIC HANDBOOK DESIGN RECOMMENDATIONS

# **Approval Requirement Needs Table**

- *Removal of healthy trees or pruning of limbs over six (6) inches in diameter in any location on the property requires Commission hearing and approval.*
- Tree topping removal of one-third of green surface of canopy, or leaving stubs larger than three (3) inches in diameter requires Commission hearing and approval.

# Chapter 5 – Section 8: Landscaping and Trees

- One of the most visible features of the Districts is the landscaping and the associated tree canopy. Activities which negatively impact any aspect of the landscape should be avoided, such as the removal of healthy trees and mature shrubs.
- Tree health may be decided upon by the acquisition of a Tree Hazard Evaluation Form issued by the City Arborist or a report submitted by a certified arborist. Healthy trees are trees that have a hazard rating of four (4) or lower. Removal of healthy trees over the size of six (6) inches in diameter (measured four (4) feet above ground) or pruning of healthy tree limbs over six (6) inches in diameter requires Historic Preservation Commission review and approval.
- All trees that are removed should be replaced with a tree of similar species in an appropriate location unless no suitable location exists on the subject site. Trees removed within street view must also have the stumps removed below ground level.
- Design Standards: Landscaping and Trees

2. Trees which are removed shall be replaced by a species which, upon maturity, is similar in scale to the removed specimen. For example, canopy trees shall be replaced with canopy trees, and understory trees with understory trees.

# **RECOMMENDATION**

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u> <u>Handbook and Guidelines</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
  - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
  - Completed project will be photographed to update the historic properties survey.

NPS' Form 10-900-a (3-82)

3

27

EXHIBIT A

# United States Department of the Interior National Park Service National Register of Historic Places Inventory—Nomination Form Continuation sheet

Invesntory List - North Union Street Historic District, Concord

> Italianate houses in Concord, which display trim typical of the style but retain a horizontal quality reflecting the traditional house forms of the North Carolina piedmont, the main block of the house has a tall, narrow form not ulike the Italianate townhouses then being built in cities of the northeast. One-story wings on both sides of the house, however, make possible a spacious first floor plan. House retains much of its Italianate exterior trim, including a paneled frieze with a sawnwork border and intricately sawn brackets. The porch, supported by thick brick piers, was the major element of a remodeling of the house undertaken in the 1920s.

#7

James William Cannon, about whom there is additional discussion in the essay on the district's significance, lived in this house until 1899, when he erected the house at 65 North Union Street, and sold this property to Amanda Boger, the wife of farmer and businessman Martin Boger (1844-1921). After Boger's death the house passed to his daughter, Pearl Boger Lafferty, the wife of pharmacist Parks Lafferty, who had the house remodeled during the 1920s.

25. I.I. Davis House 118 North Union Street ca. 1916 (SM) C

> One-and-a-half-story, frame, Colonial Revival house with gambrel roof. House has broad, one-bay, pedimented portico with Tuscan columns and board, pedimented dormer with four windows. Windows have 9/1 sash; round-headed windows light attic on both sides of house. I.I. Davis was Assistant Secretary-Treasurer to the Hartsell Mills Company

26. William J. Hill House 116 North Union Street 1906 C

> Two-story, frame house with Queen Anne and Colonial Revival elements, recently rescued from a long period of neglect. Main block has side gable roof; north (left) facade bay projects forward and has gable-front roof. Front and side gables have fish scale shingles and dentil trim. Wrap-around porch with Tuscan columns, pediment over entrance bay, and balustrade. William J. Hill was the founder and president of W.J. Hill Company.



**EXHIBIT B** 

# AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

#### APPLICANT INFORMATION

Name: Chad VanKeuren	
Address: 120 Union St N	
City: ConcordState: NCZip Code: 28025Telephone: 64	<mark>16-406-1486</mark>
Email: <mark>cvank8@gmail.com</mark>	
OWNER INFORMATION	
Name: Chad VanKeuren	
Address: 120 Union St N	
City: Concord State: NC Zip Code: 28025 Telephone: 64	<mark>46-406-1486</mark>

Email: cvank8@gmail.com

#### SUBJECT PROPERTY

Street Address: 120 Union St N		P.I.N. # <mark>5620-79-9239</mark>		
Area (acres or square feet): 0.20	Current Zoning: RM-1	Land Use: Single Family Residential		

	Staff Use Only:	
Application Received by:	Date:	, 20
Fee: \$20.00 Received by:	Date:	, 20

Planning & Neighborhood Development 35 Cabarrus Ave W • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov



#### **General Requirements**

The Unified Development Ordinance imposes the following rules, regulations and requirements on requests for Certificates of Appropriateness. The applicant must, with reference to the attached plans, demonstrate how the proposed use satisfies these requirements:

1. Project or Type of Work to be Done: I'd like to remove the Burford Holly to the right of my house (when viewing it from the front). While I'm a huge proponent of plants and am an avid gardener, unfortunately this Holly is just overgrown for the current space -- it is too close to my house (which leads to squirrels and other pests getting access to my roof, wiring, etc), it extends into my neighbor's yard, and the roots are right under my sidewalk which will inevitably cause damage if not removed. I am more than happy to replace it with a similar species in the same vicinity!

2. Detailed specifications of the project (type of siding, windows, doors, height/style of fence, color, etc.): The plan will be the safely remove the Burford Holly with a professional landscaping company.

#### Required Attachments/Submittals

- 1. Scaled site plan, if additions or accessory structures are proposed, on letter, legal or ledger paper. Larger sized copies will be accepted if **16 folded copies** are submitted for distribution.
- 2. A photograph of the front of the house.
- 3. Photographs of site, project, or existing structures from a "before" perspective.
- 4. Drawings, sketches, renderings, elevations, or photographs necessary to present an illustration of the project from an "after" perspective.
- 5. Samples of windows, doors, brick, siding, etc., may be submitted with application.
- 6. Detailed list of materials that will be used to complete the project.

\*\*\* Applications may be submitted electronically. \*\*\*

#### Certification


(1) I hereby acknowledge and say that the information contained herein and herewith is true and that this application shall not be scheduled for official consideration until all of the required contents are submitted in proper form to the City of Concord Development Services Department. (2) I understand that City staff and/or members of the Historic Preservation Commission may make routine visits to the site to insure that work being done is the same as the work that was approved. (3) I understand that photographs of the completed project will be made to update the City's historic districts inventory database.

3-7-23


Date

Signature of Owner/Agent

Planning & Neighborhood Development 35 Cabarrus Ave W • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov



H-06-23 120 Union St N PIN: 5620-79-9239





Source: City of Concord Planning Department

#### Disclaimer

These maps and products are designed for general reference only and data contained herein is subject to change. The City Of Concord, it's employees or agents make no warranty of merchantability or fitness for any purpose, expressed or implied, and assume no legal responsibility for the information contained therein. Data used is from multiple sources with various scales and accuracy. Additional research such as field surveys may be necessary to determine actual conditions.

**EXHIBIT C** 



Site/Address: 120 Union St N

Map/Location: Left Rear Corner of House

Owner: public: \_\_\_\_\_ private: \_\_\_X unknown: \_\_\_\_\_ other: \_\_\_\_\_

Date: 11/22/22\_\_\_\_ Inspector: Bill Leake

Date of last inspection:

# TREE CHARACTERISTICS

Tree #: 1 Species: Burford Holly (Ilex cortuna)

**DBH:** 14.5" # of trunks: 3 Height: 30' Spread: 20'

Form:  $\Box$  generally symmetric  $\boxtimes$  minor asymmetry  $\Box$  major asymmetry  $\Box$  stump sprout  $\Box$  stag-headed

**Crown class**: □ dominant ⊠ co-dominant □ intermediate □ suppressed

Live crown ratio: 98 % Age class:  $\Box$  young  $\Box$  semi-mature  $\boxtimes$  mature  $\Box$  over-mature/senescent

 Pruning history:
 □ crown cleaned
 □ excessively thinned
 □ topped
 ⊠ crown raised
 □ pollarded
 □ crown reduced
 □ flush cuts

 □ cabled/braced
 □ none
 ⊠ multiple pruning events
 Approx. dates:

Special Value: 🗆 specimen 🛛 heritage/historic 🗆 wildlife 🗆 unusual 🗆 street tree 🗆 screen 🗆 shade 🗆 indigenous 🖾 protected by gov. agency

# TREE HEALTH \_\_\_\_\_

Foliage color. 🛛 normal	$\Box$ chlorotic $\Box$	necrotic Epicor	mics; 🗆		Growth obstruc	tions:
Foliage density:	⊠normal □	∃sparse <b>Leaf</b>	f size: 🛛 no	ormal 🗆 small	$\Box$ stakes $\Box$ wire/ties	$\Box$ signs $\Box$ cables
Annual shoot growth:	$\Box$ excellent $\boxtimes$	average 🗆 poor	r 🗆 none	Twig Dieback: 🛛	⊠ curb/pavement	⊠ building
Woundwood :	$\Box$ excellent $\boxtimes$	average 🗆 fair 🛛	□ poor			
Vigor class:	□ excellent ⊠	average 🗆 fair 🛛	□ poor			
Major pests/diseases:	None					

# SITE CONDITIONS \_\_\_\_

 Site Character:
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x

# TARGET\_

 Use Under Tree:
 building
 parking
 traffic
 pedestrian
 recreation
 Iandscape
 hardscape
 small features
 wtility lines

 Can target be moved?
 NO
 Can use be restricted?
 NO

 Occupancy:
 □ occasional use
 □ intermittent use
 □ frequent use
 □ constant use
 □ constant use

# **EXHIBIT D**

#### **RISK RATING:**

1	0	2	3
Failure	+ Size +	Target	= Risk
Potential	of part	Rating	Rating

If approved for removal, the replacement tree species and location shall be listed on the certificate of appropriateness.

# TREE DEFECTS

ROOT DEFECTS:
Suspect root rot: NO Mushroom/conk/bracket present: NO ID:
<b>Exposed roots:</b> $\Box$ severe $\Box$ moderate $\boxtimes$ low <b>Undermined:</b> $\Box$ severe $\Box$ moderate $\boxtimes$ low
Root pruned: distance from trunk Root area affected: Buttress wounded: 🗆 When:
Restricted root area: $\Box$ severe $\Box$ moderate $\boxtimes$ low Potential for root failure: $\Box$ severe $\Box$ moderate $\boxtimes$ low
LEAN: 0 deg. from vertical 🛛 natural 🖓 unnatural 🖓 self-corrected 🖓 Soil heaving:
Decay in plane of lean:  Roots broken:  Soil cracking:
Compounding factors: Lean severity:  Severe moderate  low

*Concern Areas:* Indicate presence of individual structural issues and rate their severity (**S** = severe, **M** = moderate, **L** = low)

DEFECT	ROOT CROWN	TRUNK	SCAFFOLDS	BRANCHES
Poor taper				
Bow, sweep				
Codominants/forks		М		
Multiple attachments				
Included bark				
Excessive end weight				
Cracks/splits				
Hangers				
Girdling				
Wounds/seam				
Decay				
Cavity				
Conks/mushrooms/bracket				
Bleeding/sap flow				
Loose/cracked bark				
Nesting hole/bee hive				
Deadwood/stubs				
Borers/termites/ants				
Cankers/galls/burls				
Previous failure				
RISK RATING				

Tree part most likely to fail in the next six months: Branches

Failure potential: 1 - low: 2 - medium; 3 - high; 4 - severe	Size of part: <b>0</b> -0" - 3" <b>1</b> - 3"-6"	<b>2</b> -6"-18"	<b>3</b> -18"-30"	<b>4</b> ->30"
Target rating: 0 - no target 1 - occasional use 2 - intermittent use 3 - frequent use 4	- constant use			

# **Maintenance Recommendations**

Failure Potential + Size of Part + Target Rating = Hazard Rating	$\Box$ none $\Box$ remove defective part $\Box$ reduce end weight $\Box$ crown clean				
<u>    1    0    2    3  </u>	$\Box$ thin $\Box$ raise canopy $\Box$ crown reduce $\Box$ restructure $\Box$ cable/brace				
	Inspect further $\Box$ root crown $\Box$ decay $\Box$ aerial $\Box$ monitor				
$\hfill\square$ Remove tree $\hfill\square$ When replaced, a similar sized tree spectrum tree spe	cies would be appropriate in same general location				
$\Box$ When replaced, alternate tree replacement locations are available					
Effect on adjacent trees: 🗆 none 🗆 evaluate					
Notification:  Output on the second s					
COMMENTS					

This tree has no structural defects. It is in close proximity to the home.

Bill Leake



# EXHIBIT E



Agenda Memorandum Historic Preservation Commission

DATE	June 14, 2023
<u>SUBJECT</u>	
Certificate of Appropriateness Request:	H-09-23
Applicant:	Robert Ritchie
Location of subject property:	406 Union St S
<u>PIN:</u>	5630-14-7115
Staff Report prepared by:	Jeff Ellis, Planner

# BACKGROUND

- The subject property Dr. S. E Buchanan House, 406 S Union St (ca. 1921-1927), is designated as a "Contributing" structure in the South Union Street Historic District (Exhibit A).
- One-and-a-half story, frame bungalow with side gable roof and deep, two-bay, gable-front porch. House has broad eaves trimmed with curved brackets and 4/1 sash windows characteristic of bungalow style; another typical feature is gable-roofed dormer over north (right) facade bay. Porch is upheld by brick piers trimmed with concrete and has an arched frieze; its eaves treatment echoes that of the house's main block. At rear is two-story garage and utility structure contemporary with the house. (Exhibit A).

# **DISCUSSION**

On April 25, 2023, Robert Ritchie, applied for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 for relocation of existing picket fence and widen a small section of upper driveway with low curb (Exhibit B).

**Detailed specifications of the project:** The proposed fence relocation would consist of 4' tall French Gothic treated wood pickets, treated 4x4 and 2x4 framing materials to match existing fence. This will create a 12'x14' area that could be used for parking. The proposed curb replacement consists of replacing a 5' section of the curb with a curved curb section and concrete. This will widen the driveway to 10' from 7'8", improving vehicle access.

# **ATTACHMENTS**

Exhibit A: National Register of Historic Places Inventory Exhibit B: Application for Certificate of Appropriateness Exhibit C: Subject Property Map Exhibit D: Applicant Submitted Photographs

# HISTORIC HANDBOOK DESIGN RECOMMENDATIONS

# **Approval Requirement Needs Table: Fencing and Gates**

All types require Commission Hearing and Approval.

# Approval Requirement Needs Table: Patios, Walks, and Driveways

All new patios, walks, and driveways require Commission Hearing and Approval.

# Chapter 5 – Section 9: Fences and Walls

- Fences should be compatible with most structures in the districts.
- All wooden fences should be "stick-built" on site.

- Wooden fences visible from the street and/or wooden fences in front yards and side yards of corner lots are required to be painted or stained white or a color matching the body or trim of the structure, including shutters, foundation color, etc.
- Painting or staining is recommended, but not required, for rear yard fences unless they are visible from the street.
- Wood picket fences should have pickets spaced at a minimum of 1 inch or half the width of the picket
- Front yard fences should not exceed four feet in height.

# Design Standards: Fences and Walls

- Do not use high walls or fences to screen front yards.
- Use materials such as natural stone, brick, wood, powder coated aluminum and iron.
- Chain link or plastic materials are prohibited.
- Materials and style should coordinate with building and neighboring buildings as well as other walls and fences in the area.

# Chapter 5 – Section 10: Driveways, Walkways, and Parking


- Parking areas should not be the focal point of the property, and should be located in such a manner as to minimize their visibility from the street.
- *Excessive expanses of paving should be avoided.*
- Use vegetation screen or berms to reduce reflection and visual confusion. Within residential areas, integrate parking areas into landscaping and surface with the appropriate materials such as concrete, brick, crushed stone or gravel. In general, asphalt should only be used for areas not visible from the street; its use will be considered on a case by case basis by the Historic Preservation Commission.

# **RECOMMENDATION**

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u> <u>Handbook</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
  - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
  - Completed project will be photographed to update the historic properties survey.

# **United States Department of the Interior** National Park Service

# National Register of Historic Places Inventory—Nomination Form



OMB NO. 1024-0018

Expires 10-31-87

Continuation sheet	Item number	Page
Inventory List - South Union Street	#7	10
Historic District, Concord		

accentuates impressive site of house on ridge overlooking S. Union St.

7. L. A. Weddington House 414 S. Union St. by 1921 (SM) C

> Two-story, frame, double-pile house with hip roof, simple details, and slightly asymmetrical form. One-story, shed-roofed porch with square-in-section wood posts on brick bases and balustrade. Facade has symmetrical fenestration with paired, 9/2 sash windows flanking entrance on first floor and single 9/2 window at second story. Asymmetrical features are the projecting north (right) first story facade bay, and the slightly projecting southeast (left front) corner of the house. At rear is two-story garage and utility structure contemporary with house.

8. Dr. S. E. Buchanan House 406 S. Union Street 1921-1927 (SM) C

One-and-a-half story, frame bungalow with side gable roof and deep, two-bay, gable-front porch. House has broad eaves trimmed with curved brackets and 4/1 sash windows characteristic of bungalow style; another typical feature is gable-roofed dormer over north (right) facade bay. Porch is upheld by brick piers trimmed with concrete and has an arched frieze; its eaves treatment echoes that of the house's main block. At rear is two-story garage and utility structure contemporary with the house.

9. R. C. Crook's House 398 S. Union St. 1921-1927 (SM) C

> One-and-a-half story, relatively tall and narrow frame bungalow with a brick veneer laid in Flemish bond. Side gable roof with semi-engaged, full-facade porch with tapered posts on brick bases and balustrade. Principal feature or facade is tall, gable-front dormer with three 6/1 sash windows and exposed rafters; dormer is clad in scallop-shaped, asbestos shingles. Ground floor facade symmetrical with pairs of unusually tall and narrow 6/1 sash windows flanking a central entrance with sidelights. Shallow raised foundation accentuates both the house's





Application for Certificate of Appropriateness

EXHIBIT

В

# AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

APPLICANT INFORMATION

Name: ROBE	RT L.	RITCHIG		-	
Address: 415	SPRING	STREET	500		
City: CONCORD	State: NL	Zip Code:_ <b>280</b>	25 Telephone:	980	621-3175

### **OWNER INFORMATION**

Name: PRISCILLA BUCHANAN	RITCHIE	
Address: 415 SPRING STREET		18
City: CONCORD State: NC Zip Code:	28025 Telephone:	780 621-7818


### SUBJECT PROPERTY

Street Address:	406	UNION	STRGET	SOUTH	P.I.N. #	
Street Address:	706	UNION	STREET	JULIA	_P.I.N. #	_

Area (acres or square feet): 1/2 ACRE Current Zoning: RM-2 Land Use: SINGLG FAMILY

	Staff Use Only:	
Application Received by:	Date:	, 20
Fee: \$20.00 Received by:	Date:	, 20
The	application fee is nonrefundable.	1 H

Planning & Neighborhood Development 35 Cabarrus Ave W • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov





#### **General Requirements**

The Unified Development Ordinance imposes the following rules, regulations and requirements on requests for Certificates of Appropriateness. The applicant must, with reference to the attached plans, demonstrate how the proposed use satisfies these requirements:

1. Project or Type of Work to be Done: <u>RELOCATE EXISTING PICKET FENCE</u> <u>AND WIDEN SMALL SECTION OF MPGE DRIVEWAY WITH LOW CURB</u> 2. Detailed specifications of the project (type of siding, windows, doors, height/style of fence, color, etc.): <u>FENCE-4' FRENCH GOTNEE TREATED WOOD PICKETS, TREATED</u> <u>AX4 AND 2×4 FRAMING MATERIALS TO MATCH EXISTING FENCE</u> <u>THIS WILL CREATE A 12'× 14' AREA THAT COULD BE USED FOR</u> <u>PARKING, REPLACE A 5' SECTION OF CURB AJ TOI OF DRIVEWAY</u> <u>WITH A CURVED CURB SECTION TO WIDEN DRIVEWAY FROM 7'B"</u> TO 10' AND IMPROVE VEHICLE ACCESS

#### Required Attachments/Submittals

- 1. Scaled site plan, if additions or accessory structures are proposed, on letter, legal or ledger paper. Larger sized copies will be accepted. **Digital copies are preferred.**
- 2. Detailed written description of the project.
- 3. Photographs of site, project, or existing structures from a "before" perspective.
- 4. Drawings, sketches, renderings, elevations, or photographs necessary to present an illustration of the project from an "after" perspective if applicable.
- 5. Samples of windows, doors, brick, siding, etc. must be submitted with application.
- 6. Detailed list of materials that will be used to complete the project.

#### Certification

(1) I hereby acknowledge and say that the information contained herein and herewith is true and that this application shall not be scheduled for official consideration until all of the required contents are submitted in proper form to the City of Concord Development Services Department. (2) I understand that City staff and/or members of the Historic Preservation Commission may make routine visits to the site to insure that work being done is the same as the work that was approved. (3) I understand that photographs of the completed project will be made to update the City's historic districts inventory database.

5-17-23

Date


Signature of Owner/Agent

Planning & Neighborhood Development 35 Cabarrus Ave W • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov



H-09-23 406 Union St S

PIN: 5630-14-7115






Source: City of Concord Planning Department

#### Disclaimer

These maps and products are designed for general reference only and data contained herein is subject to change. The City Of Concord, it's employees or agents make no warranty of merchantability or fitness for any purpose, expressed or implied, and assume no legal responsibility for the information contained therein. Data used is from multiple sources with various scales and accuracy. Additional research such as field surveys may be necessary to determine actual conditions.













Agenda Memorandum Historic Preservation Commission

DATE
<u>SUBJECT</u>
Certificate of Appropriateness Request:
Applicant:
Location of subject property:
PIN:
Staff Report prepared by:

June 14, 2023

H-10-23 Melody Sloan 40 Marsh Ave. NW 5620-79-0542 Autumn C. James, Planning & Development Manager

# **BACKGROUND**

- The subject property, 40 Marsh Ave NW, is designated as a "Contributing" structure in the North Union Street Historic District (Exhibit A).
- "One-and-a-half story, frame, double-pile house with high hip roof and engaged, full-façade porch. Roof is pierced by broad, hip-roofed dormers with three windows apiece of front and both sides of the house. Porch has Tuscan columns and balustrade. Broad, seven-bay façade with tall 1/1 sash windows (Exhibit A)

# **DISCUSSION**

On April 15, 2023, Melody Sloan applied for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 for the continuance an existing wooden fence in the rear yard, including the addition of two (2) wooden gates, along with removal and replacement of two trees (Exhibit B).

The proposed wooden fence would enclose the rear yard and will measure approximately 185 ft. on two sides to tie into the existing fence line. The fence material and style will match the existing fence. One (1) wooden gate will be placed at the rear driveway and one (1) will be placed at the side yard.

The applicant has requested to remove two (2) pecan trees from the property. The removed trees, both located on the left side of the rear yard, will be replaced with Japanese Maple trees.

Tree #1 (Pecan / Carya illinoensis) was assessed by City Arborist, Bill Leake, on May 5, 2023, and was assigned a Risk Rating of 4. As noted, "This tree is in fair condition. It shows an overall lack of vitality, possibly due to fill soil added around the based of the trunk to create a planting bed." The assessment also noted that if removed, a similar sized replacement tree species would be appropriate in the same general location, or an alternate location. DBH 33" Height 80' Spread 40'.

Tree #2 (Pecan / Carya illinoensis) was assessed by City Arborist, Bill Leake, on May 5, 2023, and was assigned a Risk Rating of 4. As noted, "This tree is in good overall condition with only one area of decay in one scaffold branch that should be monitored." The assessment also noted that if removed, a similar sized replacement tree species would be appropriate in the same general location, or an alternate location. DBH 38" Height 70' Spread 40'.

# **ATTACHMENTS**

Exhibit A: National Register of Historic Places Inventory Exhibit B: Application for Certificate of Appropriateness Exhibit C: Subject Property Map

Historic Preservation Commission Case # H-10-23 Exhibit D: Applicant Submitted Photographs Exhibit E: Tree Assessments

# HISTORIC HANDBOOK DESIGN RECOMMENDATIONS

Approval Requirement Needs Table: Fencing and Gates

All types require Commission Hearing and Approval.

# Chapter 5 – Section 9: Fences and Walls

- Fences should be compatible with most structures in the districts.
- The style of fence or wall should respond to the historic nature of the property.
- All wooden fences should be "stick-built" on site.
- Painting or staining is recommended, but not required, for rear yard fences unless they are visible from the street.
- *Rear yard fences are defined as fences, which do not extend forward on the applicant's property beyond the side centerline of the house in plain view.*

# Design Standards: Fences and Walls

- Use materials such as natural stone, brick, wood, powder coated aluminum and iron.
- Materials and style should coordinate with building and neighboring buildings as well as other walls and fences in the area.

# Approval Requirement Needs Table: Trees

Removal of healthy trees or pruning of limbs over six inches in diameter in any location on the property requires Commission Hearing and Approval.

# Chapter 5 – Section 8: Landscaping and Trees

- One of the most visible features of the Districts is the landscaping and the associated tree canopy. Activities which negatively impact any aspect of the landscape should be avoided, such as the removal of healthy trees and mature shrubs.
- Tree health may be decided upon by the acquisition of a Tree Hazard Evaluation Report issued by the City Arborist or a report submitted by a certified arborist.
- Removal of healthy trees over the size of 6 inches in diameter (measured 4 feet above ground) or pruning of healthy tree limbs over 6 inches in diameter requires Historic Preservation Commission review and approval.
- All trees that are removed should be replaced with a tree of similar species in an appropriate location unless no suitable location exists on the subject site.

# Design Standards: Landscaping and Trees

• Trees which are removed shall be replaced by a species which, upon maturity, is similar in scale to the removed specimen. For example, canopy trees shall be replaced with canopy trees, and understory trees with understory trees.

# RECOMMENDATION

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u> <u>Handbook</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
  - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
  - Completed project will be photographed to update the historic properties survey.

NPS Form 10-900-a (3-82)

# United States Department of the Interior National Park Service

# National Register of Historic Places Inventory—Nomination Form

For NPS use only received date entered

OMB No. 1024-0018

Expires 10-31-87

Continuation sheet	Item number	Page
Inventory List - North Union Street	#7	<u> </u>
Historic District, Concord		

64. John M. Oglesby House
28 Marsh Avenue, N.W.
1928 (AWB)
C

Handsome, two-story brick Colonial Revival style residence designed by Charlotte architect Louis H. Asbury. House has symmetrical, five-bay facade and side gable roof pierced by three gable-roofed dormers. One-story, three-bay porch has Tuscan columns with ornamental iron in sheaf-of-wheat pattern between columns and is topped with balustrade whose disgonal latticework creates lozenge-shaped patterns. Dormers have molded pilasters and keystone-type ornaments. Dormers and central second floor windows have intersecting tracery sash. Oglesby was a practicing attorney in Concord.


House 40 Marsh Avenue, N.W. 1921 (SM) C

65.

One-and-a-half-story, frame, double-pile house with high hip roof and engaged, full-facade porch. Roof is pierced by broad, hip-roofed dormers with three windows apiece on front and both sides of house. Porch has Tuscan columns and balustrade. Broad, seven-bay facade with tall 1/1 sash windows.

66. House 46 Marsh Avenue, N.W. ca. 1925 C

Two-story, frame Colonial Revival residence with gambrel roof and full facade shed dormer. Symmetrical, five-bay facade; central entrance has projecting, gable-roofed portico with Tuscan columns. Shed-roofed porches on both sides of house; exterior end chimney on west (left) side. Shuttered windows have 9/l sash.



AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

# **APPLICANT INFORMATION**


# Name: Melody Sloan


Address: 40 Marsh Ave

City: Concord State: NC Zip Code: 28025 Telephone:

# **OWNER INFORMATION**

Name: Same Address: Zip Code: Telephone: State: City:





13

Planning & Neighborhood Development 66 Union St S • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 Fax (704) 786-1212 www.concordnc.gov

A CONTRACTOR



Application for Certificate of Appropriateness

# **General Requirements**

The Unified Development Ordinance imposes the following rules, regulations and requirements on requests for Certificates of Appropriateness. The applicant must, with reference to the attached plans, demonstrate how the proposed use satisfies these requirements:

1. Project or Type of Work to be Done: <u>rear yard fence</u> , remove + replace 2 trees pecan -> japanese maple
2. Detailed specifications of the project (type of siding, windows, doors, height/style of fence, color, etc.): <u>Continuation of existing wooden fence to enclose rear yord.</u> Addition
Approx 185 ft. on 2 sides to the into existing force line. Fence material + style 100% match of existing. Will include I wooden gate at
rear driveway & one wooden gate at side yard. Photo of Oxisting fence attached. Photo of trees attached.

- **Required Attachments/Submittals** Typed metes and bounds description of subject property. A property deed is sufficient, provided the deed
  - describes only the subject property.
  - Cabarrus County Land Records printout of names and addresses of all immediately adjacent property owners. including any directly across a street.
  - Scaled site plan, if additions or accessory structures are proposed, on letter, legal or ledger paper. Larger sized eopies will be accepted if 16 folded eopies are submitted for distribution.
  - A photograph of the front of the house. 4-
  - Photographs of site, project, or existing structures from a "before" perspective
  - Drawings, sketches, renderings, elevations, or photographs necessary to present an illustration of the project from an "after" perspective.
  - Samples of windows, doors, brick, siding, etc. must be submitted with application.
  - Detailed list of materials that will be used to complete the project. 8

# Certification

(1) I hereby acknowledge and say that the information contained herein and herewith is true and that this application shall not be scheduled for official consideration until all of the required contents are submitted in proper form to the City of Concord Development Services Department. (2) I understand that City staff and/or members of the Historic Preservation Commission may make routine visits to the site to insure that work being done is the same as the work that was approved. (3) I understand that photographs of the completed project will be made to update the City's historic districts inventory database.


Date

<u>Autody Hoan</u> Signature of Owner/Agent

Planning & Neighborhood Development 66 Union St S · P. O. Box 308 · Concord, NC 28025 Phone (704) 920-5152 Fax (704) 786-1212 www.concordnc.gov



H-10-23 40 Marsh Ave NW PIN: 5620-79-0542





Source: City of Concord Planning Department

#### Disclaimer

These maps and products are designed for general reference only and data contained herein is subject to change. The City Of Concord, it's employees or agents make no warranty of merchantability or fitness for any purpose, expressed or implied, and assume no legal responsibility for the information contained therein. Data used is from multiple sources with various scales and accuracy. Additional research such as field surveys may be necessary to determine actual conditions.

Exhibit C


56207905420000

CORD NC 28025

SLOAN MELODY M

40 MARSH AVE CONCORD NC 28025 12-022 -0050 00

	0071	0110	Mand
э :е	Deed Book	Deed Page	Link
		255220	
		255220	
		1990	
		203850	
		49380	
	LT		
	1		






Exhibit D







RISK RATING:

Potential

1

certificate of appropriateness.

Failure + Size + Target = Risk

of part Rating

4

Rating

2

If approved for removal, the replacement tree

species and location shall be listed on the

Site/Address: 40 Marsh Ave NW

Map/Location: Left side of rear yard

Owner: public: \_\_\_\_\_ private: X\_\_\_\_ unknown: \_\_\_\_\_ other: \_\_\_\_\_

Date: 05/05/23 Inspector: Bill Leake

Date of last inspection:

# TREE CHARACTERISTICS \_\_\_\_\_

Tree #1 Pecan (Carya illinoensis)

DBH: 33" # of trunks: 1 Height: 80' Spread: 40'

Form:  $\boxtimes$  generally symmetric  $\square$  minor asymmetry  $\square$  major asymmetry  $\square$  stump sprout  $\square$  stag-headed

**Crown class**: □ dominant ⊠ co-dominant □ intermediate □ suppressed

**Live crown ratio**: 95% **Age class**: □ young □ semi-mature ⊠ mature □ over-mature/senescent

 Pruning history:
 □ crown cleaned
 □ excessively thinned
 □ topped
 ⊠ crown raised
 □ pollarded
 □ crown reduced
 □ flush cuts

 □ cabled/braced
 □ none
 □ multiple pruning events
 Approx. dates:

Special Value: 🗆 specimen 🛛 heritage/historic 🗆 wildlife 🗆 unusual 🗆 street tree 🗆 screen 🗆 shade 🗆 indigenous 🖾 protected by gov. agency

# TREE HEALTH \_\_\_\_\_\_

Foliage color. 🗆 normal	$oxtimes$ chlorotic $\Box$ necrotic	Epicormics; 🗆		Growth obstructions:
Foliage density:	□normal □sparse	Leaf size: 🗆 r	ıormal ⊠ small	🗆 stakes 🗆 wire/ties 🗆 signs 🗆 cables
Annual shoot growth:	$\Box$ excellent $\boxtimes$ average	e 🗆 poor 🗆 none	Twig Dieback: 🛛	$\Box$ curb/pavement $\Box$ guards
Woundwood :	$\Box$ excellent $\boxtimes$ average $\Box$ fair $\Box$ poor			
Vigor class:	□ excellent □average	e⊠ fair □ poor		

Major pests/diseases:

# SITE CONDITIONS

# TARGET\_

 Use Under Tree: ⊠ building □ parking □ traffic □ pedestrian □ recreation ⊠ landscape ⊠ hardscape □ small features □ utility lines

 Can target be moved? NO
 Can use be restricted? NO

 Occupancy: □ occasional use ⊠ intermittent use □ frequent use □ constant use
 Exhibit E

# TREE DEFECTS

ROOT DEFECTS:
Suspect root rot: NO Mushroom/conk/bracket present: NO ID:
Exposed roots:  Severe  Moderate  Now  Undermined:  Severe  Moderate  Now  Notermined:  Severe  Notermined:  Severe  Notermined:  Severe  Notermined:  Severe  Severe
Root pruned: distance from trunk Root area affected: Buttress wounded: 🗆 When:
Restricted root area: $\Box$ severe $\Box$ moderate $\boxtimes$ low Potential for root failure: $\Box$ severe $\Box$ moderate $\boxtimes$ low
LEAN: 2 deg. from vertical 🛛 natural 🖓 unnatural 🖓 self-corrected 🖓 Soil heaving:
Decay in plane of lean:  Roots broken:  Soil cracking:
Compounding factors: Lean severity:   Severe  moderate  low

*Concern Areas:* Indicate presence of individual structural issues and rate their severity (**S** = severe, **M** = moderate, **L** = low)

DEFECT	ROOT CROWN	TRUNK	SCAFFOLDS	BRANCHES
Poor taper				
Bow, sweep				
Codominants/forks				
Multiple attachments				
Included bark				
Excessive end weight				
Cracks/splits				
Hangers				
Girdling				
Wounds/seam				
Decay		L		
Cavity		L		
Conks/mushrooms/bracket				
Bleeding/sap flow				
Loose/cracked bark				
Nesting hole/bee hive				
Deadwood/stubs			L	L
Borers/termites/ants				
Cankers/galls/burls				
Previous failure				
RISK RATING				

Tree part most likely to fail in the next six months: Dead Branches

Failure potential: <b>1</b> - low: <b>2</b> - medium; <b>3</b> - high; <b>4</b> - severe	Size of part: <b>0</b> -0"-3" <b>1</b> -3"-6"	<b>2</b> -6"-18" <b>3</b> -18"-3	<b>4</b> ->30"
Target rating: 0 - no target 1 - occasional use 2 - intermittent use 3 - frequent use 4 - o	constant use		

# **Maintenance Recommendations**

Failure Potential + Size of Part + Target Rating = Hazard Rating	$\Box$ none $\Box$ remove defective part $\boxtimes$ reduce end weight $\boxtimes$ crown clean		
	$\Box$ thin $\Box$ raise canopy $\Box$ crown reduce $\Box$ restructure $\Box$ cable/brace		
	Inspect further $\boxtimes$ root crown $\square$ decay $\square$ aerial $\square$ monitor		
$\square$ Remove tree $\boxtimes$ If removed, a similar sized replacement tree species would be appropriate in same general location			
If removed, alternate tree replacement locations are available			
Effect on adjacent trees: 🛛 none 🗆 evaluate			
Notification: $\boxtimes$ owner $\square$ manager $\boxtimes$ governing agency	Date: 5//5/23		

# COMMENTS \_\_\_\_\_

This tree is in fair condition. It shows an overall lack of vitality, possibly due to fill soil added around the base of the trunk to create a planting bed.





Site/Address: 40 Marsh Ave NW

Map/Location: Left side of rear yard

Owner: public: \_\_\_\_\_ private: X\_\_\_\_ unknown: \_\_\_\_\_ other: \_\_\_\_\_

Date: 05/05/23 Inspector: Bill Leake

Date of last inspection:

# TREE CHARACTERISTICS \_\_\_\_\_

Tree #2 Pecan (Carya illinoensis)

DBH: 38" # of trunks: 1 Height: 70' Spread: 40'

Form: □ generally symmetric □ minor asymmetry □ major asymmetry □ stump sprout □ stag-headed

**Crown class**: □ dominant ⊠ co-dominant □ intermediate □ suppressed

Live crown ratio: 99 % Age class: □ young □ semi-mature ⊠ mature □ over-mature/senescent

 Pruning history:
 □
 crown cleaned
 □
 excessively thinned
 □
 topped
 □
 pollarded
 □
 crown reduced
 □
 flush cuts

 □
 cabled/braced
 □
 none
 □
 multiple pruning events
 Approx. dates:

Special Value: 🗆 specimen 🛛 heritage/historic 🗆 wildlife 🗆 unusual 🗆 street tree 🗆 screen 🗆 shade 🗆 indigenous 🖾 protected by gov. agency

# TREE HEALTH \_\_\_\_\_

Foliage color. 🛛 normal	□ chlorotic	necrotic	Epicormics; 🗆		Growth obstructions:		
Foliage density:	⊠normal □sparse <b>Leaf size</b> : ⊠ normal □ small			🗆 stakes 🗆 wire/ties 🗆 signs 🗆 cables			
Annual shoot growth:	$\Box$ excellent	$\boxtimes$ average	$\Box$ poor $\Box$ none	Twig Dieback: 🗆	curb/pavement		
Woundwood :	$\Box$ excellent $\boxtimes$ average $\Box$ fair $\Box$ poor						
Vigor class:	□ excellent ⊠average □ fair □ poor						

Major pests/diseases:

# SITE CONDITIONS \_\_\_\_\_

 Site Character:
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x
 x

# TARGET\_

 Use Under Tree:
 building
 parking
 traffic
 pedestrian
 recreation
 Iandscape
 hardscape
 small features
 utility lines

 Can target be moved? NO
 Can use be restricted? NO

 Occupancy:
 occasional use
 intermittent use
 frequent use
 constant use

#### **RISK RATING:**

1	1	2	4					
Failure	+ Size +	Target	= Risk					
Potential	of part	Rating	Rating					
If any word for normal the nonlacoment								

If approved for removal, the replacement tree species and location shall be listed on the certificate of appropriateness.

# TREE DEFECTS

\_ \_ \_ \_ \_ \_ \_

ROOT DEFECTS:
Suspect root rot: NO Mushroom/conk/bracket present: NO ID:
Exposed roots: $\Box$ severe $\Box$ moderate $\Box$ lowUndermined: $\Box$ severe $\Box$ moderate $\Box$ low
Root pruned: distance from trunk Root area affected: Buttress wounded: 🗆 When:
Restricted root area: $\Box$ severe $\Box$ moderate $\boxtimes$ low Potential for root failure: $\Box$ severe $\Box$ moderate $\boxtimes$ low
LEAN: 5 deg. from vertical 🛛 natural 🖓 unnatural 🖓 self-corrected 🖓 Soil heaving:
Decay in plane of lean: $oxtimes$ Roots broken: $\Box$ Soil cracking: $\Box$
Compounding factors: Lean severity:   severe  moderate  low

*Concern Areas:* Indicate presence of individual structural issues and rate their severity (**S** = severe, **M** = moderate, **L** = low)

DEFECT	ROOT CROWN	TRUNK	SCAFFOLDS	BRANCHES
Poor taper				
Bow, sweep				
Codominants/forks				
Multiple attachments				
Included bark				
Excessive end weight				
Cracks/splits				
Hangers				
Girdling				
Wounds/seam				
Decay			L	
Cavity			L	
Conks/mushrooms/bracket				
Bleeding/sap flow				
Loose/cracked bark				
Nesting hole/bee hive				
Deadwood/stubs				L
Borers/termites/ants				
Cankers/galls/burls				
Previous failure				
RISK RATING				

Tree part most likely to fail in the next six months: Dead Branches

Failure potential: <b>1</b> - low: <b>2</b> - medium; <b>3</b> - high; <b>4</b> - severe	Size of part: <b>0</b> -0" - 3" <b>1</b> - 3"-6"	<b>2</b> -6"-18" <b>3</b> -18"-30"	<b>4</b> ->30"
Target rating: 0 - no target 1 - occasional use 2 - intermittent use 3 - frequent use 4 -	constant use		

### **Maintenance Recommendations**

Failure Potential + Size of Part + Target Rating = Hazard Rating	$\Box$ none $\Box$ remove defective part $\boxtimes$ reduce end weight $\boxtimes$ crown clean				
<u>    1    1    2    4    </u>	$\Box$ thin $\Box$ raise canopy $\Box$ crown reduce $\Box$ restructure $\Box$ cable/brace				
	Inspect further $\Box$ root crown $\Box$ decay $\Box$ aerial $\Box$ monitor				
□ Remove tree ⊠ If removed, a similar sized replacement tree species would be appropriate in same general location					
☑ If removed, alternate tree replacement locations are available					
Effect on adjacent trees: $\boxtimes$ none $\square$ evaluate					
Notification: $\boxtimes$ owner $\square$ manager $\boxtimes$ governing agency	Date: 5/5/23				
COMMENTS					

This tree is in good overall condition with only one area of decay in one scaffold branch that should be monitored.

Bill Leake





DATE	
<u>SUBJECT</u>	
Certificate of Appropriateness Re	equest:
Applicant:	
Location of subject property:	
<u>PIN:</u>	
Staff Report prepared by:	

June 14, 2023

H-11-23 Dimitrios and Holli Arethas 312 Union St S. 5630-05-9180 Autumn C. James, Planning & Development Manager

### **BACKGROUND**

- The subject property, 312 Union St. S, is designated as a "Contributing" structure in the South Union Street Historic District (Exhibit A).
- "Two-story, brick, Colonial Revival style residence with hip roof. Three-bay division on first and second stories with centrally placed hip-roofed dormer over second story. Full-façade porch is supported by heavy brick piers at the ends with thin Doric columns on brick piers flanking the entrance bay. On the north side of the house is a flat-roofed wing containing a sunroom. The eaves of the main block, sunroom, and porch are trimmed with decorative boards (Exhibit A).

### **DISCUSSION**

On May 17, 2023, Dimitrios and Holli Arethas, applied for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 for the removal of a pecan tree located on the right side of the home in the rear side yard. The applicants are requesting this tree removal as it currently overhangs a powerline running from the street. Additionally, the location is causing squirrel issues leading to exterior damage of the house. The applicants are willing to plant replacement(s).

A pecan tree (Carya illinoensis) was assessed by City Arborist, Bill Leake, on April 18, 2023, and was assigned a Risk Rating of 3. As noted, "This tree has three over-extended scaffold limbs. It also has a small area of injury at the base of the trunk." The assessment also noted that if removed, a similar sized replacement tree species would be appropriate at an alternate location. DBH 20" Height 30' Spread 30'.

### **ATTACHMENTS**

Exhibit A: National Register of Historic Places Inventory Exhibit B: Application for Certificate of Appropriateness Exhibit C: Subject Property Map Exhibit D: Tree Assessments

### HISTORIC HANDBOOK DESIGN RECOMMENDATIONS

### Approval Requirement Needs Table: Trees

Removal of healthy trees or pruning of limbs over six inches in diameter in any location on the property requires Commission Hearing and Approval.

### Chapter 5 – Section 8: Landscaping and Trees

• One of the most visible features of the Districts is the landscaping and the associated tree canopy. Activities which negatively impact any aspect of the landscape should be avoided, such as the removal of healthy trees and mature shrubs.

Historic Preservation Commission Case # H-11-23

- Tree health may be decided upon by the acquisition of a Tree Hazard Evaluation Report issued by the City Arborist or a report submitted by a certified arborist.
- Removal of healthy trees over the size of 6 inches in diameter (measured 4 feet above ground) or pruning of healthy tree limbs over 6 inches in diameter requires Historic Preservation Commission review and approval.
- All trees that are removed should be replaced with a tree of similar species in an appropriate location unless no suitable location exists on the subject site.

### Design Standards: Landscaping and Trees

1. Trees which are removed shall be replaced by a species which, upon maturity, is similar in scale to the removed specimen. For example, canopy trees shall be replaced with canopy trees, and understory trees with understory trees.

#### **RECOMMENDATION**

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u> <u>Handbook</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
  - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
  - Completed project will be photographed to update the historic properties survey.

# **United States Department of the Interior** National Park Service

# National Register of Historic Places Inventory—Nomination Form

OMB No. 1024-0018 Expires 10-31-87

For NPS use only received date entered

Continuation sheet	Item number	Page
Inventory List - South Union Street	#7	14
Historic District, Concord		

20. R. C. Litaker House 324 S. Union St. 1921-1927 (SM) C

Two-story, frame, late Colonial Revival residence with deep setback. The main block has a side gable roof pierced by three gable-roofed dormers on the front elevation. The entrance occupies the north (right) facade bay and is sheltered by a gable-roofed portico upheld by Doric columns. The other facade openings at 9/1 sash windows. Along the south side of the house is a one-story wing comprising a sunroom and a porte-cochere.

21.

House 312 S. Union St. 1921-1927 (SM) C

Two-story, brick, Colonial Revival style residence with hip roof. Three-bay division on first and second stories with centrally placed hip-roofed dormer over second story. Full-facade porch is supported by heavy brick piers at the ends with thin Doric columns on brick piers flanking the entrance bay. On the north side of the house is a flat-roofed wing containing a sunroom. The eaves of the main block, sunroom, and porch are trimmed with decorative boards.

22.

House 306 S. Union St. ca. 1945 F

4

Two-story, frame, Colonial style house with side gable roof, symmetrical, three-bay facade, gable-roofed portico upheld by Tuscan columns, and gable-roofed sunroom wing on south elevation.

23. House 298 S. Union St. ca. 1905 C

Two-story, frame house with simple Queen Anne and Colonial Revival elements. Main block has high hip roof; south (left) bay of facade

OLI High Performance Living 

Application for Certificate of Appropriateness

AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

APPLICANT INFORMATION Name: <u>Dimitrios</u> and Holli Arethas Address: <u>312 Union Street South</u> City: <u>Gncord</u>
OWNER INFORMATION Name: Dimitrios and Holli Arethas Address: 312 Union Street South City: Concord State: NC Zip Code: 28025 Telephone: 704-322-7208
SUBJECT PROPERTY         Street Address: 312 Union St. South         P.I.N. # 5630059180000         Area (acres or square feet): .46 acres         Current Zoning: Residential         Land Use: Single Family Residential
Staff Use Only:         Application Received by:

Creapenning & Neighbyhood Development 35 Cabarrus Ave W • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov

Exhibit B

P High Performance Living SPERDICC

#### **General Requirements**

The Unified Development Ordinance imposes the following rules, regulations and requirements on requests for Certificates of Appropriateness. The applicant must, with reference to the attached plans, demonstrate how the proposed use satisfies these requirements:

Project or Type of Work to be Done: Tree Removal 1.

2. Detailed specifications of the project (type of siding, windows, doors, height/style of fence, color, etc.): on the right side of home in Removal of Pecan Tree located rear side yard by professional tree service. Tree currently power line running from street. Additionally, overhangs squirrel issues leading to its location is causing replacements) Willing damage. extensor home

#### Required Attachments/Submittals

- Scaled site plan, if additions or accessory structures are proposed, on letter, legal or ledger paper. Larger sized 1. copies will be accepted. Digital copies are preferred.
- Detailed written description of the project.
- 2. Photographs of site, project, or existing structures from a "before" perspective.
- Drawings, sketches, renderings, elevations, or photographs necessary to present an illustration of the project 3. 4.
- from an "after" perspective if applicable. Samples of windows, doors, brick, siding, etc. must be submitted with application.
- 5. Detailed list of materials that will be used to complete the project. 6.

(1) I hereby acknowledge and say that the information contained herein and herewith is true and that this application shall not be scheduled for official consideration until all of the required contents are submitted in proper form to the City of Concord Development Services Department. (2) I understand that City staff and/or members of the Historic Preservation Commission may make routine visits to the site to insure that work being done is the same as the work that was approved. (3) I understand that photographs of the completed project will be made to update the City's historic districts inventory database.

5117/2023

Date

Holli arthas


Signature of Owner/Agent

# Created With Tiny Scanner

Planning & Neighborhood Development 35 Cabarrus Ave W 
Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordne.gov



H-11-23 312 Union St S PIN: 5630-05-9180





Source: City of Concord Planning Department

#### Disclaimer

These maps and products are designed for general reference only and data contained herein is subject to change. The City Of Concord, it's employees or agents make no warranty of merchantability or fitness for any purpose, expressed or implied, and assume no legal responsibility for the information contained therein. Data used is from multiple sources with various scales and accuracy. Additional research such as field surveys may be necessary to determine actual conditions.

Exhibit C



Site/Address: 312 Union St S

Map/Location: North side of house

Owner: public: \_\_\_\_\_ private: \_\_X\_\_\_ unknown: \_\_\_\_\_ other: \_\_\_\_

Date: 04/18/23 Inspector: Bill Leake

Date of last inspection: 03/2021

### TREE CHARACTERISTICS \_\_\_\_\_

Tree #: 1 Species: Pecan (Carya illinoensis)

DBH: 20" # of trunks: 1 Height: 30' Spread: 30'

Form:  $\Box$  generally symmetric  $\Box$  minor asymmetry  $\boxtimes$  major asymmetry  $\Box$  stump sprout  $\Box$  stag-headed

**Crown class**: □ dominant ⊠ co-dominant □ intermediate □ suppressed

**Live crown ratio**: 908% **Age class**: □ young ⊠ semi-mature □ mature □ over-mature/senescent

**Pruning history**:
  $\Box$  crown cleaned
  $\Box$  excessively thinned
  $\Box$  topped
  $\Box$  crown raised
  $\Box$  pollarded
  $\Box$  crown reduced
  $\Box$  flush cuts

  $\Box$  cabled/braced
  $\Box$  none
  $\Box$  multiple pruning events
 Approx. dates:

Special Value: 🗆 specimen 🛛 heritage/historic 🗆 wildlife 🗆 unusual 🗆 street tree 🗆 screen 🗆 shade 🗆 indigenous 🖾 protected by gov. agency

## TREE HEALTH \_\_\_\_\_\_

Foliage color. 🛛 normal	$\Box$ chlorotic $\Box$	necrotic	Epicormics; 🗆		Growth obstructions:
Foliage density:	⊠normal	□sparse	Leaf size: 🖂 r	normal $\Box$ small	$\Box$ stakes $\Box$ wire/ties $\Box$ signs $\Box$ cables
Annual shoot growth:	$\Box$ excellent $\square$	🛛 average 🛛	🗆 poor 🗆 none	Twig Dieback: 🛛	$\Box$ curb/pavement $\Box$ guards
Woundwood :	□ excellent ▷	⊠average □	🛛 fair 🗆 poor		
Vigor class:	□ excellent D	🛛 average 🗆	🛛 fair 🗆 poor		

Major pests/diseases:

# SITE CONDITIONS

# TARGET\_

 Use Under Tree: □ building □ parking □ traffic □ pedestrian □ recreation □ landscape □ hardscape □ small features □ utility lines

 Can target be moved? NO
 Can use be restricted? NO

 Occupancy: □ occasional use □ intermittent use □ frequent use □ constant use
 Exhibit D

#### **RISK RATING:**

1	0	2	3
Failure	+ Size +	Target	= Risk
Potential	of part	Rating	Rating

If approved for removal, the replacement tree species and location shall be listed on the certificate of appropriateness.

# TREE DEFECTS

ROOT DEFECTS:
Suspect root rot: NO Mushroom/conk/bracket present: NO ID:
Exposed roots: $\Box$ severe $\Box$ moderate $\boxtimes$ lowUndermined: $\Box$ severe $\Box$ moderate $\boxtimes$ low
Root pruned: distance from trunk Root area affected: 5% Buttress wounded: 🛛 When: unknown
Restricted root area: □ severe ⊠ moderate □ low Potential for root failure: □ severe □ moderate ⊠ low
LEAN: 3 deg. from vertical 🛛 natural 🖓 unnatural 🖓 self-corrected 🖓 Soil heaving:
Decay in plane of lean:  Roots broken:  Soil cracking:
Compounding factors: Lean severity: 🗆 severe 🗆 moderate 🖂 low

*Concern Areas:* Indicate presence of individual structural issues and rate their severity (**S** = severe, **M** = moderate, **L** = low)

DEFECT	ROOT CROWN	TRUNK	SCAFFOLDS	BRANCHES
Poor taper				
Bow, sweep				М
Codominants/forks				
Multiple attachments				
Included bark				
Excessive end weight				
Cracks/splits				
Hangers				
Girdling				
Wounds/seam	L			
Decay				
Cavity				
Conks/mushrooms/bracket				
Bleeding/sap flow				
Loose/cracked bark				
Nesting hole/bee hive				
Deadwood/stubs				
Borers/termites/ants				
Cankers/galls/burls				
Previous failure			L	
RISK RATING				

Tree part most likely to fail in the next six months: Branches

Failure potential: 1 - low: 2 - medium; 3 - high; 4 - severe	Size of part: <b>0</b> -0"-3" <b>1</b> -3"-6"	<b>2</b> -6"-18"	<b>3</b> -18"-30"	<b>4</b> ->30"
Target rating: 0 - no target 1 - occasional use 2 - intermittent use 3 - frequent use 4	<b>4</b> - constant use			

#### **Maintenance Recommendations**

Failure Potential + Size of Part + Target Rating = Hazard Rating	$\Box$ none $\Box$ remove defective part $\boxtimes$ reduce end weight $\Box$ crown clean				
<u>    1    0    2    3   </u>	$\Box$ thin $\Box$ raise canopy $\Box$ crown reduce $\Box$ restructure $\Box$ cable/brace				
	Inspect further $\Box$ root crown $\Box$ decay $\Box$ aerial $\Box$ monitor				
$\Box$ Remove tree $\Box$ If replaced, a similar sized tree species would be appropriate in same general location					
If replaced, alternate tree replacement locations are available					
Effect on adjacent trees: $ extsf{M}$ none $ extsf{D}$ evaluate					
Notification: ⊠ owner □ manager ⊠ governing agency Date: 04/18/23					
COMMENTS					

This tree has three over-extended scaffold limbs. It also has a small area of injury at the base of the trunk.

Bill Leake





# DATE:

**SUBJECT:** 

Certificate of Appropriateness Request: Applicants: Location of Subject Property: <u>PIN #:</u> Staff Report Prepared by: June 14, 2023

H-12-23 Stephen Rohrer 113 Union Street N 5620-79-8008 Autumn C. James, Planning & Development Manager

# BACKGROUND

- The subject property at 113 Union Street N is designated as a "Pivotal" structure in the North Union Street Historic District (ca. 1890) (Exhibit A).
- "Highly significant, exceptionally well-preserved, two-story frame Queen Anne style residence, the best example of the style in Concord. House is enhanced by its prominent setting on a large, corner lot with a fine late nineteenth century ornamental iron fence. A particularly notable feature of the house is the variety of sawn and molded woodwork applied to its surface. Each of the house's several gables is covered with scalloped shingles and framed with decorative sawn and molded boards; scalloped shingles also cover the flared base of the house's second story. Above the second floor is a cut-out frieze with a repeating tree shape; a frieze with a sheaf-of-wheat pattern run along parts of the house's sides. The facade has a gable-front by projecting from the main roofline, and · a central balcony with richly ornamented woodwork sheltered by a projecting hip roof. The southern (left) portion of the well-detailed wrap-around porch was enclosed with latticed window sash typical of the bungalow style during the 1920s" (Exhibit A).

# **DISCUSSION**

- On May 10, 2023, Stephen Rohrer applied for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 to stain the rear fence along 19 Franklin Ave, with approval by neighboring resident, based on "the change in conditions or circumstances which would justify the reconsideration of an action must be a change in the particular circumstances or condition which induced the prior decision." (Exhibit B).
- On April 14, 2021, the Historic Preservation Commission approved the rear yard fence to be stained on the Applicants' side and painted white on the side facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N as well as the height of the fence to be 4.0' along Franklin Avenue NW as shown in the Recorded Order filed April 27, 2021, with the Cabarrus County Register of Deeds.
- In February 2022, rear yard fence construction commenced including along Franklin Avenue NW.
- In September 2022, rear year fence staining commenced including on the side facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N.
- In December 2022, the Rohrer's returned to the Historic Preservation Commission with an "ex post facto" Certificate of Appropriateness requesting after-the-fact approval to stain the side of the rear yard fence facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N and to increase the height of the rear yard fence running adjacent to Franklin Ave from 4.0' to 6.0'. Based on the standards of the Handbook, and the City of Concord Code of Ordinances,

Historic Preservation Commission Case # H-12-23 including the standards listed above, the Commission concluded that there was sufficient evidence presented to reopen the prior approval and approve the "ex post facto" request for after-the-fact approval to increase the height of the fence running adjacent to Franklin Ave NW from 4.0' to 6.0' is appropriate as the wooden fence is visible from the street and is located in the rear yard and therefore may be higher than 4.0', and is in compliance with the Historic Handbook. However, there was insufficient evidence presented to reopen the prior approval as to the fence color and the Commission did not vote to amend the fence color that was initially approved in Case H-04-21 on April 14, 2021.

### **ATTACHMENTS**

Exhibit A: National Register of Historic Places Inventory
Exhibit B: "Ex Post Facto" Certificate of Appropriateness Application
Exhibit C: Subject Property Map
Exhibit D: Applicants Submitted Photos
Exhibit E: Recorded Order Dated April 27, 2021
Exhibit F: Recorded Order Dated February 2, 2023
Exhibit G: Historic Preservation Commission Meeting Minutes from December 14, 2022

# HISTORIC HANDBOOK DESIGN RECOMMENDATIONS

**Approval Requirement Needs Table: Fencing and Gates** *All types require Commission Hearing and Approval.* 

# Chapter 5 – Section 9: Fences and Walls

- Fences should be compatible with most structures in the districts.
- The style of fence or wall should respond to the historic nature of the property.
- All wooden fences should be "stick-built" on site.
- Wooden fences visible from the street and/or wooden fences in front yards and side yards of corner lots are required to be painted or stained white or a color matching the body or trim of the structure, including shutters, foundation color, etc.
- Painting or staining is recommended, but not required, for rear yard fences unless they are visible from the street.
- All proposed fences and walls should not negatively affect existing trees and mature landscaping.
- Privacy fences are defined as fences with no spacing between pickets or fences of the shadowbox design. Privacy fences may be allowed at the discretion of the Commission in the following circumstances:
  - *Privacy fences are most appropriate in rear yards.* 
    - Privacy fences may be allowed where the applicant's rear yard is directly adjacent to property that is either not in a historic district, or is within a historic district but is non-contributing or intrusive in that district. The applicant shall show to the satisfaction of the Commission:
      - that the adjacent property is unsightly in comparison to other properties surrounding the applicant's property,
      - *that the adjacent property or nearby property raises reasonable security concerns for the applicant, or*
      - that the adjacent property could reasonably be determined to negatively impact the property value of the applicant's property.
- Privacy fences encompassing an area of no more than 250 square feet may be allowed at the discretion of the Commission when adjacent to the applicant's house, garage, or other outbuilding

Historic Preservation Commission Case # H-12-23 in order to screen from view trash cans, mechanical equipment, cars or other unsightly items, provided such fence does not unreasonably impact any neighbor by blocking windows or the like.

• Privacy fences allowed by the Commission should be landscaped where practical with appropriate shrubbery to soften the appearance of the fence.

# <u>Design Guidelines</u>

- Use materials such as natural stone, brick, wood, powder coated aluminum and iron.
- Materials and style should coordinate with building and neighboring buildings as well as other walls and fences in the area.

# **RECOMMENDATION:**

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u> <u>Handbook and Guidelines</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
  - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
  - Completed project will be photographed to update the historic properties survey.

Expires 10-31-87 (3-82) United States Department of the Interior For NPS use only National Park Service **National Register of Historic Places** received **Inventory**—Nomination Form date entered Page Continuation sheet Item number Inventory List - North Union Street 33 # 7

N. Felix Yorke (1853–1916) founded the Yorke and Wadsworth Mardware Store in the 1880s; the store is still in operation and is probably the oldest business in the city.

John Phifer Allison House 39. 113 North Union Street ca. 1890 P

Historic District, Concord

Highly significant, exceptionally well-preserved, two-story frame Queen Anne style residence, the best example of the style in Concord. House is enhanced by its prominent setting on a large, corner lot with a fine late nineteenth century ornamental iron fence. A particularly notable feature of the house is the variety of sawn and molded woodwork applied to its surface. Each of the house's several gables is covered with scalloped shingles and framed with decorative sawn and molded boards; scalloped shingles also cover the flared base of the house's second story. Above the second floor is a cut-out frieze with a repeating tree shape; a frieze with a sheaf-of-wheat pattern run along parts of the house's sides. The facade has a gable-front by projecting from the main roofline, and a central balcony with richly ornamented woodwork sheltered by a projecting hip roof. The southern (left) portion of the well-detailed wrap-around porch was enclosed with latticed window sash typical of the bungalow style during the 1920s.

John Phifer Allison (b. 1848) was a financier and merchant who erected the Allison Block, on the largest buildings in downtown Concord, between 1897 and 1906. He was an officer of several important Concord businesses. Arthur W. Fisher, a Cannon Mills executive, purchased the house in 1942, and his widow still lives there.

A. Jones Yorke House 123 North Union Street 40. 1908 (01) Ρ

> Highly distinctive Colonial Revival style residence constructed of creamy tan brick, designed by Charlotte architect, Leonard L. Hunter. Gable ends of the main block, the porte-cochere that projects from the south side of the house, and the one-story garage at the rear of the house have stone-trimmed parapets. The windows are segmental-arched all and have well executed radiating brickwork and keystones. Tuscan columns grouped in threes support the porch, which is topped with a balustrade.

NPS Form 10-900-a

# OMB No. 1024-0018

EXHIBIT A



#### **General Requirements**

The Unified Development Ordinance imposes the following rules, regulations and requirements on requests for Certificates of Appropriateness. The applicant must, with reference to the attached plans, demonstrate how the proposed use satisfies these requirements:

1. Project or Type of Work to be Done: staining following HPC standards and Concord UDO

2. Detailed specifications of the project (type of siding, windows, doors, height/style of fence, color, etc.):

Staining of rear fence along 19 Frankline Ave with approval by neighboring resident.

We are submitting this application per the Historic Preservation Commission's legal instructions

provided to us via email on January 17, 2023, based on "the change in conditions or circumstances which

would justify the reconsideration of an action must be a change in the particular circumstances or condition which induced the prior decision" (ref. Deed book 16301 pages 0322-0325 attached).

List of materials: stain Required scaled site plan and photos attached as part of this application

# Required

#### Attachments/Submittals

- Scaled site plan, if additions or accessory structures are proposed, on letter, legal or ledger paper. Larger sized 1. copies will be accepted if 16 folded copies are submitted for distribution.
- 2. A photograph of the front of the house.
- 3. Photographs of site, project, or existing structures from a "before" perspective.
- Drawings, sketches, renderings, elevations, or photographs necessary to present an illustration of the project from an "after" perspective.
- 5. Samples of windows, doors, brick, siding, etc., may be submitted with application.
- Detailed list of materials that will be used to complete the project. 6.

\*\*\*Applications may be submitted electronically.\*\*\*

#### Certification

(1) I hereby acknowledge and say that the information contained herein and herewith is true and that this application shall not be scheduled for official consideration until all of the required contents are submitted in proper form to the City of Concord Development Services Department. (2) I understand that City staff and/or members of the Historic Preservation Commission may make routine visits to the site to insure that work being done is the same as the work that was approved. (3) I understand that photographs of the completed project will be made to update the City's historic districts inventory database.

5/10/2023

Date

Signature of Owner/Agent Stephen Rome

Planning & Neighborhood Development 35 Cabarrus Ave W • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 Fax (704) 920-6962 www.concord.nc.gov



# AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

#### APPLICANT INFORMATION

Name: Stephen Rohr	er		
Address: 113 Union S	St. N		
City: Concord	State: NC	_Zip Code: 28025	Telephone: (252) 267-2035
Email: stephen.rohre	er86@gmail.	com	
OWNER INFORMAT	TION		
Name: Stephen Ro	hrer		
Address: 113 Union	St. N		
City: Concord	_ State: NC	_ Zip Code: <u>28025</u> _	Telephone: (252) 267-2035
Email: stephen.rohr	er86@gmail.	com	
SUBJECT PROPER	ſY		
Street Address: 113	Union St. N		P.I.N. # <u>56207980080000</u>
Area (acres or square f		es_Current Zoning:	RM-1 Land Use: Residential

	Staff Use Only:	
Application Received by:	Date:	, 20
Fee: \$20.00 Received by:	Date:	, 20
	plication fee is nonrefundable.	

Planning & Neighborhood Development 35 Cabarrus Ave W • P. O. Box 308 • Concord, NC 28025 Phone (704) 920-5152 • Fax (704) 920-6962 • www.concordnc.gov

FILED ELECTRONICALLY CABARRUS COUNTY NC M. WAYNE NIXON

 FILED
 Dec 06, 2022

 AT
 11:08:00 AM

 HOOK
 16301

 START PAGE
 0322

 END PAGE
 0325

 INSTRUMENT #
 34009

 EXCISE TAX
 \$1,400.00

#### NORTH CAROLINA GENERAL WARRANTY DEED

Excise Stamps: 1,400.00

Parcel Identifier number: 12-26-21

Return to: Grantee

.

#### NO TITLE OPINION

Prepared by: HOWARD S. IRVIN, Attorney Hartsell & Williams, P.A. Post Office Box 368 Concord, NC 28026-0368

THIS DEED is made and entered into this the 1<sup>st</sup> day of December 2022 by and between

ROBERT W. NIXON and wife DALE P. NIXON 95 Ingleside Drive, SE Concord, NC 28025

Hereinafter GRANTOR

And

KATHERINE DRVE GONZALEZ (Free Trader) 19 Franklin Avenue, NW Concord, NC 28025

Hereinaßer GRANTEE

WITNESSETH, that the Grantor, for a valuable consideration paid by the Grantee, the receipt of which is hereby acknowledged, has and by these presents does grant, bargain, sell and convey unto the Grantee, in fee simple, all that certain lot or parcel of land being more fully described on Legal Description attached hereto, as Exhibit "A".

The property herein conveyed does not include the primary residence of a Grantor.

TO HAVE AND TO HOLD the aforesaid lot or parcel of land and all privileges and appurtenances thereto belonging to the Grantee in fee simple.

And the Grantor covenants with Grantee, that Grantor is seized of the premises in fee simple, has the right to convey the same in fee simple, that title is marketable and free and clear of all encumbrances, and that Grantor will warrant and defend the title against the lawful claims of all persons whomsoever, other than the following exceptions: all easements or right of way, restrictions and covenants, minimum building setbacks, zoning laws and ordinances of record, affecting the property hereby conveyed.

IN WITNESS WHEREOF, the Grantor has duly executed the foregoing as of the day and year shown herein.

#### (SEE SIGNATURES ATTACHED)

Robert W. Nixon (Scal) State @ Stixer (Scal) Dale P. Nixon

North Carolina, Cabarrus County

.

1, Howard S. Irvin, a Notary Public for said County and State certify that the following persons personally appeared before me this day and acknowledged to me that he voluntarily signed the foregoing document for the purposes stated therein and, in the capacity indicated:

Robert W. Nixon and wife Date P. Nixon. Tamara Harle (Unmarried).


WITNESS my hand and notary stamp, this the list day of December 2022.

Horm

Howard S. Irvin Notary Public

My Commission Expires: June 17, 2027

Notary Stamp



#### EXHIBIT "A"

Lying and Being in Ward Number One (1) Township of Cabarrus County, North Carolina on the South side of Franklin Avenue, NW and Being a portion of that property as is shown on a physical survey dated May 15, 1984 by Billy B. Long, R.L.S., and more particularly described as follows: Old Description

BEGINNING at an iron stake on Franklin Avenue at its intersection with an unnamed ten (10) foot alleyway and runs thence with Franklin Avenue North 46-31 East for a distance of 65.0 feet to an iron stake, the corner of McIver, et al.; thence with the line of McIver South 42-30 East for a distance of 149.0 feet to a point in the line of Robert Steel; thence with said line of Robert Steel South 46-31 West for a distance of 65.0 feet to an iron stake in the edge of said ten foot alleyway; thence with said alleyway North 42-30 West for a distance of 149.00 feet to the point of BEGINNING.

The above is conveyed together with and subject to a right of way over the ten (10) footalleyway referenced above.

For informational purposes only, being known as 19 Franklin Avenue, NW, Concord, NC 28025.

For back reference, see Deed Book 573, Page 770, Cabarrus Registry.

An

To whom it may concern,

I am the current owner of 19 Franklin NW, Concord NC 28025, having purchased the home from Robert and Dale Nixon. I request that the current owners of 113 Union St. N, Dana and Stephen Rohrer, do not paint the side of their rear fence the color white. I request that the stain on the fence remain.

Thank you,

amerne Gonzella


9 du not need my side @ 19 Franktin painted white. P also don't work to be put in the middle of this - there you! It

Fence will be stained to match existing wooden stain used on Front Porch columns, Minwax Red Oak 215 wood stain or similar Stain color. Example:



~


.



H-12-23

113 Union St N

PIN: 5620-79-8008






Source: City of Concord Planning Department

#### Disclaimer

These maps and products are designed for general reference only and data contained herein is subject to change. The City Of Concord, it's employees or agents make no warranty of merchantability or fitness for any purpose, expressed or implied, and assume no legal responsibility for the information contained therein. Data used is from multiple sources with various scales and accuracy. Additional research such as field surveys may be necessary to determine actual conditions.

Exhibit C





×.





FILED CABARRUS COUNTY NC WAYNE NIXON REGISTER OF DEEDS				
FILED Apr	27, 2021			
AT (	02:38 pm			
300K	15126			
START PAGE	0123			
END PAGE	0129			
NSTRUMENT #	18388			
EXCISE TAX	\$0.00			

Mail to: City of Concord, Planning Dept., PO Box 308, Concord, NC 28026 PIN#5620-79-8008

# NORTH CAROLINAORDER OF THE CITY OF CONCORDCABARRUS COUNTYHISTORIC PRESERVATION COMMISSION CASE # H-4-21

This matter came before the Historic Preservation Commission (hereinafter the "Commission") on April 14, 2021. The Commission, heard sworn testimony from the following witnesses: Katherine Godwin, Stephen Rohrer, Bill Leake, Anna Marshal, Bob Nixon, Doil Bussey, and Glenda Steel and considered the following exhibits: Exhibit A: National Register of Historic Places Inventory, Exhibit B: Application for Certificate of Appropriateness, Exhibit C: Subject Property Map, Exhibit D: Scope of Work, Exhibit E: Site Plans, Exhibit F: Tree Risk Assessment Form and Images, Exhibit G: Email Correspondence, and Exhibit H: Letter and Photographs from Glenda Steel. Based upon competent, material, and substantial evidence, the Commission makes these:

#### FINDINGS OF FACT:

7/26

SCANNED AND RETURNED

- 1. The subject property is located at 113 Union Street N, Concord, NC. The owners are Stephen and Dana Rohrer who acquired the property by deed recorded in Cabarrus County Register of Deeds Book 13690, Page 48, as recorded on August 29, 2019.
- 2. The subject property is located in the RM-1 (Residential Medium Density) zoning district and is in the North Union Street Historic District.
- 3. The subject property is designated as a "Pivotal" structure in the Concord Historic Districts Handbook (June 2001 ed.), (the "Handbook") Chapter 3 (Exhibit A).
- 4. The Handbook is an ordinance of the City of Concord duly adopted by the City Council and incorporated into the Code of Ordinances by reference.
- 5. On March 3, 2021, Stephen Rohrer submitted an application (Exhibit B) for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 to make modifications to the property including 1) removing a Crepe Myrtle tree, 2) installing an inground pool in the rear yard with pump and concrete surround, 3) moving a brick patio,

and 4) replacing, redesigning, and extending a wooden privacy fence with three gates (Exhibit B, D, E, and G).

- 6. The owners are proposing to remove a Crepe Myrtle tree in order to install a pool. The stump will be removed and the tree replaced with Nellie Stevens Hollies and Camellia trees (Exhibits B and D).
- 7. The Tree Hazard Evaluation form indicated a hazard rating of 3 and the City Arborist indicated that the tree has no structural defects but the proposed pool installation will impact the root system of the tree (Exhibit F).
- 8. The inground pool would be located in the rear yard in the Southeast corner of the property, measure 20' by 30' and be in a Full L Shape. The pool's depth would vary between 3' and 6' and would consist of fiberglass with a 2'6" concrete surround (Exhibits D and E).
- 9. The inground pool would comply with all of the standards set for in the Concord Development Ordinance Section 8.4.4 Swimming Pools (Exhibit D).
- 10. The applicants are proposing to relocate the brick patio (repurposing the bricks) from beside the garage to connect the new pool to the concrete patio in front of the garage (Exhibits D and E).
- 11. The applicants are proposing to replace, redesign and extend a privacy fence to include:
  - A) Replacing an 8' tall wooden privacy fence measuring approximately 101'3" along the southern boundary of the property with an 8' trimmed wood fence in a boxed style (Exhibits D and G).
  - B) Extending this portion of the fence approximately 49'5" towards Franklin Avenue (Exhibits D and G).
  - C) Replacing a 6' tall wooden privacy fence measuring approximately 110'9" along the eastern boundary of the property with an 8' trimmed wood fence in a boxed style (Exhibits D and G).
  - D) Replacing and moving a wooden picket fence on the eastern side of the house (approximately 46'2" in length and 2.5' in height) with a 4' tall trimmed wood fence in a boxed style (Exhibits D and G). A single side gate would be installed over the sidewalk, measure approximately 3'3" wide and 4' tall, and be of similar design as the fence (Exhibits D and G).
  - E) Replacing a wooden picket fence (approximately 32' in length and 2.5' in height) on the eastern side of the driveway with a 4' tall trimmed wood fence in a boxed style (Exhibits D and G). A double side gate would be installed near the driveway gate, measure approximately 8' wide and 4' tall, and be of similar design as the fence (Exhibits D and G).
  - F) Extending the trimmed wood fence in a boxed style along Franklin Avenue (approximately 92'9" and 4' tall) (Exhibits D and G).
- 12. The new fencing and side gates would be stained using Minwax Red Oak 215 Wood Stain to match the existing stained wood trim on the front porch (Exhibit D).

- 13. A new electric and motorized driveway gate, similar in design to the front yard iron fences and gates (keeping in design with the Queen Anne design of the house) would be installed over the driveway and setback approximately 25' from the street (Exhibit G). The gate would be black powder-coated galvanized steel, measure 6' tall and 10'2" wide and be mounted to 2 brick columns (measuring 2' by 2' and 6' tall) on either side with a concrete cap (Exhibits D and G).
- 14. The privacy fence will be stained on the applicant's side and painted white on the side facing the adjoining properties located at 19 Franklin Street and 103 Union Street N.

Based upon these Findings of Fact, the Commission makes these:

# CONCLUSIONS OF LAW

1. This matter is properly before the Commission pursuant to N.C. Gen. Stat. § 160A-400.7, et seq. and the Concord Development Ordinance.

## 2. Pursuant to the *Handbook*, Approval Requirement Needs Table

- Fencing and Gates (See Masonry Walls): All types require Commission Hearing and Approval.
- Miscellaneous: Any type of alteration of exterior features of a building, site, or environment which is not specifically listed require Commission Hearing and Approval.
- Patios, Walks, and Driveways: Repair or replacement of patios, walks, and driveways with similar materials and design does not require approval.
- Trees: Removal of healthy trees or pruning of limbs over six inches in diameter in any location on the property require Commission Hearing and Approval.

# 3. Pursuant to the *Handbook*, Chapter 5- Section 8: Landscaping and Trees

- Removal of healthy trees over the size of 6 inches in diameter (measured 4 feet above ground) or pruning of healthy tree limbs over 6 inches in diameter requires Historic Preservation Commission review and approval.
- All trees that are removed should be replaced with a tree of similar species in an appropriate location unless no suitable location exists on the subject site. Trees removed within street view must also have the stumps removed below ground level.
- Trees which are removed shall be replaced by a species which, upon maturity, is similar in scale to the removed specimen. For example, canopy trees shall be replaced with canopy trees, and understory trees with understory trees.

# 4. Pursuant to the *Handbook*, Chapter 5- Section 9: Fences and Walls

• *All wooden fences should be "stick-built" on site.* 

- Wooden fences visible from the street and/or wooden fences in front yards and side yards of corner lots are required to be painted or stained white or a color matching the body or trim of the structure, including shutters, foundation color, etc.
- Painting or staining is recommended, but not required, for rear yard fences unless they are visible from the street.
- If a fence is designed as a single-sided fence, one with detailing on only one side, the finished detail should be on the outside face of the fence (facing neighboring property).
- Additionally, wood picket fences should have pickets spaced at a minimum of 1 inch or half the width of the picket. (See notes regarding "Privacy Fences" for allowable exceptions to this rule.)
- Additionally, it is not appropriate to introduce walls or fences in front yards and side yards at corner lots that are more than 65% solid.
- Where fences are desired in front yards and side yards at corner lots, the design should be primarily decorative in nature. Front yard fences should not exceed four feet in height.
- Rear yard fences may be higher than four feet. The portions of rear yard fences that face the street should be landscaped with shrubs and trees of a planting size that will fully hide the fence from the street within two years. Size, type, and growth habits of plant materials to screen rear yard fences that face the street should be submitted at time of application.
- *All proposed fences and walls should not negatively affect existing trees and mature landscaping.*
- Privacy fences are defined as fences with no spacing between pickets or fences of the shadowbox design. Privacy fences may be allowed at the discretion of the Commission in the following circumstances:
  - 1. Privacy fences are most appropriate in rear yards.
  - 2. Privacy fences may be allowed where the applicant's rear yard is directly adjacent to property that is either not in a historic district, or is within a historic district but is non-contributing or intrusive in that district. The applicant shall show to the satisfaction of the Commission:
    - (a) that the adjacent property is unsightly in comparison to other properties surrounding the applicant's property,
    - *(b) that the adjacent property or nearby property raises reasonable security concerns for the applicant, or*
    - (c) that the adjacent property could reasonably be determined to negatively impact the property value of the applicant's property.

Privacy fences shall be allowed only on the applicant's property line directly adjoining the aforesaid adjacent property unless the Commission feels that such a partial privacy fence

would not be visually appropriate or would not accomplish the purpose(s) of the privacy fence set forth above.

3. Privacy fences encompassing an area of no more than 250 square feet may be allowed at the discretion of the Commission when adjacent to the applicant's house, garage, or other outbuilding in order to screen from view trash cans, mechanical equipment, cars or other unsightly items, provided such fence does not unreasonably impact any neighbor by blocking windows or the like.

Privacy fences allowed by the Commission should be landscaped where practical with appropriate shrubbery to soften the appearance of the fence.

#### Design Guidelines

- 1. Do not use high walls or fences to screen front yards.
- 2. Use materials like stone, brick, wood and iron.
- 3. Chain link or plastic materials are prohibited. Adding slats to existing chain link fences for screening purposes is prohibited.
- 4. Materials and style should coordinate with building and neighboring buildings as well as other walls and fences in the area.
- 5. The following criteria shall be considered, when relevant, by the Commission in reviewing applications for a Certificate of Appropriateness. All applications for Certificates of Appropriateness shall be subject to review based upon the Design Guidelines then in effect. These guidelines are set forth in a manual prepared and adopted by the Commission:
  - lot coverage, defined as the percentage of lot area covered by primary structures;
  - setback, defined as the distance from the lot lines to the building(s);
  - building height;
  - exterior building materials;
  - proportion, shape, positioning, location, pattern and sizes of any elements of fenestration;
  - surface textures;
  - structural condition and soundness;
  - walls--physical ingredients, such as brick, stone or wood walls, wrought iron fences, evergreen landscape masses, building facades, or combination of these;
  - color (new construction only and not for existing residences); and
  - effect of trees and other landscape elements.
- 6. The application is congruous with the historic aspects of the District.
- 7. Based on the standards of the Handbook, and the City of Concord Code of Ordinances, including the standards listed above, the Commission concludes that:

- A. The removal of the Crepe Myrtle (including the stump) to be replaced with Nellie Stevens Hollies and Camellia trees is appropriate because the tree will be replaced in accordance with the Historic Handbook.
- B. The installation of an inground pool in the rear yard is appropriate because the design and location is in compliance with the Historic Handbook.
- C. The relocation of the brick patio is appropriate because the proposed new location and the reuse of the brick is in compliance with the Historic Handbook.
- D. The replacement and extension of the 8' privacy fence along the southern boundary of the property with an 8' trimmed wood boxed style privacy fence is appropriate because the fence is in the rear yard and replacing an existing privacy fence.
- E. The replacement of the 6' privacy fence along the eastern boundary of the property with an 8' trimmed wood boxed style privacy fence is appropriate because the fence is in the rear yard and replacing an existing privacy fence.
- F. The replacement and relocation of the 2.5' wooden picket fence with a 4' privacy fence with side gate on the eastern side of the house is appropriate because of its height, design, and location in the front yard.
- G. The replacement of the 2.5' wooden picket fence with a 4' privacy fence and double side gate on the eastern side of the driveway is appropriate because of its height, design, and location in the front yard.
- H. The installation of a 4' privacy fence along Franklin Avenue to the concrete driveway is appropriate because of its height, design, and location on a corner lot.
- I. Staining the fencing and side gates using Minwax Red Oak 215 to match the porch trim is appropriate because the color is in compliance with the Historic Handbook.
- J. The installation of an electric driveway gate and connecting columns is appropriate because it is in compliance with the Historic Handbook with regard to material and design.
- K. The privacy fence will be stained on the applicant's side and painted white on the side facing the adjoining properties located at 19 Franklin Street and 103 Union Street N.

Based upon these Findings of Fact, Conclusions of Law, standards of the Handbook, and the City of Concord Code of Ordinances, including the standards listed above, and limited to the extent consistent with the application, exhibits, and testimony provided to the Commission, the Commission issues this

# **ORDER:**

THE COMMISSION APPROVES A CERTIFICATE OF APPROPRIATENESS TO: REMOVE A CREPE MYRTLE TO BE REPLACED WITH NELLIE STEVENS HOLLIES AND CAMELLIA TREES, INSTALL AN INGROUND FIBERGLASS POOL AND CONCRETE SURROUND, RELOCATE A BRICK PATIO, AND REPLACE, REDESIGN AND EXTEND A PRIVACY FENCE IN ACCORDANCE WITH THIS ORDER.

SO ORDERED this the 14<sup>th</sup> day of April, 2021 by the Historic Preservation Commission.

CITY OF CONCORD HISTORIC PRESERVATION COMMISSION

BY: (Chairman – Dr. Lee Gra

2 Baldwin

NORTH CAROLINA CABARRUS COUNTY

I, Kristing M Fausel, a notary public for said county and state, do hereby certify that <u>Augela Baldwin</u> personally appeared before me this day and

acknowledged the due execution of the foregoing instrument.

WITNESS my hand and official seal, this 15 day of April, 2021.

ustra aure Notary Public

My commission expires: 6-13-2023



FILED CABARRUS COUNTY NC WAYNE NIXON REGISTER OF DEEDS FILED Feb 02, 2023 AT 02:17 pm BOOK 16361 0225 START PAGE 0229 END PAGE **INSTRUMENT #** 02017 \$0.00 EXCISE TAX TMF

Mail to: City of Concord, Planning Dept., PO Box 308, Concord, NC 28026 PIN 5620-79-8008

# NORTH CAROLINAORDER OF THE CITY OF CONCORDCABARRUS COUNTYHISTORIC PRESERVATION COMMISSION CASE # H-25-22

This matter came before the Historic Preservation Commission (hereinafter the "Commission") on December 14, 2022. The Commission heard sworn testimony from the following witnesses: Brad J. Lagano, Stephen D. and wife, Dana M. Rohrer, Albert Benshoff, Connie Bussey, Jennifer Spencer, Bob Nixon, Glenda Steel, Pam Taylor, Kristen Adamczuk, Elly Steel, Bob Steel, Tristan Adamczuk, and considered the following exhibits: Exhibit A: National Register of Historic Places Inventory, Exhibit B: "Ex Post Facto" Certificate of Appropriateness Application, Exhibit C: Subject Property Map, Exhibit D: Applicants' Project Summary, Exhibit E: Recorded Order Dated April 27, 2021, Exhibit F: Packet from Albert Benshoff presented at the hearing containing case law and Certificate of Recording Officer Kim J Deason dated October 24, 2022, Exhibit G: Packet from Rob Steel presented at the hearing containing a copy of his presentation to the Commission, Exhibit H: Packet presented at the hearing containing the Steel's testimony, Civil Summons dated October 17, 2022, email from Starla Rogers, email from Derrick Caudell. Based upon competent, material, and substantial evidence, the Commission makes these:

#### **FINDINGS OF FACT:**

- 1. The subject property is located at 113 Union Street N, Concord, North Carolina. The owners are Stephen D. and wife, Dana M. Rohrer. The property was acquired by deed recorded in Cabarrus County Register of Deeds Book 13690, pages 48 through 52, on August 29, 2019.
- 2. The subject property is located in the RM-1 (Residential Medium Density) zoning district and is in the North Union Historic District.
- 3. The subject property is designated as a "Pivotal" structure in the Concord Historic Districts Handbook (June 2001 ed.), (the "Handbook") Chapter 3 (Exhibit A).

5/26

SCANNED AND RETURNED

Exhibit F

- 4. The Handbook is an ordinance of the City of Concord duly adopted by the City Council and incorporated into the Code of Ordinances by reference.
- 5. On October 25, 2022, Stephen D. and wife, Dana M. Rohrer, applied for an "ex post facto" Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 requesting after-the-fact approval to stain the side of the rear yard fence facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N and to increase the height of the rear yard fence running adjacent to Franklin Ave NW from 4.0' to 6.0' (Exhibits B, D).
- 6. On April 14, 2021, the Historic Preservation Commission approved the rear yard fence to be stained on the Applicants' side and painted white on the side facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N as well as the height of the fence to be 4.0' along Franklin Avenue NW as shown in the Recorded Order filed April 27, 2021, with the Cabarrus County Register of Deeds (Exhibit E).
- 7. In February 2022, rear yard fence construction commenced including along Franklin Avenue NW where the section of fence was constructed to a height of 6.0'.
- 8. In September 2022, rear year fence staining commenced including on the side facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N.
- 9. Both sides of the rear yard fence were stained to match the trim of the home, particularly the original historic columns of the front porch and balcony, along with the double front doors and storm doors. Minmax Red Oak 215 wood stain was used per the Recorded Order filed April 27, 2021.
- 10. Mr. Rohrer testified that fence post caps will be added and landscaping will be added in Spring 2023.
- 11. Mr. Benshoff presented case law regarding res judicata (Exhibit F).
- 12. Mr. Benshoff submitted into evidence the zoning violation issued by City of Concord Code Enforcement dated October 7, 2022 for case CNCE-2022-01876 (Exhibit F).
- 13. Mr. and Mrs. Steel submitted photographs of the subject property and surrounding fences, timeline of events, and public records responses from the City of Concord (Exhibit G and H).

Based upon these Findings of Fact, the Commission makes these:

#### CONCLUSIONS OF LAW

1. This matter is properly before the Commission pursuant to N.C. Gen. Stat. § 160A-400.7, et seq. and the Concord Development Ordinance.

#### 2. Pursuant to the Handbook, Approval Requirement Needs Table: Fencing and Gates

• All types require Commission Hearing and Approval.

### 3. Pursuant to the *Handbook*, Chapter 5 - Section 9: Fences and Walls

- All wooden fences should be "stick-built" on site.
- Wooden fences visible from the street and/or wooden fences in front yards and side yards of corner lots are required to be painted or stained white or a color matching the body or trim of the structure, including shutters, foundation color, etc.
- Painting or staining is recommended, but not required, for rear yard fences unless they are visible from the street.

- Where fences are desired in front yards and side yards at corner lots, the design should be primarily decorative in nature. Front yard fences should not exceed four feet in height.
- Rear yard fences may be higher than four feet. The portions of rear yard fences that face the street should be landscaped with shrubs and trees of a planting size that will fully hide the fence from the street within two years. Size, type, and growth habits of plant materials to screen rear yard fences that face the street should be submitted at time of application.
- All proposed fences and walls should not negatively affect existing trees and mature landscaping.
- Privacy fences are defined as fences with no spacing between pickets or fences of the shadowbox design. Privacy fences may be allowed at the discretion of the Commission in the following circumstances:
  - A. Privacy fences are most appropriate in rear yards.
  - B. Privacy fences may be allowed where the applicant's rear yard is directly adjacent to property that is either not in a historic district, or is within a historic district but is non-contributing or intrusive in that district. The applicant shall show to the satisfaction of the Commission:
    - *i. that the adjacent property is unsightly in comparison to other properties surrounding the applicant's property,*
    - *ii. that the adjacent property or nearby property raises reasonable security concerns for the applicant, or*
    - *iii.* that the adjacent property could reasonably be determined to negatively impact
    - *the property value of the applicant's property.*
  - C. Privacy fences encompassing an area of no more than 250 square feet may be allowed at the discretion of the Commission when adjacent to the applicant's house, garage, or other outbuilding in order to screen from view trash cans, mechanical equipment, cars or other unsightly items, provided such fence does not unreasonably impact any neighbor by blocking windows or the like.
  - D. Privacy fences allowed by the Commission should be landscaped where practical with appropriate shrubbery to soften the appearance of the fence.
- 4. The following criteria shall be considered, when relevant, by the Commission in reviewing applications for a Certificate of Appropriateness. All applications for Certificates of Appropriateness shall be subject to review based upon the Design Guidelines then in effect. These guidelines are set forth in a manual prepared and adopted by the Commission:
  - lot coverage, defined as the percentage of lot area covered by primary structures;
  - setback, defined as the distance from the lot lines to the building(s);
  - building height;
  - exterior building materials;
  - proportion, shape, positioning, location, pattern and sizes of any elements of fenestration;
  - surface textures;
  - structural condition and soundness;
  - walls--physical ingredients, such as brick, stone or wood walls, wrought iron fences, evergreen landscape masses, building facades, or combination of these;
  - color (new construction only and not for existing residences); and
  - effect of trees and other landscape elements.

- 5. The application is congruous with the historic aspects of the District.
- 6. Based on the standards of the Handbook, and the City of Concord Code of Ordinances, including the standards listed above, the Commission concludes that:
- There was sufficient evidence presented to reopen the prior approval and approve the "ex post facto" request for after-the-fact approval to increase the height of the fence running adjacent to Franklin Ave NW from 4.0' to 6.0' is appropriate as the wooden fence is visible from the street and is located in the rear yard and therefore may be higher than 4.0', and is in compliance with the Historic Handbook.

There was insufficient evidence presented to reopen the prior approval as to the fence color and the Commission did not vote to amend the fence color that was initially approved in Case H-04-21 on April 14, 2021.

Based upon these Findings of Fact, Conclusions of Law, standards of the Handbook, and the City of Concord Code of Ordinances, including the standards listed above, and limited to the extent consistent with the application, exhibits, and testimony provided to the Commission, the Commission issues this

#### **ORDER:**

THE COMMISSION APPROVES AN EX-POST FACTO CERTIFICATE OF APPROPRIATENESS TO INCREASE THE HEIGHT OF THE REAR YARD FENCE RUNNING ADJACENT TO FRANKLIN AVE NW FROM 4.0' TO 6.0' AT 19 FRANKLIN AVENUE NW AND 103 UNION STREET N.

THE REQUEST TO AMEND THE FENCE COLOR THAT WAS INITIALLY APPROVED AS PART OF CASE H-04-21 ON APRIL 14, 2021, WAS NOT APPROVED.

SO ORDERED this the 14<sup>th</sup> day of December, 2022 by the Historic Preservation Commission.

CITY OF CONCORD HISTORIC PRESERVATION COMMISSION

BY: William I penhow

(Chairman – William Isenhour)

1 Saldwin

NORTH CAROLINA CABARRUS COUNTY I, <u>Alicia J. Brodivay</u>, a notary public for said county and state, do hereby certify that <u>Angela Baldwin</u> personally appeared before me this day and acknowledged the due execution of the foregoing instrument.

WITNESS my hand and official seal, this  $15^{++}$  day of December, 2022.

Vilion Broadesay Notary Public My commission expires: May 28, 2026 <sup>704</sup>

### HISTORIC PRESERVATION COMMISSION MEETING MINUTES Wednesday, December 14<sup>th</sup>, 2022

Members Present:	William Isenhour James Firth Mary Margaret Underwood Meredith Barbee
Alternate Members:	
Members	Carolyn Coggins
Absent:	Ismail Diken
	Shelby Dry
	Anna Marshall
	Aimee Cain
Attorney to	
Commission:	Keith J. Merritt – Hamilton Stephens Steel + Martin, PLLC
Staff Present:	Kevin Ashley, Deputy Planning Director Scott Sherrill, Planning and Development Manager Brad Lagano, Senior Planner Angela Baldwin, Sr. Executive Assistant George Daniels, Senior Planner

#### CASES HEARD:

# H-15-22 – STC COLEMAN MILL LLC – 625 MAIN ST. SW H-25-22 – STEPHEN AND DANA ROHRER – 19 FRANKLIN ST

# CALL TO ORDER:

Chair Isenhour called the December 14<sup>th</sup>, 2022 Historic Preservation Commission meeting to order at 6:00 p.m.

#### **CHANGES TO THE AGENDA**:

Commissioner Barbee made a motion to hear Case H-25-22 first under new business. Commissioner Firth seconded the motion. The vote carried unanimously. **–The Vote: All Ayes** 

### **INTRODUCTIONS**:

Meredith Barbee, Mary Margaret Underwood, James Firth, and William Isenhour,

 $1 \mid P a g e$ 

# **APPROVAL OF MINUTES:**

Commissioner Underwood made a motion to approve the November 09, 2022 minutes. Commissioner Barbee seconded the motion. The vote carried unanimously. –The Vote: All Ayes (APPROVED)

#### H-25-22 (QUASI-JUDICIAL HEARING) STEPHEN AND DANA ROHRER HAVE SUBMITTED A CERTIFICATE OF APPROPRIATENESS APPLICATION FOR "EX POST FACTO" (AFTER THE FACT) APPROVAL TO STAIN THE SIDE OF THE REAR YARD FENCE FACING THE ADJOINING PROPERTIES AT 19 FRANKLIN ST AND 103 UNION ST N AND TO INCREASE THE HEIGHT OF THE REAR YARD FENCE RUNNING ADJACENT TO FRANKLIN ST FROM 4.0' TO 6.0' LOCATED AT 113 UNION ST N. PIN 5620-79-8008.

Brad Lagano introduce the case to the Commission.

The subject property at 113 Union Street N is designated as a "Pivotal" structure in the North Union Street Historic District (ca. 1890). "Highly significant, exceptionally well-preserved, two-story frame Queen Anne style residence, the best example of the style in Concord. House is enhanced by its prominent setting on a large, corner lot with a fine late nineteenth century ornamental iron fence. A particularly notable feature of the house is the variety of sawn and molded woodwork applied to its surface. Each of the house's several gables is covered with scalloped shingles and framed with decorative sawn and molded boards; scalloped shingles also cover the flared base of the house's second story. Above the second floor is a cut-out frieze with a repeating tree shape; a frieze with a sheaf-of-wheat pattern run along parts of the house's sides. The facade has a gable-front by projecting from the main roofline, and · a central balcony with richly ornamented woodwork sheltered by a projecting hip roof. The southern (left) portion of the well-detailed wrap-around porch was enclosed with latticed window sash typical of the bungalow style during the 1920s" (Exhibit A). Applicants' requested modification: "ex post facto" (after-the-fact) approval to stain the side of the rear yard fence facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N and to increase the height of the rear yard fence running adjacent to Franklin Avenue NW from 4.0' to 6.0'.

# **DISCUSSION**

On October 25, 2022, Stephan and Dana Rohrer applied for an "ex post facto" Certificate of Appropriateness requesting after-the-fact approval to stain the side of the rear yard fence facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N and to increase the height of the rear yard fence running adjacent to Franklin Ave from 4.0' to 6.0'. On April 14, 2021, the Historic Preservation Commission approved the rear yard fence to be stained on the Applicants' side and painted white on the side facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N as well as the height of the fence to be 4.0' along Franklin Avenue NW as shown in the Recorded Order filed April 27, 2021, with the Cabarrus County Register of Deeds. In February 2022, rear yard fence construction commenced including on the side facing the adjoining properties at 19 Franklin Avenue NW. In September 2022, rear year fence staining commenced including on the side facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N.

Concord Development Ordinance – Section 7.7.4 (A) states "front yard fences, including fences on corner lots, shall not exceed 4.0' in height. Fences may not be placed within the sight triangle." However, this provision of the zoning ordinance has not been applied consistently by the Historic Preservation Commission on corner lots. The front yard fence has been traditionally defined as the portion of the fence located between the midpoint of the structure and the street the house faces capping the fence height at 4.0' whereas the rear yard fence has been traditionally defined as the portion of the fence located between the midpoint of the structure and the rear property line allowing for taller fence heights such as 6.0' or 8.0'. The intent of the latter to allow for taller heights for rear yard privacy purposes even on corner lots.

Stephen Rohrer 113 Union Street Concord, NC appeared before the Commission. Mr. Rohrer explained that the reason for getting the fence was for security concerns for their children and pets and for privacy as they were having strangers trespassing through the property. He further stated that the fence extends to the beauty of the home and it blends with the trim on the house. Mr. Rohrer stated that he does have pictures of fences on corner lots in the Historic District but he will not show them because of privacy reasons. There are many of them and theirs does follow the rules. They made sure that their fence was not encroaching on anyone else's property lines. Mr. Rohrer stated that they do not have all of the fence post caps on the fence because their 4x6 posts have not come in yet. The plants are still coming and will be planted in the spring. The height of the fence was completely by accident and they did not know that it was 6ft. In October 2022, the HPC approved the tearing down of a 4ft fence to put up a 6ft fence in the rear of the home along the side street. The stain was chosen because it matched the trim and body of their home and it was recommended to not put paint on the fence because it would crack and peel. It will require a high level of maintenance. Mr. Rohrer showed the Commission an example of a fence recently approved by the HPC and it already shows dirt and stains.

Attorney Benshoff asked to cross-examine Mr. Rohrer.

Attorney Benshoff 221 Ravine Circle SE Concord, NC stated that he is an attorney with the Brough Law Firm in Chapel Hill, NC and he is representing Rob and Glenda Steel in this matter.

Attorney Benshoff asked Mr. Rohrer if he applied for a Certificate of Appropriateness. Mr. Rohrer explained that he did not prepare for cross-examination.

Attorney Merritt explained that the Historic Preservation Commission meeting is a quasi-judicial hearing and it functions as if the parties are in court, and the Commission members are technically serving as a judge. When you get up and you are speaking, you're sworn in beforehand and you are testifying basically as if you are in court. A person or party who is opposing your application has the right to cross-examine a witness and ask questions of that witness after they have testified. So, in this case, Mr. Benshoff, on behalf of his client, has the opportunity to cross-examine a witness who has testified in favor of the application. It is not an unusual circumstance in a quasi-judicial type hearing, but doesn't happen at every quasi-judicial hearing. In order to protect the due process rights of folks, all parties have the opportunity to cross-examine a witness.

Attorney Benshoff asked Mr. Rohrer again, did he apply for a Certificate of Appropriateness from this body for the fence? And stated that he has the order of the Commission here. Attorney Benshoff asked if he was familiar with this order from the Historic Preservation Commission.

Mr. Rohrer stated that he did not receive the Order and Mr. Lagano was the first one from the City that showed it to him. Mr. Rohrer reiterated that he has never seen the Written Order or know about it in any way, shape, or form, nor did he ever receive the Certificate of Appropriateness from his approved application. And after Mr. Lagano reached out to him Mr. Rohrer said he told him that he did not know what that is.

Attorney Benshoff asked Mr. Rohrer has he read the Order within the last sixty days? Mr. Rohrer stated yes and reconfirmed that he did not ever receive an Order or Certificate of Appropriateness. Also, he never received an Order until Mr. Lagano gave it to him at the end of October or early November.

Attorney Benshoff asked Mr. Rohrer to take a look at the Order and asked him if it says, "The privacy fence will be stained on the applicant's side and painted white on the side facing the adjoining properties, located at 19 Franklin Street and 103 North Union.

Mr. Rohrer stated yes, that is what it says.

Attorney Benshoff stated this is the Order of the Commission, signed by the Chair, attested to by the Secretary, and recorded in the title to this property in the deed at the Register of Deeds of Cabarrus County.

Attorney Benshoff asked Mr. Rohrer since April 21, 2021, when the Order was heard and granted by the Commission, what exterior changes have you made to your property?

Mr. Rohrer explained that he does not know the exact date but there's a fence on their property. Also, they have continued the original renovation that the HPC approved, which included things like siding and trim.

Attorney Benshoff asked Mr. Rohrer has he purchased any additional real property and added it to the lot. Mr. Rohrer stated no. Attorney Benshoff asked Mr. Rohrer has he sold any portion of his lot or constructed additional buildings. Mr. Rohrer stated no. Attorney Benshoff asked Mr. Rohrer has he increased the height of the existing buildings on his property. Mr. Rohrer replied that he built a second-floor addition on the back half of their house that would have removed some attics and increased the height. Attorney Merritt asked how does this relate? Attorney Benshoff stated that he trying to relate if the Rohrers' made material changes to the property.

Attorney Benshoff asked Mr. Rohrer in regards to his testimony of fences on corner lots in the district if he knows when they were erected or if they received a Certificate of Appropriateness. Mr. Rohrer stated that he does not.

Attorney Benshoff stated that he objects to the picture example presented earlier by Mr. Rohrer from being in the record as there is no foundation for including this picture.

Mr. Rohrer stated that it's two parcels to the south and the fence belongs to a board member that's not here tonight. And stated that he would hold off on calling that person out unless the Commission would like him to. Mr. Rohrer stated that it is Anna Marshall's fence that she got approved four months ago and had erected and painted white, and it's already showing spots.

Dana Rohrer 113 Union Street Concord, NC appeared before the Commission. Ms. Rohrer explained that they are in the process of renovating their home. For the past two years, her struggle has not been how they have spent their life savings on renovating their home, but dealing with their neighbors, who are going to stand up and bash and criticize them. They should not be given a platform to discourage people like her who are building a future for their families and improving the district. They put up a fence to try to stop them from harassing them, and they have forced them to call the police twice. they have installed no trespassing signs, and have gone to court three times.

Mr. Benshoff objected to Ms. Rohrer's testimony.

Ms. Rohrer continued and stated that she has photographic evidence. Ms. Rohrer stated that the neighbor is a former HPC member and their friend, the previous City of Concord attorney, trespassed on their property, and opened their front door, which is illegal and a safety concern. The neighbors continue to harass them. The neighbors could solve the problem by building their own fence and abiding by the handbook. Ms. Rohrer stated that would show the Commission a video of the neighbors' attorney trespassing and opening their front door and Ms. Rohrer asked to show the video to the Commission. Chair Isenhour stated that it would be improper to show the video as it does relevant and does not pertain to the appropriateness of the fence.

Kristin Adamczuk 97 Union Street N spoke in favor of the request. Ms. Adamczuk stated that she thinks her case was H-10-20 back in 2020, and she was never allowed to address anyone other than the board during her case. She stated that the hard work that the Rohrers have put into their property has been in no violation of the historic handbook, and the people that continue to waste the Boards' time and the City's resources should be embarrassed. It doesn't portray the community of Concord she grew up in, and it certainly doesn't portray what she is proud of. Ms. Adamczuk stated that she doesn't find it necessary to discuss the color of the fence. It's in the handbook. The Commission is supposed to be here to approve what's in the handbook. Ms. Adamczuk stated that she would like to address the security and safety concerns. Ms. Adamczuk stated that she lives two doors down and can attest to unwanted individuals coming onto their property including recently released inmates and homeless people. Ms. Adamczuk stated that officer Parker here tonight can attest and corroborate her testimony. If their fence wasn't the height that it is right now, the people walking down Franklin can look right into their backyard and perhaps people in opposition don't have children or don't understand that safety concern. There's no reason that their COA tonight shouldn't just be approved.

# **OPPOSITION:**

Mr. Albert Benshoff, of Borough Law Firm 1526 East Franklin Street Chapel Hill, NC 27516, passed out some documents to the Commission. Mr. Benshoff stated his firm's address is 1526 East Franklin Street, Chapel Hill, NC 27516. Mr. Benshoff stated that he has three witnesses. First, he stated that he could like to make a presentation about the case law that governs this hearing tonight. The Rohrers got a Certificate of Appropriateness on April 21, 2022, which contained conditions in the order about the fence and the height of the fence. The deadline to appeal is 30 days, which was approximately May 22, 2021. There's no appeal in the record. On October 7, 2022, the City issued a notice of violation which is included in the materials he presented. There is no evidence that the violation is not still valid, and the color of the fence and the height of the fence are in violation of the April 21 order. On October 25, the Rohrers made an ex post facto application.

He handed up two cases which are the behind the explanation of the case Law.

The fact is that in North Carolina, once the quasi-judicial decision becomes effective, this board has no legal authority or jurisdiction to hear the matter a second time. This has been the law in North Carolina since 1928 in the case of Little versus the City of Raleigh Board of Adjustment. On page two of the Little case, the holding of the court is highlighted. In that case, the NC Supreme Court found that the applicant could not bring the same matter before the Board of Adjustment of Raleigh once it had been decided. The holding in the Little case was affirmed by the Court of Appeals in the cited Mount Ulla case, which is also attached. Furthermore, the Mount Ulla case introduced that a change in the law that said that the case could be heard again if there is a material change, or a change in circumstances which led to the prior decision. In this case, you have the same exact claim.

Attorney Benshoff stated that they heard no testimony that there was a material change in the condition of the property that would make this a new case. Lawyers call this res judicata. Decisions already made by a court cannot be heard again. The Court of Appeals found that a second application was barred because it was so similar to the previous quasi-judicial decision. The Court adopted the definition that the change in circumstances must be such that the application for the same or substantially similar or special exception or variance no longer can be characterized as the same claim.

Attorney Benshoff moved that the Rohrer application be dismissed because this Commission lacks subject matter jurisdiction and the applicants have not made a valid claim or application that can be granted. There is no competent material and substantial evidence in the record of a material change in the facts and circumstances to overcome his client's claim of res judicata that the matter is barred because it's essentially a rehearing of the same matter that was heard in 2021.

Mr. Rohrer asked Attorney Benshoff to state to everyone the type of application he submitted.

Attorney Benshoff stated that he has read Mr. Rohrer's application.

Mr. Rohrer stated that an ex post facto application should give him the right, as a homeowner in the district, to come back when there are changes, or unapproved changes by the Commission. He stated that he thinks that's why they have the ex post facto in the first place.

Attorney Benshoff stated that those are not material changes under North Carolina law.

Mr. Rohrer stated that in reference to the process that one person who is not the applicant or a neighboring party has taken over 10 to 20 minutes of our time. This has been a very lengthy process and we need to hear the other people, and they need to have their two minutes.

### COMMISSION DISCUSSION:

Chair Isenhour stated that the question for the commissioners is if they want to rule on dismissal now or if they want to hear the rest of the opponent's testimony and then discuss that after they close the public hearing.

Commissioner Barbee questioned ruling on dismissal at this point. To her, she understands the argument about the facts haven't materially changed. However, she would be interested to hear more testimony from the folks opposed as well as perhaps the applicant, about what caused them to bring an ex post facto application.

# **OPPOSITION**:

Attorney Benshoff pointed out that there's no evidence in the record of any kind that an ex post facto application is recognized by the Concord Development Ordinance.

Mr. Benshoff presented a PowerPoint presentation to the Commission.

Robert Steel 103 Union Street N Concord, NC appeared in opposition to the request. Mr. Steel stated that he is the neighbor to the left facing the front of the Rohrer's home. Mr. Steel stated that the neighbors opposed the dark brown stain of the fence adjacent to their property. It's not visible from the street facing the front side of 113 Union Street but creates for them a glaring aesthetic concern with the adjacent white fence on the neighboring property that affect the property values. It's simply not appropriate in the Historic district. The homeowners violated their agreement with the adjacent property owners.

# **CROSS-EXAMINATION:**

Mr. Rohrer asked Mr. Steel, of all the fences that are adjacent to his property, could he tell the Board what color, what different colors, unique colors there are of those fences that are all adjoining or adjacent to his property.

Mr. Steel replied that he has a white picket fence that was put in in 1980 and in the back part of his property he has a wooden fence stopping at Mr. Rohrer's area.

Mr. Rohrer asked Mr. Steel, if he knew how far from the property line the new fence was constructed, and Mr. Steel replied less than Steel 18in.

Mr. Rohrer said to Mr. Steel so you are saying that the fence is well within his property. Mr. Steel stated that he did not say that at all.

Attorney Benshoff stated that he would like to qualify Mr. Steel as an expert witness and asked him if he has any training, education, or experience in historic preservation.

Mr. Steel stated yes, he is a registered professional engineer. He was attracted to the historic district because of the buildings and the appropriateness that they like to maintain. He stated that he sat on this Commission for over six years and was chair of it for three years. In fact, he co-authored the handbook the Commission is using.

Chair Isenhour asked Attorney Benshoff what is Mr. Steel an expert in. Attorney Benshoff stated that he wanted to qualify Mr. Steel as an expert to be able to give an opinion that it was not appropriate.

Commissioner Barbee stated that he she does not think he needs to be qualified as an expert to testify to that as a neighbor can do that.

# **OPPOSITION**:

Glenda Steel 103 Union Street N Concord, NC appeared in opposition to the request. Ms. Steel stated that on March 3<sup>rd</sup>, the original application and all work were supported and unopposed by neighbors, except for the standing on the adjacent neighbors' side, which isn't seen by 113 Union Street North. That was the original application. At the April 14 meeting, the minutes reflected that Mr. Rohrer met with the Nixons and the Steels, and the consensus was for the fence designed to stay the same, and the Nixon's and Steel's sides of the fence will be painted white and stained on the inside. Commissioners approved that COA with amendments including item K. The Certificate of Appropriateness was issued after the agreement made at the HPC meeting on April 14, stating that the approved rear yard fence is to be stained on the applicant's side and painted white on the side facing the adjoining properties.

February 2022 is when the work started on the fence with no notice to adjacent owners. The fence design as proposed and approved in the April 21, COA has not been completed as of December 14<sup>th</sup>, and it was not painted white as agreed upon. Ms. Steel stated that it was her understanding that the owners had the right to appeal within thirty (30) days. The Planning Department was contacted and Kristen Sullivan explained, as stated in the order, they have to stain the fence and paint it white on the sides facing their home and 19 Franklin Street.

On June 22 of this year, Ms. Steel contacted the Planning Department again and Starla Rogers explained to her, if the project is completed and is not installed or constructed as approved, the City can make contact to the owner either through Planning to notify the property owner of the requirements or through Code Enforcement via violation. Ms. Steel indicated that per Ms. Rogers, Planning had discussed the requirements with the applicant, and it was their understanding that the intent was to install the fence and

finish the fence as approved. Ms. Steel stated that as a direct result of that inquiry, Ms. Rohrer went to the police two days later to file a claim of harassment. On September 22, the fence was stained.

Ms. Steel stated that the current COA from April 21 which includes agreement with the owners of 113 Union Street North, and with adjacent property owners should be enforced and followed.

#### **Cross Examination:**

Mr. Rohrer asked Ms. Steel if the handbook requires notice to neighbors to start work on an approved project. Ms. Steel stated that she thinks it is standard courtesy if someone enters someone else's property, they should receive notice.

Mr. Rohrer asked Ms. Steel, how far is the fence from her property line.

Ms. Steel stated that she thinks it was setback approximately six inches, and that was intentional on their part. She stated that Planning informed her that the main issue relative to fence setbacks is that the fence is placed on the subject property.

# **OPPOSITION:**

Dr. Ellie Steel 24 Franklin Avenue NW appeared in opposition to the request.

Dr. Steel stated that she is adjacent to the Rhorer's' property and she does not object to the increased fence height and understands that they value their privacy. Dr. Steel noted that on her parent's property, there are only two privacy fences, so when discussing a black fence, a white fence, or a green fence that are all four feet tall or less with spacing in between the pickets, that is a different aesthetic and not a privacy fence. Dr. Steel stated that the applicant's fence is a wall of dark brown staining. She stated that she thinks that's what Mr. Rohrer was trying to say, that there are multiple fences and there are, but she contends they are not privacy fences as they are not higher than four feet tall.

Dr. Steel explained that when she has made changes to her house, as required, she applies in advance to get a Certificate of Appropriateness, before the work is commenced and if any change or if there was anything that she was going to disagree with, she would need to appeal within 30 days. After that, an ex post facto application is not an appropriate application process, as that is not in the Handbook. The Rohrers are asking for approval after the fact, which the Handbook and North Carolina General Statute says has to be followed and is enforceable. So, when zoning violations or planning violations are communicated to the City of Concord, that is not an attack on owners.

Dr. Steel stated that Mr. Rohrer said that handbooks make suggestions, which is not true as the handbook is part of the Ordinance. And again, the only issue that they are asking to be rectified by this Commission and denied by this Commission is that the owners agreed to something with both of their adjacent property owners and those changes were ignored when the original COA was violated. Also, all of the post caps have been installed in other areas on their fence except for the ones in between these two properties.

Attorney Benshoff summed up the matter by stating that all have heard the saying, it's better to ask for forgiveness rather than permission. And that's the case you have here. People are asking the Commission to approve something that's in violation of the order issued by this board in April 2021, and there's a violation still in effect. Attorney Benshoff stated that he would urge the Commission to not approve the COA or to dismiss the COA.

Bob Nixon 65 Curtis Street Concord, NC spoke regarding the request. Mr. Nixon stated that he was in the process of putting his house on the market and their realtor asked him if he could find out wat was going to happen with the fence as it had not been painted. Mr. Nixon stated that he asked Mr. Rohrer about his plans for the fence and Mr. Rohrer stated that they would be painting the fence, and putting the caps on in about four to six months.

### **CROSS EXAMINATION:**

Mr. Rohrer asked Mr. Nixon if he has the messages between them and his realtor regarding the fence at tonight's hearing. Mr. Nixon stated that he did not.

Mr. Rohrer clarified the messages between him, his wife, and Ford Craven the realtor stated that they were having trouble trying to wrap up the first renovation of their house is why the fence was taking longer.

#### **OPPOSITION**:

Pam Taylor 92 Spring Street NW Concord, NC appeared before the Commission. Ms. Taylor explained for all the reasons that have been mentioned tonight by Rob and Glenda Steel and Glenda and Rob's daughter, she feels that the Commission should enforce the decision that was made in, 2021 regarding the painting of the adjacent property side of the fence.

#### **SWEARING IN OF WITNESS:**

Tristan Adamczuk was sworn in to speak.

#### **PROPONENT:**

Mr. Adamczuk 97 Union Street N Concord, NC appeared in favor of the request. Mr. Adamczuk stated that none of the facts mentioned by Attorney Benshoff will be valid for Cabarrus County. He further stated that it boils down to nothing with the color, and nothing with the fence height. It is boiling down to just animosity. There are multiple parties that are affected by this conflict, not just the Rohrers and this is a waste of time and resources. Mr. Adamczuk stated that Mr. Rohrer cannot control the majority of the things that they are going through because it is a massive renovation. He stated that they are in support of the Rohrers.

#### **COMMISSION QUESTIONS AND DISCUSSION:**

Commissioner Barbee asked Ms. Steel if she is correct in saying that all they want to happen is for their side of the fence to be painted white.

Ms. Steel stated that is correct.

Commissioner Barbee asked Mr. Steel she feels about having a stained fence with different colored post caps.

Mr. Steel stated that she is okay if the caps are stained and not white.

Commissioner Barbee asked about a maintenance plan for the fence. Mr. Steel stated that his history with the Nixons is that they would help out and work together on it.

Dr. Steel stated that it was also not an issue with the previous fence that separated 113 Union Street and 103 Union Street North. As Mr. Rohrer has pointed out, their side was not in as good a condition, and that was due to previous owners not maintained maintaining it as well.

Chair Isenhour stated to the Steels for clarification that their primary complaint is the white paint as he has not heard anything against the height on Franklin Street.

Ms. Steel stated that the only thing they ever asked for in the original application was white on their side, which no one would see but them.

Commissioner Barbee made a motion to close the public hearing. Commissioner Underwood seconded the motion. The vote carried unanimously. –**The Vote: All Ayes** 

# **COMMISSION RULES OF PROCEDURE**

Attorney Merritt stated that the Commission does have a set of bylaws and rules of procedure that it adopted that he had requested and that the attorney that usually sits here sent him a copy of. And before consideration, he wanted to make the Commissioner aware of a few things that are in the rules of procedure. In a quasi-judicial hearing, cross-examination of witnesses is allowed and the party asking for their certificate shall present evidence to the Commission, and the applicant has the burden of proof to establish their entitlement to the application that they are seeking from the Commission. There are also procedural motions that are allowed.

Attorney Merritt stated there are two of procedural issues that he thinks are relevant to the consideration of the issue tonight. The first is to consider or reopen the previous quasi-judicial matter. This certificate was also issued at a quasi-judicial hearing and this motion may be made at the meeting during which the original vote is taken, or in the case of the submission of new evidence, at a later meeting as the Commission has the ability to reconsider or reopen a quasi-judicial matter in the case of submission of new evidence. The applicant needs to show some type of new evidence in order to have a prior quasi-judicial hearing reopened. The other issue that is relevant, is that the commission can make a motion to consider whether an application or topic has previously been decided and that it explains the legal terms are res judicata, which is claim preclusion, and collateral estoppel, which is issue preclusion. Mr. Merritt stated that the first order of business is to determine if application that's before the Commission has been previously decided.

Commissioner Barbee stated that she thinks there has been some new evidence presented, not only from the applicant but as well as the folks in opposition. Commissioner Barbee stated that the testimony from the Steels is that there is no objection to the height.

Commissioner Underwood stated that she thinks they should reopen the case because she does not understand how it was decided that a fence could be two different colors.

Chair Isenhour stated that he does not think the Commission can go back and second-guess the decisions made by a prior Commission. Chair Isenhour stated that when the Commission issues orders, it is with the expectation that the applicants are going to comply with the order. In the event that there has been a change of circumstances that led to the granting of the certificate in the first place, that may cause the Commission to revisit the case. Orders are issued for a reason and the height change appears to be an accident but the stain issue is not.

Commissioner Barbee explained that the color is specifically outlined in the order.

Attorney Merritt stated that as far as the effect of the order, they are filed with the registered deeds office, runs with the land, and is a requirement that binds future property owners.

Commissioner Barbee stated that she was comfortable reopening the public hearing regarding the height of the fence as there was some testimony from the applicant about security concerns which would constitute a change in circumstances. But, no one has given any evidence of a change in circumstances relative to the paint color.

Attorney Merritt explained that there is an appeal process that must be followed when applicants do not agree with decisions made by the Commission, and stated that he thinks the Commission can make a decision to find that there is sufficient new evidence to reopen the prior decision relative to the height of the fence, but not sufficient new evidence to reopen the prior decision as to the color of the fence. As a result, the Commission would have two separate decisions.

Commissioner Barbee made a motion to re-open the quasi-judicial matter to reconsider the fence height only. Commissioner Underwood seconded the motion. The vote carried unanimously. –**The Vote: All Ayes** 

Commissioner Barbee made a motion to approve the Findings of Fact as amended with respect to the height of the fence with the witnesses on the sign in sheet. Commissioner Firth seconded the motion. The vote carried unanimously. –The Vote: All Aye

# FINDINGS OF FACT:

- 1. The subject property is located at 113 Union Street N, Concord, North Carolina. The owners are Stephen D. and wife, Dana M. Rohrer. The property was acquired by deed recorded in Cabarrus County Register of Deeds Book 13690, pages 48 through 52, on August 29, 2019.
- 2. The subject property is located in the RM-1 (Residential Medium Density) zoning district and is in the North Union Historic District.
- 3. The subject property is designated as a "Pivotal" structure in the Concord Historic Districts Handbook (June 2001 ed.), (the "Handbook") Chapter 3 (Exhibit A).
- 4. The Handbook is an ordinance of the City of Concord duly adopted by the City Council and incorporated into the Code of Ordinances by reference.
- 5. On October 25, 2022, Stephen D. and wife, Dana M. Rohrer, applied for an "ex post facto" Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 requesting afterthe-fact approval to stain the side of the rear yard fence facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N and to increase the height of the rear yard fence running adjacent to Franklin Ave NW from 4.0' to 6.0' (Exhibits B, D).
- 6. On April 14, 2021, the Historic Preservation Commission approved the rear yard fence to be stained on the Applicants' side and painted white on the side facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N as well as the height of the fence to be 4.0' along Franklin Avenue NW as shown in the Recorded Order filed April 27, 2021, with the Cabarrus County Register of Deeds (Exhibit E).
- 7. In February 2022, rear yard fence construction commenced including along Franklin Avenue NW where the section of fence was constructed to a height of 6.0'.
- 8. In September 2022, rear year fence staining commenced including on the side facing the adjoining properties at 19 Franklin Avenue NW and 103 Union Street N.
- 9. Both sides of the rear yard fence were stained to match the trim of the home, particularly the original historic columns of the front porch and balcony, along with the double front doors and storm doors. Minmax Red Oak 215 wood stain was used per the Recorded Order filed April 27, 2021.

- 10. Mr. Rohrer testified that fence post caps will be added and landscaping will be added in Spring 2023.
- 11. Mr. Benshoff presented case law regarding *res judicata* (Exhibit F).
- 12. Mr. Benshoff submitted into evidence the zoning violation issued by City of Concord Code Enforcement dated October 7, 2022 for case CNCE-2022-01876 (Exhibit F).
- 13. Mr. and Mrs. Steel submitted photographs of the subject property and surrounding fences, timeline of events, and public records responses from the City of Concord (Exhibit G and H).

Commissioner Barbee made a motion to approve the Conclusions of Law as amended with respect to the height of the fence and color of fence. Commissioner Firth seconded the motion. The vote carried unanimously. –The Vote: All Aye

### **CONCLUSIONS OF LAW:**

- 1. This matter is properly before the Commission pursuant to N.C. Gen. Stat. § 160A-400.7, et seq. and the Concord Development Ordinance.
- 2. Pursuant to the *Handbook*, Approval Requirement Needs Table: Fencing and Gates
  - All types require Commission Hearing and Approval.
- 3. Pursuant to the *Handbook*, Chapter 5 Section 9: Fences and Walls
  - All wooden fences should be "stick-built" on site.
  - Wooden fences visible from the street and/or wooden fences in front yards and side yards of corner lots are required to be painted or stained white or a color matching the body or trim of the structure, including shutters, foundation color, etc.
  - Painting or staining is recommended, but not required, for rear yard fences unless they are visible from the street.
  - Where fences are desired in front yards and side yards at corner lots, the design should be primarily decorative in nature. Front yard fences should not exceed four feet in height.
  - Rear yard fences may be higher than four feet. The portions of rear yard fences that face the street should be landscaped with shrubs and trees of a planting size that will fully hide the fence from the street within two years. Size, type, and growth habits of plant materials to screen rear yard fences that face the street should be submitted at time of application.
  - All proposed fences and walls should not negatively affect existing trees and mature landscaping.
  - Privacy fences are defined as fences with no spacing between pickets or fences of the shadowbox design. Privacy fences may be allowed at the discretion of the Commission in the following circumstances:
    - A. Privacy fences are most appropriate in rear yards.
    - B. Privacy fences may be allowed where the applicant's rear yard is directly adjacent to property that is either not in a historic district, or is within a historic district but is non-contributing or intrusive in that district. The applicant shall show to the satisfaction of the Commission:
      - *i. that the adjacent property is unsightly in comparison to other properties surrounding the applicant's property,*
      - *ii. that the adjacent property or nearby property raises reasonable security concerns for the applicant, or*
      - *iii. that the adjacent property could reasonably be determined to negatively impact the property value of the applicant's property.*

- C. Privacy fences encompassing an area of no more than 250 square feet may be allowed at the discretion of the Commission when adjacent to the applicant's house, garage, or other outbuilding in order to screen from view trash cans, mechanical equipment, cars or other unsightly items, provided such fence does not unreasonably impact any neighbor by blocking windows or the like.
- D. Privacy fences allowed by the Commission should be landscaped where practical with appropriate shrubbery to soften the appearance of the fence.
- 4. The following criteria shall be considered, when relevant, by the Commission in reviewing applications for a Certificate of Appropriateness. All applications for Certificates of Appropriateness shall be subject to review based upon the Design Guidelines then in effect. These guidelines are set forth in a manual prepared and adopted by the Commission:
  - lot coverage, defined as the percentage of lot area covered by primary structures;
  - setback, defined as the distance from the lot lines to the building(s);
  - building height;
  - exterior building materials;
  - proportion, shape, positioning, location, pattern and sizes of any elements of fenestration;
  - surface textures;
  - structural condition and soundness;
  - walls--physical ingredients, such as brick, stone or wood walls, wrought iron fences, evergreen landscape masses, building facades, or combination of these;
  - color (new construction only and not for existing residences); and
  - effect of trees and other landscape elements.
- 5. The application is congruous with the historic aspects of the District.
- 6. Based on the standards of the Handbook, and the City of Concord Code of Ordinances, including the standards listed above, the Commission concludes that:
- There was sufficient evidence presented to reopen the prior approval and approve the "ex post facto" request for after-the-fact approval to increase the height of the fence running adjacent to Franklin Ave NW from 4.0' to 6.0' is appropriate as the wooden fence is visible from the street and is located in the rear yard and therefore may be higher than 4.0', and is in compliance with the Historic Handbook.

There was insufficient evidence presented to reopen the prior approval as to the fence color and the Commission did not vote to amend the fence color that was initially approved in Case H-04-21 on April 14, 2021.

Commissioner Barbee made a motion to approve the ex post facto Certificate of Appropriateness in respect to the fence height and to allow the Chairman to sign the Order out of session. Commissioner Firth seconded the motion. The vote carried. –**The Vote: All Ayes (APPROVED)** 

Commissioner Underwood made a motion to reopen the quasi-judicial hearing with respect to the painting of the fence. Commissioner Firth seconded the motion. The vote carried. –**The Vote: Yays -2; Nays -2** The motion fails.

Commissioner Barbee made a motion to not reopen the quasi-judicial hearing with respect to the fence paint color because there has been no testimony or evidence that are in the record regarding a change of circumstance or new evidence. Chair Isenhour seconded the motion. The vote carried. –**The Vote: Yays** -2; Nays -2 The motion fails.

Attorney Merritt explained that it fails and they can appeal.

Attorney Merritt explained that the motion failed on a two to two vote, therefore the Commission will not consider the reopening the application relative to the paint color, and as a result, the application to amend the paint color is not approved. Attorney Merritt stated that there is no reason to make findings of fact or conclusions of law because the item was not reopened.

### H-15-21 (QUASI-JUDICIAL HEARING) STC COLEMAN MILL, LLC, HAS SUBMITTED A CERTIFICATE OF APPROPRIATENESS APPLICATION TO RENOVATE AND REPURPOSE THE EXISTING COLEMAN MILL BUILDINGS INTO APARTMENT UNITS AT 625 MAIN ST. SW. PIN 5529-69-3574.

Scott Sherrill introduced the case to the Commission.

Full background on authority as well as the relevant standards for review are encompassed in the materials from Case H-23-18, which was considered with a preliminary endorsement, but no COA, by the Historic Preservation Commission on August 8, 2018. The full staff report from that case is included as Exhibit G of this staff report. This staff report highlights the evolution of the project from the initial COA request, through rezoning, and technical site and building reviews. There are enough details and modifications from the original that a new COA request is merited. It should be noted that labels on the fenestration exhibits in Exhibit G are misleading with regard to which side of the building is being discussed.

Coleman Mill last came before the Historic Preservation Commission on August 8, 2018, for a COA for the conversion (Case H-23-18). Following the consideration by the Historic Preservation Commission, it proceeded to a rezoning hearing, which was considered by the Planning and Zoning Commission on April 16, 2019 as Case Z(CD)-16-18. The project has been in Technical Review since June of 2021, and also pursued a variance request from CDO Section 4.3.2. regarding buffer and setback widths, Section 10.3.1.C.1.b. for parking within the front yard setback, and from Technical Standards Manual Article 3, Section 16 for Driveways General Design Standards: the variance request was granted on January 25, 2022 by the Board of Adjustment. The applicant was notified that modifications to building design would require returning to the Historic Preservation Commission during the first round of building plan review in August of 2021 due to deviations from the 2018 Certificate of Appropriateness, and submitted a Certificate of Appropriateness Application on October 1, 2021. The application was subsequently revised on November 8, 2022 to reflect a more accurate scope of work after the securing of National Park Service conditional approval as a tax credit project.

The scope of work requested includes the following overall project description as set forth by the applicant, with analysis regarding changes from prior approvals indicated in *italics*:

# **Overall Project Description**

The proposed is the adaptive reuse of the Coleman Mill into a 150 unit affordable housing project for family tenants. The property is listed on the National Register of Historic Places.

#### When first considered in Case H-23-18, 156 units were proposed, and 151 units in Z(CD)-16-18.

The community will have 150 LIHTC units between two buildings and covered parking in a third building. The units are comprised of 36 efficiency, 41 one bedroom, 60 two bedroom, and 13 three bedroom units. Sixteen (16) units will be fully accessible for the mobility impaired, eight (8) of those will have roll in showers. All apartments will fully meet or exceed the NCHFA design guidelines for amenities and quality of apartment design.

The development will have the three (3) QAP required tenant amenities as shown on the site plan, namely the Covered Picnic Area with 150 sf and 2 tables and 2 grills. Multi-Purpose Room (250 sq. ft.), and Playground. The three (3) additional amenities include: an Exercise Room, a Computer Room (with a minimum of 2 computers), and Outdoor Sitting Areas (min 3 locations).

Case H-23-18 reflected a pool, but no playground in addition to structured and podium parking with significant impact to the stream. The zoning plan for Z(CD)-16-18 reflected no additional buildings or parking across the stream, unless the railroad began use of more of its right of way, but amenities were reflected: playground, multi-purpose room, covered picnic area, swimming pool, exercise room, and resident computer center. The swimming pool was removed from the technical site plan to provide adequate fire access.

All community and common areas will be fully accessible to those with disabilities. Parking will be 1.75 spaces per LIHTC unit. ADA parking will be provided as required. Landscaping will meet or exceed both NCH FA and the Town of Concord's standards and be well maintained.

The National Park Service noted that: "New landscape features and improvements must be compatible with the historic industrial character of the complex. Landscaping must be held close to the ground and not overwhelm the industrial character of the historic buildings and site, which was generally without landscaping historically. The three proposed oak trees that abut the main mill building (Hold response received on February 16, 2022) do not meet the Standards and should not be planted. The proposed landscaping along the Main Mill Building should be minimal and remain low to the ground. Trees may be planted in the parking lot but should be away from the mill and warehouse. A revised landscaping plan must be submitted for review and approval by the SHPO and NPS." The applicant has submitted a revised landscape plan to the National Park Service for review, and it is included among the selections from the site plan (Exhibit D).

# Site Work

• Remove all debris and extraneous material from site *No impact from a Certificate of Appropriateness perspective.* 

• Seal and restripe existing parking lot per site plan. Add new paving as shown. Sealing and restriping has no impact from a Certificate of Appropriateness perspective. The new paving is less impactful across the stream than what was shown in H-23-18, and ultimately shows a reduction from 4.528 acres of impervious to 4.512 acres of impervious.

• Install new pole-mounted site lights throughout the property including the parking areas *The materials submitted for H-23-18 did not include details on site lighting. No lighting plan was provided with Z(CD)-16-18 either. A lighting plan has been submitted with the building plan, which is included in Exhibit E (Sheet SA.01 from PRB2021-02298).* 

• Create new screened dumpster pad and enclosure

H-23-18 reflected a trash enclosure roughly within the existing stream on site. Z(CD)-16-18 did not reflect the dumpster enclosures. The site plan reflected concrete pads, but no dumpsters specifically. The building plan architectural site plan reflects two dumpster locations: one on the street side of the West Warehouse, and the other towards the railroad tracks from the main mill building in the railroad right of way. The applicant is reflecting a brick dumpster screen on sheet SA.04 in Exhibit E.

• Add new native landscaping, as well as new walkways, and planting beds. Repair and replace damaged sidewalks where necessary.

See note under overall project description. The applicant has submitted a revised landscaping plan to the NPS for review; the file has been sent to the City Arborist for comment, and additional information will be provided at the hearing.

• Provide new handicap-accessible ramp at main front entrance.

The handicap ramp was not shown in case H-23-18, nor Z(CD)-16-18. The technical site plan reflects handicap parking and ramps along the north and south sides of the buildings, the reference to main front entrance refers to the western entrance on the south side of the main mill building.

• Repair/replace existing storm drainage system to meet or exceed both state and local requirements. Provide positive drainage to meet or exceed NCH FA guidelines *The site plan is consistent with the variance case V-03-21. This level of detail was not provided in H-23-18 nor Z(CD)-16-18, but covered during technical site plan review.* 

• Achieve final grading, balancing cut and fill in newly graded and paved areas. The site plan is consistent with the variance case V-03-21. This level of detail was not provided in H-23-18 nor Z(CD)-16-18, but covered during technical site plan review.

# Demolition

Remove or abandon all existing mechanical, electrical, and plumbing equipment and fixtures
Remove noncontributing buildings from site pending full approval from NPS.

Main Mill East Façade: western appendage was proposed for removal in H-23-18; the appendage on the south west corner on the building appears to have been removed and is not shown on the existing floor plan in the building plans.

Main Mill South Façade: Four accessory structures dating from 1947-1950 were shown for demolition in Case H-23-18. Parking was proposed in the area in Case Z(CD)-16-18, and carried through to the Technical Site Plan and building plans. Several later appendages were also proposed for removal in Case H-23-18, and also carried through to Technical Site Plan and Building Plans. These appendages have not yet been removed.

Main Mill West Façade: No demolition shown.

Main Mill North Façade: 2 Existing ventilation rooms to be removed and one of three existing elevator shafts according to the building plans. Only existing ductwork was flagged in H-23-18; however, area was reflected as green space in Z(CD)-16-18, the technical site plan does not reflect removal of the ventilation rooms.

National Park Service Condition: "The two historic stair towers on the Main Mill building must be retained with the historic stairs intact."

West Warehouse: No specific demolition shown.

East Warehouse: No specific demolition shown.

# Utilities

• Remove any overhead electrical lines and install new underground electrical feed to each major building section

Not a significant impact for Certificate of Appropriateness review.

# **Building Exteriors**

• Replace all rotted wood trim to match existing profiles. Clean, scrape, and paint all wood trim *The National Park Service has added a condition stating: Replacement metal and wood siding on the East and West Cotton Warehouses must only be installed selectively, based on the condition of individual siding elements. Any replacement material must match the historic in visual appearance, exposure, and thickness. Documentation of the need for, and extent of, any siding replacement must be submitted for review and approval prior to the removal of the historic material.* 

• Repair original brick exteriors for minor cracks and clean all surfaces in accordance with the

Secretary of Interior's Standards for historic properties. Brick to be cleaned per NPS guidelines Based on the information provided, applicant is committing to following NPS guidelines for cleaning and repair.

• Windows vary from building to building and elevation to elevation. Remove infill masonry from existing window locations and install new historically compatible as necessary. New windows and locations for same are to be approved by NPS.

National Park Service Condition: "Many of the replacement windows and doors being proposed here are inappropriate for a piedmont textile mill of this age and style. In particular the following proposed windows and doors must be revised:

- The 1912 addition to the main mill would not likely have had 4 over 1 windows. Instead, narrow, multi-lite steel windows were more probably employed.
- Fully glazed entry doors are also problematic. Double-leaf entry doors would have been wooden doors with floating panels, and, at most, glazing held to the top third of each slab.
- The new windows along the first floor of the west warehouse must reflect the industrial character of the warehouse and not resemble residential hung windows.

Replacement window and door details must either be substantiated by documentary evidence (e.g. historic photographs or extant windows) or better conform to standard details seen on historic mills elsewhere in the region. To ensure all replacement windows and doors meet the Standards, detailed and dimensioned drawings of all proposed replacement units (Main Mill, West Warehouse, East Warehouse), once selected and finalized, must be submitted for review. Drawings should illustrate the windows in relationship to the wall assembly, and must include elevations as well as sill, jamb, head, meeting rail, and muntin details. Simulated divided light windows must have muntin grids installed on the exterior, interior, and feature spacers bars or equivalent separations between the glass.

H-23-18 reflected only six over six windows. The building plans reflect replica windows on the west main mill elevation, except on the southern side, where six over six windows are still reflected. On the south elevation, new 8-light center divide windows are now reflected on the western half of the elevation, with replica windows on the eastern side. The north elevation reflects replica windows on the eastern portion of the elevation with 8 light center divide windows of varying sizes on the two-thirds of the façade, generally.

On the west warehouse, west side fenestrations on the upper level do not appear to change. There are six new lower level window and two door openings and two existing doors are proposed to be fixed in place. On the south side, 11 new windows are proposed, three closed window openings will be reestablished, and one new door opening would be added. This is a greater level of detail than was provided on H-23-18. On the east side, six new windows would be added. The north elevation 20 new windows and two doors are proposed for addition.

On the east warehouse, one new door is being added to the west façade, two garage doors are being added on the south elevation, no changes are proposed on the north elevation or the east elevation.

• Replace/repair roof with compatible materials consistent with the Secretary of the Interior's standards

The National Park Service has added a condition stating: Replacement metal and wood siding on the East and West Cotton Warehouses must only be installed selectively, based on the condition of individual siding elements. Any replacement material must match the historic in visual appearance, exposure, and thickness. Documentation of the need for, and extent of, any siding replacement must be submitted for review and approval prior to the removal of the historic material.

# **Building Interiors**

- Remove or abandon all electrical equipment, wiring, and fixtures
- Remove or abandon all mechanical equipment and ductwork

National Park Service Condition: "New mechanical, electrical, and plumbing systems must be installed in a manner that has minimal effect on the historic character of the building. Exposed systems must be sized and located to minimize their visual impact and be held back from the windows an adequate distance to avoid a noticeable impact from the building's exterior. Systems may be installed above lowered ceilings in secondary spaces such as bathrooms and closets. In order to ensure the installation of the systems meets the Standards, details of the location, size, and concealment or finish of the ductwork and utility lines, ideally in the form of mechanical drawings and reflected ceiling plans, must be submitted for review.

- Original walls to be exposed and repaired.
- Where possible, original doors to be sanded, refinished, and reused.
- Repair all existing wood floors where salvageable. In areas where the wood floor cannot be repaired, install new wood, carpet, or vinyl

Interior details were not available at the time of H-23-18, although a floor plan was provided. Over the revisions, the floor plan and arrangement has changed substantially and many more details have been made available regarding finishes.

National Park Service Condition: Interior architectural finishes, consisting of the wood floors in the Main Mill Building and concrete floors in the West Warehouse, must be preserved where they existed historically. Some carpeting or LVT is acceptable in secondary spaces, such as bathroom and bedrooms in residential units.

National Park Service condition: Main Mill Building Ceilings: Interior architectural finishes, such as the exposed ceilings, must be preserved. The exposed wooden beams must still be expressed in the individual units and corridors. If necessary for fire code protection, gypsum board may be placed between the beams held tight to the wood planking above. On the third floor, there must not be gypsum board ceilings and the historic structure must be fully exposed. Photographs showing the historic fabric preserved in place must be submitted with the Request for Certification of Completed Work.

The building plans reflect two typical finishes for the main mill building: on the first floor existing concrete, with carpet in bedrooms; where wood floor is present on the first, second, and third floor, carpet would go on the existing wood floor in the bedrooms, and stone patterned LVT in bathrooms. In the western part of the main mill building, existing creosote contaminated wood would be removed and replaced with a 4" concrete slab. For residential units in the west warehouse, concrete would be in most living areas, with carpet on existing concrete in bedrooms.

- Refinish hard wood flooring in new corridors where present otherwise install VCT in corridors
- Laundry rooms to have VCT tile floors and eight (8) sets of washer and dryers (1 set per 20 units)
- Construct tenant storage areas as appropriate, provide 1 storage unit per residential unit with 16 unobstructed sq. ft. and min 36 inch in depth will be provided.
- Install ramps and elevators to provide accessible route as shown on plans
- Install fire suppression system per international fire code
- Install 2 passenger elevator.
- Community interior amenities will be added; Community Room with kitchenette, Management Office, Exercise Room, and Computer Lab

National Park Service Condition: The historic utilitarian character of the West Warehouse (exposed wood siding, brick knee walls, brick demising walls, concrete floors, exposed beams and decking) must be retained to the maximum amount possible. First floor units must retain the historic flooring and mimic the unfinished surfaces on the exterior walls. In order to ensure that the proposed interior finishes in the West Warehouse meet the Standards, a detailed finish schedule (including product specs, texture, and color) must be reviewed and approved by both the SHPO and NPS before proceeding with this work.

# **Unit Construction**

- All units to be constructed in accordance with NCHFA Design Standard and Building Codes in effect in Concord
- Install new interior partitions. Wall construction to be 2x4 wood studs with S/8" gypsum board. Tenant demising walls to be 2x6 studs with insulation and 5/8" fire rated gypsum board
- Refinish existing wood floors in living and dining rooms. Install carpet in bedrooms
- Install new VCT tile flooring in kitchen and bathrooms where existing wood floors cannot be saved
- Install kitchen cabinetry with wood face cabinets and plastic laminate tops. Install new Energy Star rated refrigerators and dishwashers. Install sinks, disposal units, and ranges with hoods vented to the exterior
- In bathrooms, provide mirror that extends down to backsplash and medicine cabinet
- Provide new lever type door hardware and install new deadbolts and peep holes on all unit entry doors. Entry door to be solid core wood door with a painted finish
- All interior doors to be panel hardboard doors with paint finish
- Install mini-blinds on all apartment windows to achieve uniform appearance from street
- All interior trim to be painted wood
- Install wood-blocking for future grab bars in bathroom locations as required by Accessibility Code

See NPS Conditions with regard to Building Interiors.

# Mechanical, Electrical, and Plumbing

- Install new electrical system from new meter bases and panels to new outlets, switches and lights, with ceiling fans in living rooms and bedrooms.
- Provide a light fixture at each unit entry inside corridor
- Provide lighting package that meets or exceeds NCHFA building guidelines
- Provide monitored system for fire suppression systems
- Install new electric water heater with an Energy Factor of at least .95 for each apartment
- Install new plumbing supply and waste lines from the service entrance
- Install new low-flow, EPA "Watersense" rate shower heads and faucets. Provide lever faucet controls for all kitchen and bathroom sinks
- Install new split system heat pump HVAC units for each apartment.
- Mechanically ventilate all bathrooms with externally vented Energy Star rated exhaust fans at 90 CCFM. Fans are to be wired to run whenever bathroom light is on

• Install venting to the outside for range hoods

National Park Service Condition: "New mechanical, electrical, and plumbing systems must be installed in a manner that has minimal effect on the historic character of the building. Exposed systems must be sized and located to minimize their visual impact and be held back from the windows an adequate distance to avoid a noticeable impact from the building's exterior. Systems may be installed above lowered ceilings in secondary spaces such as bathrooms and closets. In order to ensure the installation of the systems meets the Standards, details of the location, size, and concealment or finish of the ductwork and utility lines, ideally in the form of mechanical drawings and reflected ceiling plans, must be submitted for review.

Jared Burgess, 10710 Sunderland Road Louisville, KY spoke regarding the request. Mr. Burgess stated that his architect was available to answer any technical questions. He stated that they have put forth their best effort to the City of Concord's preservation standards, and National Park Service and North Carolina State Historic Preservation Office (SHPO).

Chair Isenhour stated that he is happy this project is progressing.

Commissioner Barbee made a motion to close the public hearing. Commissioner Firth seconded the motion. The vote carried unanimously. **–The Vote: All Ayes** 

Commissioner Barbee made a motion to approve the Findings of Fact. Commissioner Underwood seconded the motion. The vote carried unanimously. –**The Vote: All Ayes** 

# FINDINGS OF FACT:

- 1. The subject property is located at 625 Main St SW, Concord, NC. The owner is Bryton Partners, LLC. Bryton Partners, LLC acquired the property by deed recorded in Cabarrus County Register of Deeds Book 12825, Page 137, as recorded on December 28, 2017.
- 2. The subject property is located in the RC-CD (Residential Compact-Conditional District) zoning district and is a local landmark (Exhibit B).
- 3. The subject property is designated as the Coleman-Franklin-Cannon Mill on the National Register (Exhibit G.A).
- 4. The Handbook is an ordinance of the City of Concord duly adopted by the City Council and incorporated into the Code of Ordinances by reference.
- 5. On October 1, 2021, Martin Riley Associates, Leigh Gomez submitted an application for a Certificate of Appropriateness under Concord Development Ordinance (CDO) §9.8 for a proposed adaptive reuse of the Coleman Mill into a 156 unit affordable housing project for family tenants; this original application was not included with the staff report, but a revised application and scope of work was submitted by STC Coleman Mill, LLC on November 8, 2022 (Exhibit A) for 150 units.
- 6. City Staff provided selections from the applicant's Technical Site Plans for case PRS2021-01908 (Exhibit D)
- 7. City Staff provided selections from the applicant's Building Plans for case PRB2021-02298 (Exhibit E).
- 8. Staff provided photographs from Case H-23-18 (Exhibit G.E.)
- 9. The applicant provided conditional approval documentation from the National Park Service and their consultant response memorandum (Exhibit C).
- 10. The Commission considered Preservation Brief 18 (Exhibit G).

Commissioner Barbee made a motion to approve the Conclusions of Law as amended. Commissioner Underwood seconded the motion. The vote carried unanimously. –**The Vote: All Ayes** 

#### **CONCLUSIONS OF LAW:**

- 6. This matter is properly before the Commission pursuant to N.C. Gen. Stat. § 160A-400.7, et seq. and the Concord Development Ordinance.
- 7. Pursuant to the <u>LLD-01-17 Local Designation Ordinance (18-01)</u>, and Appendix A from the *Historic District Handbook*:
  - Commission Hearing and Approval Required For: modifications that impact, affect, or obscure architectural or layout details as set forth in the landmark report and supplementary materials. The local landmark designation encompasses the site, building exteriors of all contributing structures as established in the National Register Nomination for the Coleman-Franklin-Cannon Mill (November 2014), and the building interior of the Coleman-Franklin-Cannon Mill, 1898, 1912, 1950s, 1960s Contributing Building, East Cotton Warehouse 1902, 1912, 1926 Contributing Building, and West Cotton Warehouse 1927-1938 Contributing Building.
  - A property shall be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces, and spatial relationships.
  - The historic character of a property shall be retained and preserved. The removal of distinctive materials or alteration of features, spaces and spatial relationships that characterize a property shall be avoided.
  - Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or elements from other historic properties, shall not be undertaken.
  - Changes to a property that have acquired historic significance in their own right shall be retained and preserved.
  - Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a property shall be preserved.
  - Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and where possible, materials. Replacement of missing features shall be substantiated by documentary and physical evidence.
  - Chemical or physical treatments, if appropriate, shall be undertaken using the gentlest means possible. Treatments that cause damage to historic materials shall not be used.
  - Archeological resources shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.

- New additions, exterior alterations, or related new construction shall not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and shall be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.
- New additions and adjacent or related new construction shall be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.
- The guidance that is basic to the treatment of all historical buildings **identifying**, **retaining**, **preserving** the form and detailing of those architectural materials and features that are important in defining the historic character is always listed in the "Recommended" column. The parallel "Not Recommended" column lists the types of actions that are most apt to cause the diminution or even loss of the building's historic character. It should be remembered, however, that such loss of character is just as often caused by the cumulative effect of a series of actions that would seem to be minor interventions. Thus, the guidance in all of the "Not Recommended" columns must be viewed in that larger context, e.g. for the total impact on a historic building.

### <u>Masonry</u>

Recommended: Identifying, retaining, and preserving masonry features that are important in defining the overall historic character of the building such as walls, brackets, railings, cornices, window architraves, door pediments, steps, and columns; and joint and unit size, tooling and bonding patterns, coatings, and color.

Recommended: Protecting and maintaining masonry by providing proper drainage so that water does not stand on flat, horizontal surfaces or accumulate in curved decorative features.

Recommended: Cleaning masonry only when necessary to halt deterioration or remove heavy soiling.

Recommended: Carrying out masonry surface cleaning tests after it has been determined that such cleaning is necessary. Tests should be observed over a sufficient period of time so that both the immediate effects and the long-range effects are known to enable selection of the gentlest method possible.

Recommended: Cleaning masonry surfaces with the gentlest method possible, such as low-pressure water and detergents, using natural bristle brushes.

Recommended: Evaluating the overall condition of the masonry to determine whether more than protection and maintenance are required, that is, if repairs to the masonry fence will be necessary.

Recommended: **Repairing** masonry walls and other masonry features by repointing the mortar joints where there is evidence of deterioration such as disintegrating mortar, cracks in mortar joints, loose bricks, damp walls, or damaged plaster work.

Recommended: Removing deteriorated mortar by carefully hand-raking the joints to avoid damaging the masonry.

Recommended: Duplicating old mortar in strength, composition, color, and texture.

Recommended: Duplicating old mortar joints in width and in joint profile.

Recommended: Repairing masonry features by patching, piecing-in, or consolidating the masonry using recognized preservation methods. Repair may also include the limited replacement in kind – or with compatible substitute material of those extensively deteriorated or missing parts of masonry features when there are surviving prototypes such as terra-cotta brackets or stone balusters.

Recommended: Applying new or non-historic surface treatment such as water-repellent coatings to masonry only after repointing and only if masonry repairs have failed to arrest water penetration problem.

Recommended: Replacing in kind an entire masonry feature that is too deteriorated to repair – if the overall form and detailing are still evident – using the physical evidence to guide the new work. Examples can include large sections of a wall, a cornice, balustrade, column, or stairway. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Recommended: Designing and installing a new masonry feature such as steps or a door pediment when the historic feature is completely missing. It may be an accurate restoration using historical, pictorial, and physical documentation; or be a new design that is compatible with the size, scale, material, and color of the historic building.

Not recommended: Removing or radically changing masonry features which are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Not recommended: Replacing or rebuilding a major portion of the exterior masonry walls that could be repaired so that, as a result, the building is no longer historic and is essentially new construction.

Not recommended: Applying paint or other coatings such as stucco to masonry that has been historically unpainted or uncoated to create a new appearance.

Not recommended: Failing to evaluate and treat the various causes of mortar joint deterioration such as leaking roofs or gutters, differential settlement of the building, capillary action, or extreme weather exposure.

Not recommended: Cleaning masonry surfaces when they are not heavily soiled to create a new appearance, thus needlessly introducing chemicals or moisture into historic materials.

Not recommended: Cleaning masonry surfaces without testing or without sufficient time for testing to be of value.

Not recommended: Sandblasting brick or stone surfaces using dry or wet grit or other abrasives. These methods of cleaning permanently erode the surface of the material and accelerate deterioration.

Not recommended: Using a cleaning method that involves water or liquid chemical solutions when there is any possibility of freezing temperatures.

Not recommended: Cleaning with chemical products that will damage masonry, such as using acid on limestone or marble, or leaving chemicals on masonry surfaces.

Not recommended: Applying high pressure water cleaning methods that will damage historic masonry and the mortar.

Not recommended: Failing to undertake adequate measures to assure the preservation of masonry features.

Not recommended: Removing undeteriorated mortar from sound joints, then repointing the entire building to achieve a uniform appearance.

Not recommended: Using electric saws and hammers rather than hand tools to remove deteriorated mortar from joints prior to repointing.

Not recommended: Repointing with mortar of high Portland cement content (unless it is the content of the historic mortar). This can often create a bond that is stronger than the historic material and can cause damage as a result of the differing coefficient of expansion and the differing porosity of the material and the mortar.

Not recommended: Repointing with a synthetic caulking compound.

Not recommended: Using a "scrub" coating technique to repoint instead of traditional repointing methods.

Not recommended: Changing a width or joint profile when repointing

Not recommended: Replacing an entire masonry feature such as a cornice or balustrade when repair of the masonry and limited replacement of deteriorated or missing parts are appropriate.

Not recommended: Using a substitute material for the replacement part does not convey the visual appearance of the surviving parts of the masonry feature or that is physically or chemically incompatible.

Not recommended: Applying waterproof, water-repellant, or non-historic coatings such as stucco to masonry as a substitute for repointing and masonry repairs. Coatings are frequently unnecessary, expensive, and may change the appearance of historic masonry as well as accelerated its deterioration.

Not recommended: Removing a masonry feature that is unrepairable and not replacing it; or replacing it with new feature that does not convey the same visual appearance.

Not recommended: Creating a false historical appearance because the replaced masonry feature is based on insufficient historical, pictorial, and physical documentation.

Not recommended: Introducing a new masonry feature that is incompatible in size, scale, material, and color.

#### Wood

Recommended: **Identifying, retaining, and preserving** wood features that are important in defining the overall historic character of the building such as siding, cornices, brackets, window architraves, and doorway pediments; and their paints, finishes, and colors.

Recommended: **Protecting and maintaining** wood features by providing proper drainage so that water is not allowed to stand on flat, horizontal surfaces or accumulate in decorative features.

Recommended: Applying chemical preservatives to wood features such as beam ends or outriggers that are exposed to decay hazards and are traditionally unpainted.

Recommended: Retaining coatings such as paint that help protect the wood from moisture and ultraviolet light. Paint removal should be considered only where there is paint surface deterioration and as part of an overall maintenance program which involves repainting or applying other appropriate protective coatings.

Recommended: Inspecting painted wood surfaces to determine whether repainting is necessary or if cleaning is all that is required.

Recommended: Removing damaged or deteriorated paint to the next sound layer using the gentlest method possible (hand scraping and hand sanding), then repainting.

Recommended: Using with care electric hot-air guns on decorative wood features and electric heat plates on flat wood surfaces when paint is so deteriorated that total removal is necessary prior to repainting.

Recommended: Using chemical strippers primarily to supplement other methods such as hand scraping, hand sanding and the above-recommended thermal devices. Detachable wooden elements such as shutters, doors, and columns may – with the proper safeguards be chemically dip-stripped.

Recommended: Applying compatible paint coating systems following proper surface preparation.

Recommended Repainting with colors that are appropriate to the historic building and district.

Recommended: Evaluating the overall condition of the wood to determine whether more than protection and maintenance are required, that is, if repairs to wood features will be necessary.

Recommended: **Repairing** wood features by patching, piecing-in, consolidating, or otherwise reinforcing the wood using recognized preservation methods. Repair may also include the limited replacement in kind or with compatible substitute material of those extensively deteriorated or missing parts of features where there are surviving prototypes such as brackets, moldings, or sections of siding.

Recommended: **Replacing** in kind an entire wood feature that is too deteriorated to repair if the overall form and detailing are still evident – using the physical evidence to guide the new work. Example of wood features include a cornice, entablataure or balustrade. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Not recommended: Removing or radically changing wood features which are important in defining the overall character of the building so that, as a result, the character is diminished.

Not recommended: Removing a major portion of the historic wood instead of repairing or replacing only the deteriorated wood, then reconstructing the facade with new material in order to achieve a uniform or "improved" appearance.

Not recommended: Radically changing type of finish or its color or accent scheme so that the historic character of the exterior is diminished.

Not recommended: Stripping historically painted surfaces to bare wood, then applying clear finishes or stains in order to create a "natural look."

Not recommended: Stripping paint or varnish to bare wood rather than repairing or reapplying a special finish, i.e., a grained finish to an exterior wood feature such as a front door.

Not recommended: Failing to identify, evaluate, and treat the causes of wood deterioration, including faulty flashing, leaking gutters, cracks and holes in siding, deteriorated caulking in joints and seams, plant material growing too close to wood surfaces, or insect or fungus infestation.

Not recommended: Using chemical preservatives such as creosote which can change the appearance of wood features unless they were used historically.

Not recommended: Stripping paint or other coatings to reveal bare wood, thus exposing historically coated surfaces to the effects of accelerated weathering.

Not recommended: Removing paint that is firmly adhering to, and thus, protecting wood surfaces.

Not recommended: Using destructive paint removal methods such as a propane or butane torches, sandblasting or waterblasting. These methods can irreversibly damage historic woodwork.

Not recommended: Using thermal devices improperly so that the historic woodwork is scorched.

Not recommended: Failing to neutralize the wood thoroughly after using chemicals so that new paint does not adhere.

Not recommended: Allowing detachable wood features to soak too long in a caustic solution so that the wood grain is raised and the surface roughened.

Not recommended: Failing to follow manufacturers' product and application instructions when repainting exterior woodwork.

Not recommended: Using new colors that are inappropriate to the historic building or district.

Not recommended: Failing to undertake adequate measures to assure the preservation of wood features.

Not recommended: Replacing an entire wood feature such as a cornice or wall when repair of the wood and limited replacement of deteriorated or missing parts are appropriate.

Not recommended: Using substitute materials for the replacement part that does not convey the visual appearance of the surviving parts of the wood feature or that is physically or chemically incompatible.

Not recommended: Removing an entire wood feature that is unrepairable and not replacing it; or replacing it with a new feature that does not convey the same visual appearance.

#### Architectural Metals

Recommended: **Identifying, retaining, and preserving** architectural metal features such as columns, capitals, window hoods, or stairways that are important in defining the overall historic character of the building; and their finishes and colors.

Recommended: **Protecting and maintaining** architectural metals by providing proper drainage so that water does not stand on flat, horizontal surfaces or accumulate in curved decorative features.

Recommended: Cleaning architectural metals, when necessary, to remove corrosion prior to repainting or applying other appropriate protective coatings.

Recommended: Identifying the particular type of metal prior to any cleaning procedure and then testing to assure that the gentlest cleaning method possible is selected or determining that cleaning is inappropriate for the particular metal.

Recommended: Cleaning soft metals such as lead, tin, copper, terneplate, and zinc with appropriate chemical methods because their finishes can be easily abraded by blasting methods.

Recommended: Using the gentlest cleaning methods for cast iron, wrought iron, and steel – hard metals – in order to remove paint, build up and corrosion. If hand scraping and wire brushing have proven ineffective, low pressure dry grit blasting may be used as long as it does not abrade or damage the surface.

Recommended: Applying appropriate paint or other coating systems after cleaning in order to decrease the corrosion rate of metals or alloys.

Recommended: Repainting with colors that are appropriate to the historic building or district.

Recommended: Applying an appropriate protective coating such as lacquer to an architectural metal such as a bronze door which is subject to heavy pedestrian use.

Recommended: Evaluating the overall condition of the architectural metals to determine whether more than protection and maintenance are required, that is, if repairs to the features will be necessary.

Recommended: **Repairing** architectural metal features by patching, splicing, or otherwise reinforcing the metal using recognized preservation methods. Repair may also include the limited replacement in kind – or with compatible substitute material – of those extensively deteriorated or missing parts of features where there are surviving prototypes such as porch balusters, column capitals or bases, or porch cresting.

Recommended: **Replacing** in kind an entire architectural metal feature that is too deteriorated to repair – if the overall form and detailing are still evident – using the physical evidence to guide the new work. Examples could include cast iron porch steps or steel sash windows. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Not recommended: Removing or radically changing architectural metal features which are important in defining the overall character of the building so that, as a result, the character is diminished.

Not recommended: Removing a major portion of the historic architectural metal instead of repairing or replacing only the deteriorated metal, then reconstructing the facade with new material in order to achieve a uniform or "improved" appearance.

Not recommended: Radically changing the type of finish or its historic color or accent scheme.

Not recommended: Failing to identify, evaluate, and treat the causes of corrosion, such as moisture from leaking roofs or gutters.

Not recommended: Placing incompatible metals together without providing a reliable separation material. Such incompatibility can result in galvanic corrosion of the noble metal, e.g. copper will corrode cast iron, steel, tin, and aluminum.

Not recommended: Exposing metals which were intended to be protected from the environment.

Not recommended: Applying paint or other coatings to metals such as copper, bronze, or stainless steel that were meant to be exposed.

Not recommended: Using cleaning methods which alter or damage the historic color, texture, and finish of the metal.

Not recommended: Removing the patina of historic metal. The patina may be a protective coating on some metals, such as bronze or copper, as well as a significant historic finish.

Not recommended: Cleaning soft metals such as lead, tin, copper, terneplate, and zinc with grit blasting which will abrade the surface of the metal.

Not recommended: Failing to employ gentler methods prior to abrasively cleaning cast iron, wrought iron or steel; or using high pressure grit blasting.

Not recommended: Failing to re-apply protective coating systems to metals or alloys that require them after cleaning so that accelerated corrosion occurs.

Not recommended: Using new colors that are inappropriate to the historic building or district.

Not recommended: Failing to assess pedestrian use or new access patterns so that architectural metal features are subject to damage by use or inappropriate maintenance such as salting adjacent sidewalks.

Not recommended: Failing to undertake adequate measures to assure the preservation of architectural metal features.

Not recommended: Replacing an entire architectural metal feature such as a column or a balustrade when repair of the metal and limited replacement of deteriorated or missing parts are appropriate.

Not recommended: Using a substitute material for the replacement part that does not convey the visual appearance of the surviving parts of the architectural metal feature or that is physically or chemically incompatible.

Not recommended: Removing an architectural metal feature that is unrepairable and not replacing it; or replacing it with a new architectural metal feature that does not covey the same visual appearance.

# <u>Roofs</u>

Recommended: **Identifying, retaining, and preserving** roofs- and their functional and decorative features- that are important in defining the overall historic character of the building. This includes the roofs' shape, such as hipped, gambrel, and mansard; decorative features such as cupolas, cresting, chimneys, and weathervanes; and roofing material such as slate, wood, clay tile, and metal, as well as its color, and patterning.

Recommended: **Protecting and maintaining** a roof by cleaning the gutters and downspouts and replacing deteriorated flashing. Roof sheathing should also be checked for proper venting to prevent moisture condensation; and to ensure that materials are free from insect infestation.

Recommended: Providing adequate anchorage for roofing material to guard against wind damage and moisture penetration.

Recommended: Protecting a leaking roof with plywood and building paper until it can be properly repaired.

Recommended: **Repairing** a roof by reinforcing the historic materials which comprise roof features. Repairs will also generally include the limited replacement in kind – or with compatible substitute material – of those extensively deteriorated or missing parts of features when there are surviving prototypes such as cupola louvers, dentils, dormer roofing; or slates, tiles, or wood shingles on a main roof.

Recommended: **Replacing** in kind an entire feature of the roof that is too deteriorated to repair- if the overall form and detailing are still evident – using the physical evidence to guide the new work. Examples can include a large section of roofing, or a dormer or chimney. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Recommended: Installing mechanical and service equipment on the roof such as air conditioning, transformers, or solar collectors when required for the new use so that they are inconspicuous from the public right-of-way and do not damage or obscure character-defining features.

Recommended: Designing additions to roofs such as residential, office, or storage spaces; elevator housing; decks and terraces; or dormers or skylights when required by the new use so that they are inconspicuous from the public right-of-way and do not damage or obscure character-defining features.

Not recommended: Radically changing, damaging, or destroying roofs which are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Not recommended: Removing a major portion of the roof or roofing material that is repairable, then reconstructing it with new material in order to create a uniform, or "improved" appearance.

Not recommended: Changing the configuration of a roof by adding new features such as dormer windows, vents, or skylights so that the historic character is diminished.

Not recommended: Stripping the roof of sound historic material such as slate, clay tile, wood, and architectural metal.

Not recommended: Applying paint or other coatings to roofing material which has been historically uncoated.

Not recommended: Failing to clean and maintain gutters and downspouts properly so that water and debris collect and cause damage to roof fasteners, sheathing, and underlying structure.

Not recommended: Allowing roof fasteners, such as nails and clips to corrode so that roofing material is subject to accelerated deterioration.

Not recommended: Permitting a leaking roof to remain unprotected so that accelerated deterioration of historic building materials- masonry, wood, plaster, paint and structural members – occurs.

Not recommended: Replacing an entire roof feature such as a cupola or dormer when repair of the historic materials and limited replacement of deteriorated or missing parts are appropriate.

Not recommended: Using a substitute material for the replacement part that does not convey the visual appearance of the surviving parts of the roof or that is physically or chemically incompatible.

Not recommended: Removing a feature of the roof that is unrepairable, such as a chimney or dormer, and not replacing it; or replacing it with a new feature that does not convey the same visual appearance.

Not recommended: Installing mechanical or service equipment so that it damages or obscures characterdefining features; or is conspicuous from the public right of way. Not recommended: Radically changing a character-defining roof shape or damaging or destroying character-defining roofing material as a result of incompatible design or improper installation techniques.

### **Windows**

Recommended: **Identifying, retaining, and preserving** windows- and their functional and decorative features – that are important in defining the overall historic character of the building. Such features can include frames, sash, muntins, glazing, sills, heads, hoodmolds, panelled or decorated jambs and moldings, and interior and exterior shutters and blinds.

Recommended: **Protecting and maintaining** the wood and architectural metal which comprise the window frame, sash, muntins, and surrounds through appropriate surface treatments such as cleaning, rust removal, limited paint removal, and re-application of protective coating systems.

Recommended: Making windows weathertight by recaulking and replacing or installing weatherstripping. These actions also improve thermal efficiency.

Recommended: Evaluating the overall condition of materials to determine whether more than protection and maintenance are required, i.e. if repairs to windows and window features will be required.

Recommended: **Repairing** window frames and sash by patching, splicing, consolidating or otherwise reinforcing. Such repair may also include replacement in kind of those parts that are either extensively deteriorated or missing when there are surviving prototypes such as architraves, hoodmolds, sash, sills and interior or exterior shutters and blinds.

Recommended: **Replacing** in kind an entire window that is too deteriorated to repair – if the overall form and detailing are still evident – using the physical evidence to guide the new work. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Recommended: Designing and installing new windows when the historic windows (frame, sash and glazing) are completely missing. The replacement windows may be an accurate restoration using historical, pictorial, and physical documentation; or be a new design that is compatible with the new window openings and the historic character of the building.

Recommended: Designing and installing additional windows on rear and on other-non character defining elevations if required by the new use. New windows openings may also be cut into exposed party walls. Such design should be compatible with the overall design of the building, but not duplicate the fenestration pattern and detailing of a character-defining elevation.

Recommended: Providing a setback in the design of dropped ceilings when they are required for the new use to allow for the full height of the window openings.

Not recommended: Removing or radically changing windows which are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Not recommended: Changing the number, location, size or glazing pattern of windows, through cutting new openings, blocking-in windows, and installing replacement sash which does not fit the historic window opening.

Not recommended: Changing the historic appearance of windows through the use of inappropriate designs, materials, finishes, or colors which radically change the sash, depth of reveal, and muntin configuration; the reflectivity and color of the glazing; or the appearance of the frame.

Not recommended: Obscuring historic window trim with metal or other material.

Not recommended: Stripping windows of historic material such as wood, iron, cast iron, and bronze.

Not recommended: Failing to provide adequate protection of materials on a cyclical basis so that deterioration of the window results.

Not recommended: Retrofitting or replacing windows rather than maintaining the sash, frame, and glazing.

Not recommended: Failing to undertake adequate measures to assure the preservation of historic windows.

Not recommended: Replacing an entire window when repair of materials and limited replacement of deteriorated or missing parts are appropriate.

Not recommended: Failing to reuse serviceable window hardware such as brass lifts and sash locks.

Not recommended: Using a substitute material for the replacement part that does not convey the visual appearance of the surviving parts of the window or that is physically or chemically incompatible.

Not recommended: Removing a character-defining window that is unrepairable and blocking it in; or replacing it with a new window that does not convey the same visual appearance.

Not recommended: Creating a false historical appearance because the replaced window is based on insufficient historical, pictorial, and physical documentation.

Not recommended: Introducing a new design that is incompatible with the historic character of the building.

Not recommended: Installing new windows, including frames, sash, and muntin configuration that are incompatible with the building's historic appearance or obscure, damage, or destroy character-defining features.

Not recommended: Inserting new floors or furred-down ceilings which cut across the glazed areas of windows so that the exterior form and appearance of the windows are changed.

# **Entrances and Porches**

Recommended: **Identifying, retaining, and preserving** entrances – and their functional and decorative features – that are important in defining the overall historic character of the building such as doors, fanlights, sidelights, pilasters, entablatures, columns, balustrades, and stairs.

Recommended: **Protecting and maintaining** the masonry, wood, and architectural metal that comprise entrances and porches through appropriate surface treatments such as cleaning, rust removal, limited paint removal, and re-application of protective coating systems.

Recommended: Evaluating the overall condition of materials to determine whether more than protection and maintenance are required, that is, if repairs to entrance and porch features will be necessary.

Recommended: **Repairing** entrances and porches by reinforcing the historic materials. Repair will also generally include the limited replacement in kind – or with compatible substitute material – of those extensively deteriorated or missing parts of repeated features where there are surviving prototypes such as balustrades, cornices, entablatures, columns, sidelights, and stairs.

Recommended: **Replacing** in kind an entire entrance or porch that is too deteriorated to repair – if the overall form and detailing are still evident – using the physical evidence to guide the new work. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Recommended: Designing enclosures for historic porches when required by the new use in a manner that preserves the historic character of the building. This can include using large sheets of glass and recessing the enclosure wall behind existing scrollwork, posts, and balustrades.

Recommended: Designing and installing additional entrances or porches when required for the new use in a manner that preserves the historic character of the building, i.e., limiting such alteration to non-character-defining elevations.

Not recommended: Removing or radically changing entrances or porches which are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Not recommended: Stripping entrances and porches of historic material such as wood, iron, cast iron, terra cotta, tile and brick. Removing an entrance or porch because the building has been reoriented to accommodate a new use.

Not recommended: Cutting new entrances on a primary elevation.

Not recommended: Altering utilitarian or service entrances so they appear to be formal entrances by adding paneled doors, fanlights, and sidelights.

Not recommended: Failing to provide adequate protection to materials on a cyclical basis so that deterioration of entrances and porches results.

Not recommended: Failing to undertake adequate measures to assure the preservation of historic entrances and porches.

Not recommended: Replacing an entire entrance or porch when the repair of materials and limited replacement of parts are appropriate.

Not recommended: Using a substitute material for the replacement parts that does not convey the visual appearance of the surviving parts of the entrance and porch or that is physically or chemically incompatible.

Not recommended: Removing an entrance or porch that is unrepairable and not replacing it; or replacing it with a new entrance or porch that does not convey the same visual appearance.

Not recommended: Creating a false historical appearance because the replaced entrance or porch is based on insufficient historical, pictorial, and physical documentation.

Not recommended: Introducing a new design that is incompatible with the historic character of the building.

Not recommended: Enclosing porches in a manner that results in a diminution or loss of historic character such as using solid materials such as wood, stucco, or masonry.

Not recommended: Installing secondary service entrances and porches that are incompatible in size and scale with the historic building or obscure, damage, or destroy character-defining features.

### **Building Interior: Structural System**

Recommended: **Identifying, retaining, and preserving** structural systems- and individual features of systems that are important in defining the overall historic character of the building, such as post and beam systems, trusses, summer beams, vigas, cast iron columns, above grade stone foundation walls, or loadbearing brick or stone walls.

Recommended: **Protecting and maintaining** the structural system by cleaning the roof gutters and downspouts; replacing roof flashing; keeping masonry, wood, and architectural metals in a sound condition, and assuring that structural members are free from insect infestation.

Recommended: **Repairing** the structural systems by augmenting or upgrading individual parts or features. For example, weakened structural members such as floor framing can be spliced, braced, or otherwise supplemented and reinforced.

Recommended: **Replacing** in kind-or with substitute material-those portions or features of the structural system that are either extensively deteriorated or are missing when there are surviving prototypes such as cast-iron columns, roof rafters or trusses, or sections of loadbearing walls. Substitute material should convey the same form, design, and overall visual appearance as the historic features; and, at a minimum, be equal to its loadbearing capabilities.

Recommended: Examining and evaluating the physical condition of the structural system and its individual features using non-destructive techniques such as x-ray photography.

Recommended: Limiting any new excavations adjacent to historic foundations to avoid undermining the structural stability of the building or adjacent historic buildings.

Recommended: Correcting structural deficiencies in preparation for the new use in a manner that preserves the structural system and individual character-defining features.

Recommended: Designing and installing new mechanical or electrical systems when required for the new use which minimize the number of cutouts or holes in structural members.

Recommended: Adding a new floor when required for the new use if such an alteration does not damage or destroy the structural system or obscure, damage, or destroy character-defining spaces, features, or finishes.

Recommended: Creating an atrium or a light well to provide natural light when required for the new use in a manner that assures the preservation of the structural system as well as character-defining interior spaces, features, and finishes.

Not recommended: Removing, covering, or radically changing features of structural systems which are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Not recommended: Putting a new use into the building which could overload the existing structural system, or installing equipment or mechanical systems which could damage the structure.

Not recommended: Demolishing a loadbearing masonry wall that could be augmented and retained and replacing it with a new wall (i.e. brick or stone), using the historic masonry only as an exterior veneer.

Not recommended: Leaving known structural problems untreated such as deflection of beams, cracking and bowing of walls, or racking of structural members.

Not recommended: Utilizing treatments or products that accelerate the deterioration of structural material such as introducing urea-formaldehyde foam insulation into frame walls.

Not recommended: Failing to provide proper building maintenance on a cyclical basis so that deterioration of the structural system results.

Not recommended: Utilizing destructive probing techniques that will damage or destroy structural material.

Not recommended: Upgrading the building structurally in a manner that diminishes the historic character of the exterior, such as installing strapping channels or removing a decorative cornice; or damages interior features or spaces.

Not recommended: Replacing a structural member or other feature of the structural system when it could be augmented and retained.

Not recommended: Installing a replacement feature that does not convey the same visual appearance, e.g., replacing an exposed wood summer beam with a steel beam.

Not recommended: Using substitute material that does not equal the loadbearing capabilities of the historic material and design or is otherwise physically or chemically incompatible.

Not recommended: Carrying out excavations or regrading adjacent to or within a historic building which could cause the historic foundation to settle, shift, or fail; or could have a similar effect on adjacent historic buildings.

Not recommended: Radically changing interior spaces or damaging or destroying features or finishes that are character defining while trying to correct structural deficiencies in preparation for the new use.

Not recommended: Installing new mechanical and electrical systems or equipment in a manner which results in numerous cuts, splices, or alterations to the structural members.

Not recommended: Inserting a new floor when such a radical change damages a structural system or obscures or destroys interior spaces, features, or finishes.

Not recommended: Inserting new floors or furred-down ceilings which cut across the glazed areas of windows so that the exterior form and appearance of the windows are radically changed.

Not recommended: Damaging the structural system or individual features; or radically changing, damaging, or destroying character-defining interior spaces, features, or finishes in order to create an atrium or a light well.

# **Building Interior: Spaces, Features, and Finishes**

Recommended: **Identifying, retaining, and preserving** a floor plan or interior spaces that are important in defining the overall historic character of the building. This includes the size, configuration, proportion, and relationship of rooms and corridors; the relationship of features to spaces; and the spaces themselves such as lobbies, reception halls, entrance halls, double parlors, theaters, auditoriums, and important industrial or commercial use spaces.

Recommended: **Identifying, retaining, and preserving** interior features and finishes that are important in defining the overall historic character of the building, including columns, cornices, baseboards, fireplaces and mantles, paneling, light fixtures, hardware, and flooring; and wallpaper, plaster, paint, and finishes such as stenciling, marbling, and graining; and other decorative materials that accent interior features and provide color, texture, and patterning to walls, floors, and ceilings.

Recommended: **Protecting and maintaining** masonry, wood, and architectural metals which comprise interior features through appropriate surface treatments such as cleaning, rust removal, limited paint removal, and reapplication of protective coating systems.

Recommended: Protecting interior features and finishes against arson and vandalism before project work begins, erecting protective fencing, boarding-up windows, and installing fire alarm systems that are keyed to local protection agencies.

Recommended: Protecting interior features such as a staircase, mantel, or decorative finishes and wall coverings against damage during project work by covering them with heavy canvas or plastic sheets.

Recommended: Installing protective coverings in areas of heavy pedestrian traffic to protect historic features such as wall coverings, parquet flooring and paneling.

Recommended: Removing damaged or deteriorated paints and finishes to the next sound layer using the gentlest method possible, then repainting or refinishing using compatible paint or other coating systems.

Recommended: Repainting with colors that are appropriate to the historic building.

Recommended: Limiting abrasive cleaning methods to certain industrial or warehouse buildings where the interior masonry or plaster features do not have distinguishing design, detail, tooling, or finishes; and where wood features are not finished, molded, beaded, or worked by hand. Abrasive cleaning should only be considered after other, gentler methods have been proven ineffective.

Recommended: Evaluating the overall condition of materials to determine whether more than protection and maintenance are required, that is, if repairs to interior features and finishes will be necessary.

Recommended: **Repairing** interior features and finishes by reinforcing the historic materials. Repair will also generally include the limited replacement in kind – or with compatible substitute material – of those extensively deteriorated or missing parts of repeated features when there are surviving prototypes such as stairs, balustrades, wood paneling, columns; or decorative wall coverings or ornamental tin or plaster ceilings.

Recommended: **Replacing** in kind an entire interior feature or finish that is too deteriorated to repair – if the overall form and detailing are still evident – using the physical evidence to guide the new work. Examples could include wainscoting, a tin ceiling, or interior stairs. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Recommended: Accommodating service functions such as bathrooms, mechanical equipment, and office machines required by the building's new use in secondary spaces such as first floor service areas or on upper floors.

Recommended: Reusing decorative materials or features that have had to be removed during the rehabilitation work including wall and baseboard trim, door moulding, paneled doors, and simple wainscoting; and relocating such material or features in areas appropriate to their historic placement.

Recommended: Installing permanent partitions in secondary spaces; removable partitions that do not destroy the sense of space should be installed when the new use requires the subdivision of character defining interior spaces.

Recommended: Enclosing an interior stairway where required by code so that its character is retained. In many cases, glazed fire-rated walls may be used.

Recommended: Placing new code-required stairways or elevators in secondary and service areas of the historic building.

Recommended: Creating an atrium or a light well to provide natural light when required for the new use in a manner that preserves character-defining interior spaces, features, and finishes as well as the structural systems.

Recommended: Adding a new floor if required for the new use in a manner that preserves characterdefining structural features, and interior spaces, features, and finishes.

Not recommended: Radically changing a floor plan or interior spaces-including individual rooms-which are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Not recommended: Altering the floor plan by demolishing principal walls and partitions to create a new appearance.

Not recommended: Altering or destroying interior spaces by inserting floors, cutting through floors, lowering ceilings, or adding or removing walls.

Not recommended: Relocating an interior feature such as a staircase so that the historic relationship between features and space is altered.

Not recommended: Removing or radically changing features and finishes which are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Not recommended: Installing new decorative material that obscures or damages character-defining interior features or finishes.

Not recommended: Removing paint, plaster, or other finishes from historically finished surfaces to create a new appearance (e.g. removing plaster to expose masonry surfaces such as brick walls or a chimney piece).

Not recommended: Applying paint, plaster, or other finishes to surfaces that have been historically unfinished to create a new appearance.

Not recommended: Stripping historically painted wood surfaces to bare wood, then applying clear finishes or stains to create a "natural look."

Not recommended: Stripping paint to bare wood rather than repairing or reapplying grained or marbled finishes to features such as doors and paneling.

Not recommended: Radically changing the type of finish or its color, such as painting a previously varnished wood feature.

Not recommended: Failing to provide adequate protection to materials on a cyclical basis so that deterioration of interior features results.

Not recommended: Permitting entry into historic buildings through unsecured or broken windows and doors so that interior features and finishes are damaged by exposure to weather or through vandalism.

Not recommended: Stripping interiors of features such as woodwork, doors, windows, light fixtures, copper piping, radiators; or of decorative materials.

Not recommended: Failing to provide proper protection of interior features and finishes during work so that they are gouged, scratched, dented, or otherwise damaged.

Not recommended: Failing to take new use patterns into consideration so that interior features and finishes are damaged.

Not recommended: Using destructive methods such as propane or butane torches or sandblasting to remove paint or other coatings. These methods can irreversibly damage the historic materials that comprise interior features.

Not recommended: Using new paint colors that are inappropriate to the historic building.

Not recommended: Changing the texture and patina of character-defining features through sandblasting or using other abrasive methods to remove paint, discoloration or plaster. This includes both exposed wood (including structural members) and masonry.

Not recommended: Failing to undertake adequate measures to assure the preservation of interior features and finishes.

Not recommended: Replacing an entire interior feature such as a staircase, paneled wall, parquet floor, or cornice; or finish such as a decorative wall covering or ceiling when repair of materials and limited replacement of such parts are appropriate.

Not recommended: Using a substitute material for the replacement part that does not convey the visual appearance of the surviving parts or portions of the interior feature or finish or that is physically or chemically incompatible.

Not recommended: Removing a character defining feature or finish that is unrepairable and not replacing it; or replacing it with a new feature or finish that does not convey the same visual appearance.

Not recommended: Creating a false historical appearance because the replaced feature is based on insufficient physical, historical, and pictorial documentation or on information derived from another building.

Not recommended: Introducing a new interior feature or finish that is incompatible with the scale, design, materials, color, and texture of the surviving interior features and finishes.

Not recommended: Dividing rooms, lowering ceilings, and damaging or obscuring character-defining features such as fireplaces, niches, stairways or alcoves, so that a new use can be accommodated in the building.

Not recommended: Discarding historic material when it can be reused within the rehabilitation project or relocating it in historically inappropriate areas.

Not recommended: Installing permanent partitions that damage or obscure character-defining spaces, features, or finishes.

Not recommended: Enclosing an interior stairway with fire-rated construction so that the stairwell space or any character-defining features are destroyed.

Not recommended: Radically changing, damaging, or destroying character-defining spaces, features, or finishes when adding new code-required stairways and elevators.

Not recommended: Destroying character-defining interior spaces, features, or finishes; or damaging the structural system in order to create an atrium or light well.

Not recommended: Inserting a new floor within a building that alters or destroys the fenestration; radically changes a character-defining interior space; or obscures, damages, or destroys decorative detailing.

## Mechanical Systems: Heating, Air Conditioning, Electrical, and Plumbing

Recommended: **Identifying, retaining, and preserving** visible features of early mechanical systems that are important in defining the overall historic character of the building, such as radiators, vents, fans, grilles, plumbing fixtures, switchplates, and lights.

Recommended: **Protecting and maintaining** mechanical, plumbing, and electrical systems and their features through cyclical cleaning and other appropriate measures.

Recommended: Preventing accelerated deterioration of mechanical systems by providing adequate ventilation of attics, crawlspaces, and cellars so that moisture problems are avoided.

Recommended: **Repairing** mechanical systems by augmenting or upgrading system parts, such as installing new pipes and ducts; rewiring; or adding new compressors or boilers.

Recommended: **Replacing** in kind – or with compatible substitute material – those visible features of mechanical systems that are either extensively deteriorated or are missing when there are surviving prototypes such as ceiling fans, switchplates, radiators, grilles, or plumbing fixtures.

Recommended: Installing a completely new mechanical system if required for the new use so that it causes the least alteration possible to the building's floor plan, the exterior elevations, and the least damage to historic building material.

Recommended: Installing the vertical runs of ducts, pipes, and cables in closets, service rooms, and wall cavities.

Recommended: Installing air conditioning units if required by the new use in such a manner that the historic materials and features are not damaged or obscured.

Recommended: Installing heating/air conditioning units in the window frames in such a manner that the sash and frames are protected. Window installations should be considered only when all other heating/cooling systems would result in significant damage to historic materials.

Not recommended: Removing or radically changing features of mechanical systems that are important in defining the overall historic character of the building so that, as a result, the character is diminished.

Not recommended: Failing to provide adequate protection of materials on a cyclical basis so that deterioration of mechanical systems and their visible features results.

Not recommended: Enclosing mechanical systems in areas that are not adequately ventilated so that deterioration of the systems results.

Not recommended: Replacing a mechanical system or its functional parts when it could be upgraded and retained.

Not recommended: Installing a replacement feature that does not convey the same visual appearance.

Not recommended: Installing a new mechanical system so that character-defining structural or interior features are radically changed, damaged, or destroyed.

Not recommended: Installing vertical runs of ducts, pipes, and cables in places where they will obscure character – defining features.

Not recommended: Concealing mechanical equipment in walls or ceilings in a manner that requires the removal of historic building material.

Not recommended: Installing "dropped" acoustical ceilings to hide mechanical equipment when this destroys the proportions of character –defining interior spaces.

Not recommended: Cutting through features such as masonry wall in order to install air conditioning units.

Not recommended: Radically changing the appearance of the historic building or damaging or destroying windows by installing heating/air conditioning units in historic window frames.

# **Building Site**

Recommended: **Identifying, retaining, and preserving** buildings and their features as well as features of the site that are important in defining its overall historic character. Site features can include driveways, walkways, lighting, fencing, signs, benches, fountains, wells, terraces, canal systems, plants and trees, berms, and drainage or irrigation ditches; and archeological features that are important in defining the history of the site.

Recommended: Retaining the historic relationship between buildings, landscape features, and open space.

Recommended: **Protecting and maintaining** buildings and the site by providing proper drainage to assure that water does not erode foundation walls; drain toward the building; nor erode the historic landscape.

Recommended: Minimizing disturbance of terrain around buildings or elsewhere on the site, thus reducing the possibility of destroying unknown archeological materials.

Recommended: Surveying areas where major terrain alteration is likely to impact important archeological sites.

Recommended: Protecting, e.g. preserving in place known archeological material whenever possible.

Recommended: Planting and carrying out any necessary investigation using professional archeologists and modern archeological methods when preservation in place is not feasible.

Recommended: Protecting the building and other features of the site against arson and vandalism before rehabilitation work begins, i.e., erecting protective fencing and installing alarm systems that are keyed into local protection agencies.

Recommended: Providing continued protection of masonry, wood, and architectural metals which comprise building and site features through appropriate surface treatments such as cleaning, rust removal, limited paint removal, and re-application of protective coating systems; and continued protection and maintenance of landscape features, including plant material.

Recommended: Evaluating the overall condition of materials to determine whether more than protection and maintenance are required, that is, if repairs to building and site features will be necessary.

Recommended: **Repairing** features of buildings and the site by reinforcing the historic materials. Repair will also generally include replacement in kind – with a compatible substitute material – of those extensively deteriorated or missing parts of features where there are surviving prototypes such as fencing and paving.

Recommended: **Replacing** in kind an entire feature of the building or site that is too deteriorated to repair – if the overall form and detailing are still evident – using the physical evidence to guide the new work. This could include an entrance or porch, walkway, or fountain. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Recommended: Designing new on-site parking, loading docks, or ramps when required by the new use so that they are as unobtrusive as possible and assure the preservation of character-defining features of the site.

Recommended: Designing new exterior additions to historic buildings or adjacent new construction which is compatible with the historic character of the site and which preserve the historic relationship between a building or buildings, landscape features, and open space.

Recommended: Removing nonsignificant buildings, additions, or site features which detract from the historic character of the site.

Not recommended: Removing or radically changing buildings and their features or site features which are important in defining the overall historic character of the building site so that, as a result, the character is diminished.

Not recommended: Removing or relocating historic buildings or landscape features, thus destroying the historic relationship between buildings, landscape features, and open space.

Not recommended: Removing or relocating historic buildings on a site or in a complex of related historic structures – such as a mill complex or farm – thus diminishing the historic character of the site or complex.

Not recommended: Moving buildings onto the site, thus creating a false historical appearance.

Not recommended: Lowering the grade level adjacent to a building to permit development of a formerly below-grade area such as a basement in a manner that would drastically change the historic relationship of the building to its site.

Not recommended: Failing to maintain site drainage so that buildings and site features are damaged or destroyed; or, alternatively, changing the site grading so that water no longer drains properly.

Not recommended: Introducing heavy machinery or equipment into areas where their presence may disturb archeological materials.

Not recommended: Failing to survey the building site prior to the beginning of rehabilitation project work so that, as a result, important archeological material is destroyed.

Not recommended: Leaving known archeological material unprotected and subject to vandalism, looting and destruction by natural elements, such as erosion.

Not recommended: Permitting unqualified project personnel to perform data recovery so that improper methodology results in the loss of important archeological material.

Not recommended: Permitting buildings and site features to remain unprotected so that plant materials, fencing, walkways, archeological features, etc. are damaged or destroyed.

Not recommended: Stripping features from buildings and the site such as wood siding, iron fencing, masonry balustrades; or removing or destroying landscape features, including plant material.

Not recommended: Failing to provide adequate protection of materials on a cyclical basis so that deterioration of building and site features results.

Not recommended: Failing to undertake adequate measures to assure the preservation of building and site features.

Not recommended: Replacing an entire feature of the building or site such as a fence, walkway, or driveway when repair of materials and limited replacement of deteriorated or missing parts are appropriate.

Not recommended: Using a substitute material for the replacement part that does not convey the visual appearance of the surviving parts of the building or site feature or that is physically or chemically incompatible.

Not recommended: Removing a feature of the building or site that is unrepairable and not replacing it; or replacing it with a new feature that does not convey the same visual appearance.

Not recommended: Creating a false historical appearance because the replaced feature is based on insufficient historical, pictorial, and physical documentation.

Not recommended: Introducing a new building or site feature that is out of scale or otherwise inappropriate.

Not recommended: Introducing a new landscape feature or plant material that is visually incompatible with the site or that destroys site patterns or vistas.

Not recommended: Placing parking facilities directly adjacent to historic buildings where automobiles may cause damage to the buildings or landscape features or be intrusive to the building site.

Not recommended: Introducing new construction onto the building site which is visually incompatible in terms of size, scale, design, materials, color and texture or which destroys historic relationships on the site.

Not recommended: Removing a historic building in a complex, a building feature, or a site feature which is important in defining the historic character of the site.

## **District Neighborhood**

Recommended: **Identifying, retaining, and preserving** buildings, and streetscape, and landscape features which are important in defining the overall historic character of the district or neighborhood. Such features can include streets, alleys, paving, walkways, streetlights, signs, benches, parks and gardens, and trees.

Recommended: Retaining the historic relationship between buildings, and streetscape and landscape features such as town square comprised of row houses and stores surrounding a communal park or open space.

Recommended: **Protecting and maintaining** the historic masonry, wood, and architectural metals which comprise building and streetscape features, through appropriate surface treatments such as cleaning, rust removal, limited paint removal, and reapplication of protective coating systems, and protecting and maintaining landscape features, including plant material.

Recommended: Protecting buildings, paving, iron fencing, etc. against arson and vandalism before rehabilitation work begins by erecting protective fencing and installing alarm systems that are keyed into local protection agencies.

Recommended: Evaluating the overall condition of building, streetscape and landscape materials to determine whether more than protection and maintenance are required, that is, if repairs to features will be necessary.

Recommended: **Repairing** features of the building, streetscape, or landscape by reinforcing the historic materials. Repair will also generally include the replacement in kind – or with a compatible substitute material – of those extensively deteriorated or missing parts or features when there are surviving prototypes such as porch balustrades, paving materials, or streetlight standards.

Recommended: **Replacing** in kind an entire feature of the building, streetscape, or landscape that is too deteriorated to repair – when the overall form and detailing are still evident – using the physical evidence to guide the new work. This could include a storefront, a walkway, or a garden. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

Recommended: Designing and constructing a new feature of the building, streetscape or landscape when the historic feature is completely missing, such as row house steps, a porch, streetlight, or terrace. It may be a restoration based on historical, pictorial, and physical documentation; or be a new design that is compatible with the historic character of the district or neighborhood.

Recommended: Designing required new parking so that it is as unobtrusive as possible, i.e., on side streets or at the rear of buildings. "Shared" parking should also be planned so that several businesses can utilize one parking area as opposed to introducing random, multiple lots.

Recommended: Designing and constructing new additions to historic buildings when required by the new use. New work should be compatible with the historic character of the district or neighborhood in terms of size, scale, design, material, color and texture.

Recommended: Removing nonsignificant buildings, additions, or streetscape and landscape features which detract from the historic character of the district or the neighborhood.

Not recommended: Removing or radically changing those features of the district or neighborhood which are important in defining the overall historic character so that, as a result, the character is diminished.

Not recommended: Destroying streetscape and landscape features by widening existing streets, changing paving material, or introducing inappropriately located new streets or parking lots.

Not recommended: Removing or relocating historic buildings, or features of the streetscape and landscape, thus destroying the historic relationship between buildings, features, and open space.

Not recommended: Failing to provide adequate protection of materials on a cyclical basis so that deterioration of building, streetscape, and landscape features results.

Not recommended: Permitting buildings to remain unprotected so that windows are broken; and interior features are damaged.

Not recommended: Stripping features from buildings or the streetscape such as wood siding, iron fencing, or terra cotta balusters; or removing or destroying landscape features, including plant material.

Not recommended: Failing to undertake adequate measures to assure the preservation of building, streetscape, and landscape features.

Not recommended: Replacing an entire feature of the building, streetscape, or landscape such as a porch, walkway, or streetlight, when repair of materials and limited replacement of deteriorated or missing parts are appropriate.

Not recommended: Using a substitute material for the replacement part that does not convey the visual appearance of the surviving parts of the building, streetscape, or landscape feature or that is physically or chemically incompatible.

Not recommended: Removing a feature of the building, streetscape, or landscape that is unrepairable and not replacing it; or replacing it with a new feature that does not convey the same visual appearance.

Not recommended: Creating a false historical appearance because the replaced feature is based on insufficient historical, pictorial, and physical documentation.

Not recommended: Introducing a new building, streetscape or landscape feature that is out or scale or otherwise inappropriate to the setting's historic character, e.g. replacing picket fencing with chain link fencing.

Not recommended: Placing parking facilities directly adjacent to historic buildings which cause the removal of historic plantings, relocation of paths and walkways, or blocking of alleys.

Not recommended: Introducing new construction into historic districts that is visually incompatible or that destroys historic relationships within the district or neighborhood.

Not recommended: Removing a historic building, building feature, or landscape or streetscape feature that is important in defining the overall historic character of the district or the neighborhood.

## Health and Safety Code Requirements

Recommended: Identifying the historic building's character-defining spaces, features, and finishes so that code required work will not result in their damage or loss.

Recommended: Complying with health and safety code, including seismic codes and barrier-free access requirements, in such a manner that character-defining spaces, features, and finishes are preserved.

Recommended: Working with local code officials to investigate alternative life safety measures or variances available under some codes so that alterations and additions to historic buildings can be avoided.

Recommended: Providing barrier-free access through removable or portable, rather than permanent, ramps.

Recommended: Providing seismic reinforcement to a historic building in a manner that avoids damaging the structural system and character-defining features.

Recommended: Upgrading historic stairways and elevators to meet health and safety codes in a manner that assures their preservation, i.e. so that they are not damaged or obscured.

Recommended: Installing sensitively designed fire suppressions systems, such as a sprinkler system for wood frame mill buildings, instead of applying fire-resistant sheathing to character-defining features.

Recommended: Applying fire-retardant coatings, such as intumescent paints, which expand during fire to add thermal protection to steel.

Recommended: Adding a new stairway or elevator to meet health and safety codes in a manner that preserves adjacent character-defining features and space.

Recommended: Placing a code-required stairway or elevator that cannot be accommodated within the historic building in a new exterior addition. Such an addition should be located at the rear of the building or an inconspicuous side; and its size and scale limited in relationship to the historic building.

Not recommended: Undertaking code-required alterations to a building or site before identifying those spaces, features, or finishes which are character-defining and must therefore be preserved.

Not recommended: Altering, damaging, or destroying character-defining spaces, features, and finishes while making modifications to a building or site to comply with safety codes.

Not recommended: Making changes to historic buildings without first seeking alternatives to code requirements.

Not recommended: Installing permanent ramps that damage or diminish character-defining features.

Not recommended: Reinforcing a historic building using measures that damage or destroy characterdefining structural and other features.

Not recommended: Damaging or obscuring historic stairways and elevators or altering adjacent spaces in the process of doing work to meet code requirements.

Not recommended: Covering character-defining wood features with fire-resistant sheathing which results in altering their visual appearance.

Not recommended: Using fire-retardant coatings if they damage or obscure character-defining features.

Not recommended: Radically changing, damaging, or destroying character-defining spaces, features, or finishes when adding a new code required stairway or elevator.

- 8. The following criteria shall be considered, when relevant, by the Commission in reviewing applications for a Certificate of Appropriateness. All applications for Certificates of Appropriateness shall be subject to review based upon the Design Guidelines then in effect. These guidelines are set forth in a manual prepared and adopted by the Commission:
  - lot coverage, defined as the percentage of lot area covered by primary structures;
  - setback, defined as the distance from the lot lines to the building(s);
  - building height;
  - exterior building materials;
  - proportion, shape, positioning, location, pattern and sizes of any elements of fenestration;
  - surface textures;
  - structural condition and soundness;
  - walls--physical ingredients, such as brick, stone or wood walls, wrought iron fences, evergreen landscape masses, building facades, or combination of these;
  - color (new construction only and not for existing residences); and
  - effect of trees and other landscape elements.
- 9. The application is congruous with the historic aspects of the landmark.
- 10. Based on the standards of the Handbook, and the City of Concord Code of Ordinances, including the standards listed above, the Commission concludes that:
  - a. The Site Work as described in the scope of work dated November 8, 2022 and Technical Site Plan Case PRS2021-01908 as of December 14, 2022, is appropriate for the site based on the conditions applied by the National Park Service and the review of the project under the standards of Appendix A of the *Historic Handbook*. The National Park Service and City Arborist will need to reach agreement on an approvable landscape and lighting plan. Site work is subject to the conditions imposed by the National Park Service in their letter of October 12, 2022.
  - b. The demolition work as described in the scope of work dated November 8, 2022 and Technical Site Plan Case PRS2021-01908 and Building Plan case PRB2021-02298 as of December 14, 2022, which includes the removal of the two ventilation rooms on the north side of the main mill building, is appropriate based on the evidence presented and on the

conditions applied by the National Park Service and the review of the project under the standards of Appendix A of the *Historic Handbook*.

- c. The utilities work described in the scope of work dated November 8, 2022 and Technical Site Plan Case PRS2021-01908 as of December 14, 2022, is appropriate for the site based on the conditions applied by the National Park Service and the review of the project under the standards of Appendix A of the *Historic Handbook*.
- d. The building exteriors work described in the scope of work dated November 8, 2022 and Building Plan case PRB2021-02298 as of December 14, 2022, is appropriate based on the conditions applied by the National Park Service and the review of the project under the standards of Appendix A of the *Historic Handbook*.
- e. The building interiors, unit construction, and mechanical/electrical/plumbing work described in the scope of work dated November 8, 2022 and Building Plan case PRB2021-02298 as of December 14, 2022, is appropriate based on the conditions applied by the National Park Service and the review of the project under the standards of Appendix A of the Historic Handbook.

Commissioner Barbee made a motion to approve the Findings of Fact. Commissioner Underwood seconded the motion. The vote carried unanimously. –**The Vote: All Ayes** 

Commissioner Barbee made a motion to approve the Certificate of Appropriateness and to allow the Chairman to sign the Order out of session. Commissioner Underwood seconded the motion. The vote carried. –The Vote: All Ayes (APPROVED)

# **STAFF UPDATE:**

## **<u>HISTORIC HANDBOOK</u>**:

Mr. Sherrill stated that the Historic Handbook Committee has met a couple of times since the last Commission meeting. They have worked their way trough Chapter Four and are basically visiting each chapter twice. Mr. Sherrill introduced Autumn James, who is the new Senior Planner and is doing a great job of getting materials out to the Committee as well. He stated that they are talking about doing a little bit of restructuring, making sure that the flow charts and procedures are clear, which is clearly a need based on some of the testimony that was heard this evening. Also, they are going a fair amount of rearrangement in Articles 3 and 4, in Chapters 3 and 4. They are taking one section at a time but they are moving at a pretty good speed.

## **ADJOURNMENT:**

A motion was made and carried to adjourn the meeting at 9:40 p.m.

Chair–William Isenhour

Secretary – Angela Baldwin