

Historic Preservation Commission

DATE: July 11, 2018

SUBJECT:

Certificate of Appropriateness Request:

Applicant:

<u>Location of subject property:</u>

Staff Report prepared by:

H-16-18

Monty Coggins 166A Union St N

Scott Sherrill, Sr. Planner

BACKGROUND:

• The subject property is site of an "Intrusive" structure and is located in the North Union Street Historic District. (Exhibit A)

• Date of construction: ca. 1950

- One-story, brick structure with louvered windows, wrought-iron porch supports. Although materials and design of building and incongruous with the district, the setback of the building is reasonably compatible with those of its contributing neighbors and the building is largely hidden by a large magnolia tree (Exhibit A).
- Applicant is seeking to remove a 40' tall pecan tree with a Hazard Rating of "4".

DISCUSSION:

Applicant is seeking to remove a 40' tall pecan tree with a Hazard Rating of "4". Trees with a hazard rating less than "5" require Historic Preservation Commission review and approval. City Arborist Bill Leake has recommended that removal be considered, noting "This tree was subject to root damage and inappropriate pruning during recent building renovations. It has small area of decay at the base of the trunk, on the fence side, and two small areas of decay in the upper crown." Typically, tree removal is conditioned with replacement with a similar species, but Mr. Leake has reported that, "there are no appropriate locations to replant a large growing tree species on this property."

ATTACHMENTS

Exhibit A: National Register of Historic Places Inventory—Nomination Form

Exhibit B: Application for Certificate of Appropriateness

Exhibit C: Tree Hazard Evaluation

Exhibit D: Photographs

HISTORIC HANDBOOK DESIGN RECOMMENDATIONS:

Chapter 5 - Section 8: Landscaping and Trees

One of the most visible features of the Districts is the landscaping and associated tree canopy. Activities which negatively impact any aspect of the landscape should be avoided, such as the removal of healthy trees and mature shrubs.

Tree health may be decided upon by the acquisition of a Tree Hazard Evaluation Report issued by the City Arborist or a report submitted by a certified arborist. Healthy trees are trees that have a hazard rating of 4 or lower. Removal of healthy trees over the size of 6 inches in diameter (measured 4 feet above ground) or pruning of healthy tree limbs over 6 inches in diameter requires Historic Preservation Commission review and approval. City staff may approved [sic] a Certificate of Appropriateness for the removal of healthy trees under 6 inches in diameter. Staff may also approve removal or pruning of

unhealthy trees/limbs of any size and in any location if the tree is deemed hazardous by the Tree Hazard Evaluation Report. City Staff may refer any tree pruning or removal request to the Historic Preservation Commission.

All trees that are removed should be replaced with a tree of similar species in an appropriate location unless no suitable location exists on the subject site. Trees removed within street view must also have the stumps removed below ground level.

Design Guidelines and Recommendations

- 2. Trees which are removed shall be replaced by a species which, upon maturity, is similar in scale to the removed specimen. For example, canopy trees shall be replaced with canopy trees, and understory trees with understory trees.
- 3. Placement of all vegetation should not interfere with utilities and vehicular traffic (sight-triangles).

RECOMMENDATION:

- 1. The Historic Preservation Commission should consider the circumstances of this application for a Certificate of Appropriateness relative to the <u>North and South Union Street Historic Districts</u>

 Handbook and <u>Guidelines</u> and act accordingly.
- 2. If approved, applicant(s) should be informed of the following:
 - City staff and Commission will make periodic on-site visits to ensure the project is completed as approved.
 - Completed project will be photographed to update the historic properties survey.

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only
received 1

عدم حلك مصحرة المنافرة المنافر

Continuation sheet Item number Page

Inventory List - North Union Street #7 24

Historic District, Concord

the materials and details of the building are somewhat incongruous with the district, the harmonious landscaping and setback (parking is at the rear of the building) keep it from being an intrusion.

16. House 180 North Union Street ca. 1940

Two-story, frame, late Colonial Revival residence with side gable roof and full facade, two-story portico with simple molded columns. House has symmetrical, five-bay facade with 6/6 sash windows; most distinctive feature of house is entrance, which is composed of fluted I onic pilasters rising to a broken pediment, sidelights, and a small, fan-shaped transom.

17. House 172 North Union Street ca. 1925

One-and-a-half-story bungalow with a veneer of oversize, enamelized brick laid in Flemish bond with glazed headers. Two-bay, gable-front porch and gable-roofed porte-cochere on north (left) side of house upheld by thin, square posts grouped in twos and threes. Above the first floor house is sheathed in patterned asbestos shingles. Broad, shed-roofed dormer pierces side gable roof on front of house. To the rear of the house is a two-story garage and apartment of frame construction clad with asbestos shingles that is contemporary with the house.

18. Ritchie Nursing Home 166 North Union Street ca. 1950

One-story, brick structure with louvered windows, wrought-iron porch supports. Although materials and design of building are incongruous with the district, the setback of the building is reasonably compatible with those of its contributing neighbors and the building is largely hidden by a large magnolia tree.




H-16-18

Monty Coggins

166A Union St N

PIN: 5620-79-5721





Source: City of Concord Planning Department

Disclaimer

These maps and products are designed for general reference only and data contained herein is subject to change. The City Of Concord, it's employees or agents make no warranty of merchantability or fitness for any purpose, expressed or implied, and assume no legal responsibility for the information contained therein. Data used is from multiple sources with various scales and accuracy. Additional research such as field surveys may be necessary to determine actual conditions.





AN INCOMPLETE APPLICATION WILL NOT BE PLACED ON THE AGENDA UNTIL ALL OF THE REQUIRED ATTACHMENTS AND/OR ITEMS LISTED ON PAGE 2 ARE SUBMITTED.

APPLICANT INFORMATION	
Name: Monty Cognins	
Address: 166A Union St N	
City: What State: NC Zip Code: 28025	Telephone: 704 701 9775
OWNER INFORMATION	
Name: Same	3
Address:	
City: State: Zip Code:	Telephone:
SUBJECT PROPERTY	
Street Address: 166A UNIDY STN	P.I.N.#
Area (acres or square feet):Current Zoning:	Land Lice
Thea (acres of square feet)current Zohnig	Land Osc.
Artea (acres of square reet)Carrent Zonnig	Land Ose.
Artea (acres of square reet)Current Zonnig	Land Ose.
	Land Ose.
Staff Use Only:	Land Ose.
Staff Use	
Staff Use Only:	
Staff Use Only: Application Received by:	Date:

Exhibit B



Certificate of Appropriateness

General Requirements

The Unified Development Ordinance imposes the following rules, regulations and requirements on requests for Certificates of Appropriateness. The applicant must, with reference to the attached plans, demonstrate how the proposed use satisfies these requirements:

1.	Project or Type of Work to be Done: taking down dead tree in side
	Project or Type of Work to be Done: taking down dead tree in side yand/Marsh St.
2.	Detailed specifications of the project (type of siding, windows, doors, height/style of fence, color, etc.):
_	
_	

Required Attachments/Submittals

- 1. Scaled site plan, if additions or accessory structures are proposed, on letter, legal or ledger paper. Larger sized copies will be accepted if **16 folded copies** are submitted for distribution.
- 2. A photograph of the front of the house.
- 3. Photographs of site, project, or existing structures from a "before" perspective
- 4. Drawings, sketches, renderings, elevations, or photographs necessary to present an illustration of the project from an "after" perspective.
- 5. Samples of windows, doors, brick, siding, etc. must be submitted with application.
- 6. Detailed list of materials that will be used to complete the project.

Certification

(1) I hereby acknowledge and say that the information contained herein and herewith is true and that this application shall not be scheduled for official consideration until all of the required contents are submitted in proper form to the City of Concord Development Services Department. (2) I understand that City staff and/or members of the Historic Preservation Commission may make routine visits to the site to insure that work being done is the same as the work that was approved. (3) I understand that photographs of the completed project will be made to update the City's historic districts inventory database.

June 27, 2018

Date

Signature of Owner/A gent

Planning & Neighborhood Development

^{***}Applications may be submitted electronically. ***

TREE RISK ASSESSMENT FORM

City (A deliverant ACC A Division Ch N	RISK RATING:
Site/Address: 166-A Union St N	
Map/Location: Left side along Marsh Avenue	Potential of part Rating Rating
Owner: public: private:X unknown: other:	Immediate action needed
Date: 0/1/18 Inspector: Bill Leake	Needs further inspection
Date of last inspection:	Dead tree
TREE CHARACTERISTICS	
Tree #: 1Species: Pecan (Carya illinoensis)	
DBH: 18" # of trunks: 1 Height: 40' Spread: 25'	
Form: \square generally symmetric \square minor asymmetry \boxtimes major asymmetry \square s	stump sprout 🗆 stag-headed
Crown class: ☐ dominant ☒ co-dominant ☐ intermediate ☐ suppressed	
Live crown ratio: 95 % Age class: □ young ⊠ semi-mature □ mature	e □ over-mature/senescent
Pruning history: □ crown cleaned □ excessively thinned ⋈ topped ⋈ crown rais □ cabled/braced □ none □ multiple pruning events Approx. dat	·
Special Value: \square specimen \boxtimes heritage/historic \square wildlife \square unusual \square street tre	ee \square screen \square shade \square indigenous \boxtimes protected by gov. agency
TREE HEALTH	
Foliage color. ⊠ normal □ chlorotic □ necrotic Epicormics; ⊠	Growth obstructions:
Foliage density: □normal ☑sparse Leaf size: □ normal ☑ s	mall □ stakes □ wire/ties □ signs □ cables
Annual shoot growth: ☐ excellent ☒ average ☐ poor ☐ none Twig Die	eback: Surb/pavement guards
Woundwood: ☐ excellent ⊠average ☐ fair ☐ poor	
Vigor class: ☐ excellent ☐ average ☒ fair ☐ poor	
Major pests/diseases:	
SITE CONDITIONS	
Site Character: $oxtimes$ residence $oxtimes$ commercial $oxtimes$ industrial $oxtimes$ park $oxtimes$ op	en space □ natural □woodland/forest
Landscape type: \square parkway \square raised bed \square container \square mound \boxtimes la	awn □ shrub border □ wind break
Irrigation : \boxtimes none \square adequate \square inadequate \square excessive \square trunk wetter	
Recent site disturbance? YES $\ \ \ \ \ \ \ \ \ \ \ \ \ $	change
% dripline paved: 50% Pavement lifted: NO	
% dripline w/ fill soil: 0%	
% dripline grade lowered: 0%	
Soil problems: □ drainage □ shallow ⋈ compacted □ droughty □ saline □ a ⋈ clay □ expansive ⋈ slope 10° aspect:	
Conflicts: \Box lights \Box signage \Box line-of-sight \Box view \Box overhead lines \Box under	
Exposure to wind: \square single tree \boxtimes below canopy \square above canopy \square recently exposure to wind:	kposed $oxtimes$ windward, canopy edge $oxtimes$ area prone to windthrow
Prevailing wind direction:SW Occurrence of snow/ice storms □ r	never ⊠ seldom □ regularly
TARGET	
Use Under Tree: $⊠$ building $□$ parking $⊠$ traffic $⊠$ pedestrian $□$ recreation $□$	
Can target be moved? NO Can use be restricted? NO	
Occupancy: □ occasional use ⊠ intermittent use □ frequent use □ constant u	se

Exhibit C

7

ROOT DEFECTS: Suspect root rot: NO Mushroom/conk/bracket present: NO ID: Exposed roots:
Exposed roots:
Root pruned: YES distance from trunk: 4' Root area affected: 30% Buttress wounded: When: Restricted root area: Severe moderate low Potential for root failure: severe moderate low LEAN: 3 deg. from vertical matural moderate self-corrected soli heaving: Decay in plane of lean: Roots broken: Soil cracking: Compounding factors: Lean severity: severe moderate with low CROWN DEFECTS: Indicate presence of individual defects and rate their severity (S = severe, M = moderate, L = low) DEFECT ROOT CROWN TRUNK SCAFFOLDS BRANCHES Poor taper Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
Restricted root area: ⊠ severe □ moderate □ low Potential for root failure: □ severe ⊠ moderate □ low LEAN: 3 deg. from vertical □ natural □ unnatural □ self-corrected □ Soil heaving: Decay in plane of lean: ☑ Roots broken: □ Soil cracking: □ Compounding factors: Lean severity: □ severe□ moderate ☒ low CROWN DEFECTS: Indicate presence of individual defects and rate their severity (S = severe, M = moderate, L = low) DEFECT ROOT CROWN TRUNK SCAFFOLDS BRANCHES Poor taper Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
Restricted root area: ⊠ severe □ moderate □ low Potential for root failure: □ severe ⊠ moderate □ low LEAN: 3 deg. from vertical ⊠ natural □ unnatural □ self-corrected □ Soil heaving: Decay in plane of lean: ☒ Roots broken: □ Soil cracking: □ Compounding factors: Lean severity: □ severe□ moderate ☒ low CROWN DEFECTS: Indicate presence of individual defects and rate their severity (S = severe, M = moderate, L = low) DEFECT ROOT CROWN TRUNK SCAFFOLDS BRANCHES Poor taper Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
LEAN: 3 deg. from vertical □ natural □ unnatural □ self-corrected □ Soil heaving: Decay in plane of lean: □ Roots broken: □ Soil cracking: □ Compounding factors: Lean severity: □ severe□ moderate □ low CROWN DEFECTS: Indicate presence of individual defects and rate their severity (S = severe, M = moderate, L = low) DEFECT ROOT CROWN TRUNK SCAFFOLDS BRANCHES Poor taper Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
Decay in plane of lean: ☑ Roots broken: ☐ Soil cracking: ☐ Compounding factors: Lean severity: ☐ severe☐ moderate ☒ low CROWN DEFECTS: Indicate presence of individual defects and rate their severity (S = severe, M = moderate, L = low) DEFECT ROOT CROWN TRUNK SCAFFOLDS BRANCHES Poor taper Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
Compounding factors: Lean severity: □ severe□ moderate ☒ low CROWN DEFECTS: Indicate presence of individual defects and rate their severity (S = severe, M = moderate, L = low) DEFECT ROOT CROWN TRUNK SCAFFOLDS BRANCHES Poor taper Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
CROWN DEFECTS: Indicate presence of individual defects and rate their severity (S = severe, M = moderate, L = low) DEFECT ROOT CROWN TRUNK SCAFFOLDS BRANCHES Poor taper Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
DEFECT ROOT CROWN TRUNK SCAFFOLDS BRANCHES Poor taper Bow, sweep Codominants/forks Codominants/forks Multiple attachments Included bark Excessive end weight Excessive end weight
Poor taper Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
Bow, sweep Codominants/forks Multiple attachments Included bark Excessive end weight
Codominants/forks Multiple attachments Included bark Excessive end weight
Multiple attachments Included bark Excessive end weight
Included bark Excessive end weight
Excessive end weight
Cracks/splits Cracks/splits
Hangers
Girdling
Wounds/seam M
Decay L L
Cavity
Conks/mushrooms/bracket
Bleeding/sap flow
Loose/cracked bark Nothing held/hoo hive
Nesting hole/bee hive Stub cuts M
Stub cuts M Borers/termites/ants
Cankers/galls/burls
Previous failure
HAZARD RATING
Tree part most likely to fail: Branches
Failure potential: 1 - low: 2 - medium; 3 - high; 4 - severe Size of part; 1 - <6" 2 - 6-18" 3 - 18-30" 4 - >30"
Failure potential: 1 - low: 2 - medium; 3 - high; 4 - severe <u>Size of part:</u> 1 - <6" 2 - 6-18" 3 - 18-30" 4 - >30" Target rating: 1 - cocasional use 2-intermittent use 3 - frequent use 4 - constant use
Maintenance Recommendations
Failure Potential + Size of Part + Target Rating = Hazard Rating 1
Inspect further □ root crown ⊠ decay □ aerial □ monitor
□ Remove tree □ When replaced, a similar sized tree species would be appropriate in same location
☐ When replaced, alternate tree replacement locations are available
Effect on adjacent trees: ⊠ none □ evaluate
Notification: ⊠ owner □ manager ⊠ governing agency Date: 4/24/18 COMMENTS
This tree was subject to root damage and inappropriate pruning during recent building renovations. It has small area of decay at the

This tree was subject to root damage and inappropriate pruning during recent building renovations. It has small area of decay at the base of the trunk, on the fence side, and two small areas of decay in the upper crown. I recommend removal be considered. However, there are no appropriate locations to replant a large growing tree species on this property.

Bill Leake

