COA Supporting Information

Jon L. Hobbs 197 Union Street, South Concord, NC 28025

Proposed Remodeling: Replacement of original lower level road facing windows

Reasoning:

The house was refinanced in September, 2018. As a requirement of the VA Loan the lower lever front windows are required to be replaced or reglazed. Replacement is the most economical and environmentally favored and energy efficient choice. Esthetically, this will allow all of the windows to be vinyl seeing that half were vinyl when we purchased the house in 2006 and when HPC approved the installation of Vinyl windows in the dormer install with the upstairs renovation in 2008.

Therefore, we have contracted with Universal Windows to replace the nine (9) lower windows. Not only will the new windows look similar to the existing windows, they will provide the necessary protection so the old storm windows can be removed.

Included is the information requested by the HOC guidelines. Thank you for your consideration.

Street View:



The Windows to be replaced:













Old Storm Windows

Glazing Falling Off

Replacement Information:

Universal Windows Direct		Jon Hobbs 197 Union Street S Concord, NC 28025		7047948869 Calvin865@aol.com Date: 12/29/2018 Rep: Thomas Jenser
Additional (Customer Information			
197 Unio	n Street S , NC 28025			
Year Home B	Built			1932
Source				Canvass
Vindow Pack	Window Style Quantity Vinyl Color Hardware Screen Style Grid Position Cap Color	Double Hung 9 White Standard Half All Glacier White	Location Innergy Size Screen Type Grid Style/Type Cap Type	Front of house 1st floor Yes 32 x 62 Standarc Colonial - Contou G8
*Classic Pa	ckage does not meet Energ	gy Star requirements**	MY	/////

The windows will have the same window pane configuration and the inserts will have architectural frames which will be representative of the existing wooden counter parts.



The windows will have the same configuration and size, fitted to each window.



The Inserts will closely resemble the previous wooden frames.