

TREE # 1 IS AT FRONT OF GARAGE
TREE # 2 IS AT REAR OF GARAGE

PHOTO # 1 DAMAGE TO ROOF 7/4/19 WITH
LARGE LIMB FROM TREE # 2

PHOTO # 2 lg. limb at left hanging onto
tree # 1 7/4/19

PHOTO # 3 SIZE OF HOLE FROM DAMAGE
7/4/19

PHOTO # 4 LARGE SECTION OF TREE # 1 THAT
FELL ON DRIVEWAY IN FALL 2017

PHOTO # 5 OTHER VIEW OF LIMB IN PHOTO # 4

PHOTO # 6 STRAIGHT DOWN VIEW OF LOT THAT
CAUSED LIMB TO FALL IN PHOTO # 4

PHOTO # 7 DARKER SHINGLES OF REPAIR
OF ENTIRE EAVE REPAIR FROM LIMB
THAT FELL IN HURRICANE FROM TREE
1 IN 9/18

PHOTO # 8 EVIDENCE OF LOT CUT ABOUT
12' UP IN TREE # 2 7/4/19